



# Pavement Data Collection and Pavement Management System Implementation for City of Crystal Lake, IL

Prepared for  
**City of Crystal Lake, Illinois**  
In Association with  
**Chicago Metropolitan Agency for Planning**

Prepared by  
**Applied Research Associates, Inc.**

100 Trade Centre Drive, Suite 200  
Champaign, Illinois 61820  
Tel. (217) 356-4500  
Fax (217) 356-3088

## FINAL REPORT

November 2021

## Table of Contents

<b>INTRODUCTION .....</b>	<b>3</b>
1.1 Background .....	3
1.2 Project Kick-off and Records Review .....	3
1.3 Network Segmentation .....	3
1.4 Traffic Data.....	4
<b>2. FIELD DATA COLLECTION AND ASSESSMENT.....</b>	<b>6</b>
2.1 Digital Survey Vehicle (DSV).....	6
2.2 Pavement Condition Index Procedure .....	8
2.3 Pavement Network and Current Condition .....	11
<b>3. PAVEMENT MANAGEMENT SYSTEM IMPLEMENTATION.....</b>	<b>14</b>
3.1 PAVER™ Pavement Management System Overview .....	15
3.2 Pavement Performance Model .....	16
3.3 Treatment Matrix.....	17
3.4 Unit Costs .....	19
3.5 Annual Budget.....	20
<b>4. MAINTENANCE AND REHABILITATION ANALYSIS.....</b>	<b>20</b>
4.1 Funding Scenario Results .....	21
4.2 Consequence of Local Distress Maintenance .....	25
4.3 Pavement Preservation.....	26
<b>5. SUMMARY AND RECOMMENDATION.....</b>	<b>26</b>
5.1 Summary .....	26
5.2 Recommendations .....	26
5.2.1 Better utilization of available funds by performing timely repairs.....	26
5.2.2 Routine update of PAVER™ pavement management system.....	27
5.2.3 Routine pavement condition survey.....	27
<b>6. PAVEMENT PRESERVATION.....</b>	<b>27</b>
<b>REFERENCE .....</b>	<b>32</b>
<b>APPENDIX — A.....</b>	<b>32</b>

### List of Abbreviations

<b>Abbreviation</b>	<b>Explanation</b>
AADT -	Annual Average Daily Traffic
AC -	Asphalt Concrete
ADT -	Average Daily Traffic
AECOM -	The organization AECOM
ARA -	Applied Research Associates
ASTM -	American Society for Testing and Materials
CMAP -	Chicago Metropolitan Agency for Planning
DSV -	Digital Survey Vehicle
FHWA -	Federal Highway Administration
GIS -	Geographic Information System
GPS -	GLOBAL Positioning System
HMA -	Hot Mix Asphalt
HPMS -	Highway Performance Monitoring System
IDOT -	Illinois Department of Transportation
IRI -	International Roughness Index
LCMS -	Laser Crack Measurement System
LTR -	Load Transfer Restoration
NHS -	National Highway System
PCC -	Portland Cement Concrete
PCI -	Pavement Condition Index
PMS -	Pavement Management System
RSL -	Remaining Service Life
STA -	State Transportation Agencies

## INTRODUCTION

### 1.1 Background

Chicago Metropolitan Agency for Planning (CMAP) selected ARA to develop pavement management plans for a selected number of local agencies from the CMAP region, including additional data collection for non-Federal Aid routes. The pavement management plans will provide participating local agencies with a document that describes the importance and types of pavement preservation, the current condition of pavements, scenarios evaluating the cost to meet different network-level pavement conditions, and a recommended capital plan based on the selected pavement condition/spending scenario. The pavement management plan includes summary tables, charts, graphics, and maps depicting current pavement conditions and forecasted pavement conditions under different scenarios. CMAP and AECOM staff managed the development of the pavement management plans in conjunction with the City of Crystal Lake.

As part of this project, ARA has evaluated the current condition of the City of Crystal Lake's roadway pavement network, implemented a pavement management system (PMS) using PAVER™ software, forecasted condition, generated budget scenarios, and recommended future maintenance and rehabilitation (M&R) plans.

### 1.2 Project Kick-off and Records Review


ARA met with the City of Crystal Lake, CMAP, and AECOM representatives for a project kick-off meeting on March 18, 2021. Based on the kick-off meeting and documents provided by the City and CMAP, pavement data was collected between April 14<sup>th</sup> and May 2<sup>nd</sup>, 2021. The GIS shapefile was provided by CMAP and was used as the base map for the field data collection. The network segmentation provided in the GIS shapefile was the primary source of roadway inventory for the pavement management database. The City responded with valuable information to the questionnaire that ARA developed for an understanding of the PMS inputs available from the City and any specific project requirements. ARA worked with the City to finalize the treatment types and unit costs information and their annual budget from 2022 through 2031 to plan future M&R activities. The following documents were reviewed as part of this effort:

- GIS shapefile for the local agency (CMAP)
- Network Segmentation for collection (CMAP)
- Review of network segmentation (City of Crystal Lake)
- Completed Questionnaire (City of Crystal Lake)

### 1.3 Network Segmentation

The City of Crystal Lake manages approximately 170.49 miles of roadway pavements, consisting primarily of asphalt pavements. The pavement network was divided into 753 segments based on the feedback provided by the City. Figure 1 shows the network segmentation that was approved by the City.

---



**Figure 1. City of Crystal Lake's roadway network segmentation.**

#### 1.4 Traffic Data

Table 1 displays the distribution of network length based on functional class. As observed in Table 1, the majority of the roadway network is comprised of residential streets.

Collectors gather traffic from local roads and funnel it to the arterial network. Collectors serve primarily intra-county travel and typical travel distances are shorter than on arterial routes. Collectors are broken down into two categories: Major Collectors and Minor Collectors. Generally, major collector routes are longer in length; have lower driveway densities; have higher speed limits; are spaced at greater intervals; have higher traffic volumes; and may have more travel lanes than their minor collector counterparts.

The minimum spacing between two collector roadways in suburban areas of Illinois is  $\frac{1}{2}$  or 1 mile typically. In a densely populated urban area, two collector roadways might be found at  $\frac{1}{4}$  mile spacing or less, but in most areas within the Chicago metropolitan region  $\frac{1}{4}$  mile is considered an absolute minimum and requires significant justification in terms of the traffic patterns and land uses served. An exception is the case of paired one-way roads serving traffic moving in the opposite direction of each other. Projects on roadways with a minor collector functional classification and located outside of the adjusted urbanized area boundary are not eligible for federal-aid funding.

Local/residential roads primarily provide access to property and connect with higher classified routes. Design speeds are low, stub sections are common, and the main consideration is given to access needs. They offer the lowest level of mobility, have the shortest trip lengths, and through traffic is often deliberately discouraged. Local roads and streets are typically not eligible for federal-aid funding, though some bicycle and pedestrian projects on local roads and streets may be eligible for federal-aid funding.

Average daily traffic (ADT) data for the City of Crystal Lake's network was obtained from the following two resources:

- Illinois Department of Transportation (IDOT) transportation management system:  
<http://www.gettingaroundillinois.com/gai.htm?mt=aadt>.
- IDOT Traffic Count Database Systems:  
<https://idot.ms2soft.com/tcds/tsearch.asp?loc=Idot&mod=>

The maximum traffic volume in the City's network is 17,200 vehicles per day. Figure 2 shows the annual average daily traffic (AADT) data for the individual pavement sections.

**Table 1. City of Crystal Lake's roadway network distribution.**

Network/Functional Class	Length	Unit	Maximum AADT in 2021	Minimum AADT in 2021
Collector	27.81	miles	17,200	700
Arterial	6.03	miles	15,900	2,950
Residential	136.64	miles	7,650	575
Total Network	170.49	miles		





Figure 2. City of Crystal Lake's annual average daily traffic data.

## 2. FIELD DATA COLLECTION AND ASSESSMENT

### 2.1 Digital Survey Vehicle (DSV)

ARA collected geo-referenced images of the entire City of Crystal Lake roadway network using the DSV between April 14<sup>th</sup> and May 2<sup>nd</sup>, 2021. ARA's DSV equipped with the Laser Crack Measurement System (LCMS), shown in Figure 3, captures images at 20-ft intervals. Each image is linearly referenced with the DSV's onboard distance measuring instrument (DMI) and associated global positioning system (GPS) coordinates. For two-lane City highways, ARA collected images in a single direction. In four-lane pavement sections, data was collected in the outermost lane in both directions.



**Figure 3. ARA's laser crack measurement system.**

The LCMS captures enhanced right-of-way images using a right-of-way camera system. The images were used to assess the surface condition of the pavement using the Pavement Condition Index (PCI) methodology in accordance with ASTM D6433. In addition to the images, sensor collected data were collected including the International Roughness Index (IRI) and rutting for all the segments. The weighted average IRI value of the City network is 207 inch/mile, which indicates the network is in 'Rough' condition in terms of pavement roughness. Figure 4 illustrates a scale that is recommended by the Federal Highway Administration (FHWA) as part of its Highway Performance Monitoring System (HPMS) requirements. The HPMS requirements for roadway smoothness is relatively stringent because it involves pavements that are in the National Highway System (NHS).

IRI (in/mile)	Condition
0 – 95	Smooth
96 – 170	Marginal
171 – 220	Rough
Over 220	Unacceptable

**Figure 4: Pavement condition rating scale based on IRI values.**

However, pavement roughness is subjective to human perception. The level of tolerance of roadway roughness is relatively higher for urban-street travelers because of lower operating speed than Interstate and US highways. Moreover, urban street smoothness is largely impacted by frequently intersecting streets, and localized roughness (e.g., manhole covers, railroad crossings, bridge approaches, roundabouts, etc.). Many of these items are not existent in Interstate or US highways. To account for these variabilities into pavement roughness estimation, a study was conducted by the District Department of Transportation (DDOT) in 2009 (1). The study was focused on IRI values of dense urban roadways of Washington D.C. As part of the study, a survey was conducted asking D.C. travelers to give their opinions on pavement smoothness based on the Weaver/AASHO scale. The ratings were directly used to establish a correlation between actual IRI value and perceived smoothness. The study proposed a new scale for the DDOT suggesting 188-318 in/mi for Collectors and 182-281 in/mi for Arterials as acceptable ranges.

Therefore, the village of Glen Ellyn's network average IRI is not of a concern or require immediate attention. Because of this wide variability, IRI was not used in generating any of the budget scenarios presented in this report.

## 2.2 Pavement Condition Index Procedure

The pavement condition index (PCI) is a measurement of pavement condition which ranges from 0 to 100. This is an industry-standard defined in ASTM D6433. A newly constructed pavement will have a PCI of 100 whereas a failed pavement will have a PCI of 10 or less. After the construction of pavements, the condition of pavement starts deteriorating with time due to traffic loads and volumes, climate, construction materials, and age. Examples of common traffic load-related distresses are fatigue cracking, corner break, etc. whereas block cracking, longitudinal and transverse cracking, etc. are climate-related distresses.

PCI Value	Pavement Rating
100	
85	Good
70	Satisfactory
55	Fair
40	Poor
25	Very Poor
10	Serious
0	Failed


**Figure 5. Pavement condition category based on the PCI value.**

---

A PCI survey allows users to compare all pavements on a common scale and provides an index for monitoring pavement deterioration and treatment selection during the PMS analysis. Typically, PCI surveys are conducted foot-on-ground in the field. The modified version allows the use of digital images to perform the survey in an office environment and still provides the highest detail of distress rating.

ARA's LCMS system identifies the pavement distresses and reports the type, severity, and extent of key pavement distresses, as shown in Figure 6. Some sample pavement surface images with representative PCI values are shown in Figure 7.

Ten percent of the surveyed sections were subjected to an internal quality assurance survey by an independent surveyor. After completion of the PCI calculation, visual checks were performed to ensure that the PCI values are representative of the surveyed images.



**Figure 6. Pavement distress detection using LCMS system.**

---



**Figure 7. Sample pavement images with different PCI values.**

## 2.3 Pavement Network and Current Condition

After performing an automated condition survey with the collected images, the inspection data was imported into the PAVER™ software. However, one (1) section listed below was not inspected because the segment was found unpaved and it ran through a wooded area.

- Cog Cir (Sec. 0736, Length = 0.05 mi)

Based on the April 2021 pavement condition survey, the weighted average PCI of the network is 72.5, which represents a pavement network is in “satisfactory” condition. ARA discussed the results of the PCI survey on June 29, 2021. Table 2 shows the pavement condition, percent area, number of sections, and number of sections by pavement surface type.

**Table 2. Pavement condition, percent area, and the number of sections by pavement surface type.**

Surface Type	Wt. Avg PCI	Pavement Area (SqFt)	% Area	Number of Sections
Asphalt Concrete (AC)	72.5	25,132,525	100	752




Figure 8 shows the distribution of network pavement area based on pavement current conditions. In Figure 8, it can be observed that only 1% of the pavement network is in ‘serious’ condition. It is observed that about 23% of the network is in ‘poor’ or ‘very poor’ condition whereas about 57% of the network is in ‘satisfactory’ or ‘good’ condition. Figure 9 shows the detail distribution of pavement conditions based on the functional class of the streets.




**Figure 8. Distribution of network pavement area based on pavement condition.****Figure 9. Pavement condition distribution based on functional class.**

Figure 10 shows the average pavement condition based on functional class. The collector pavement sections comprise about 16.3% of the network by mileage and are in “satisfactory” condition with an average PCI value of 73.1. The arterial pavement sections comprise about 3.5% of the network by mileage and are in “satisfactory” condition with an average PCI value of 83.1. The major part (80.2% by mileage) of the network consists of residential streets and are on “Satisfactory” condition with an average PCI value of 71.6. A GIS map with PCI scores for all of the segments is shown in Figure 11.



**Figure 10. Average pavement condition index (PCI) based on functional class.**




Figure 11. City of Crystal Lake's current pavement condition ratings.

### 3. PAVEMENT MANAGEMENT SYSTEM IMPLEMENTATION

ARA discussed the PMS analysis with the City, CMAP, and AECOM on July 23, 2021. ARA discussed pavement performance models, treatment matrix, unit costs, and consequences of several funding scenarios. Based on the City's feedback on PMS analysis, ARA prepared the PMS analysis and results are presented in this section.

ARA used PAVER™ pavement management software to implement a pavement management system (PMS) for the City of Crystal Lake. PAVER™ provides pavement management capabilities to (a) develop and organize the pavement inventory, (b) assess the current condition of pavements, (c) develop models

to predict future conditions, (d) report on past and future pavement performance, (e) develop scenarios for M&R based on budget or condition requirements, and (f) plan projects.

### **3.1 PAVER™ Pavement Management System Overview**

Figure 12 shows the various modules of the PAVER™ software which includes:

- Inventory — The inventory module is designed based on a hierarchical structure including network, branch, and sections where a section is the smallest pavement unit managed by the agency. This structure allows users to easily organize their inventory while providing numerous fields and levels for storing pavement data.
- Work History — Similar to the inventory module, the work history module also follows the hierarchical structure. To update a pavement section's attribute or work history, it is required to have the network, branch, and section information.
- Inspection — In the inspection module, pavement can be surveyed manually or the automated survey data can be imported and modified, and finally PCI is being calculated.
- PCI Family Model— The PCI family model module is used to create a pavement performance model. Basically, it uses historical pavement condition and age data.
- Condition Analysis — The condition analysis module is used to analyze or predict the condition of the entire or part of the network. This feature reports past conditions based on prior interpolated values between previous inspections and projected conditions based on prediction models.
- M&R Family Models — M&R Family Models module is used to select treatment, treatment consequences, unit costs, and treatment matrix.
- M&R Working Plans — M&R working plans module allows creating multi-year network and project level M&R planning, scheduling, and budgeting. This module allows the users to create a consequence of the current funding level and generates funding scenarios for targeted PCI, backlog eliminations, etc.
- Reports — This module facilitates the generation of summary charts, latest condition maps, and user-defined reports. The users can pick and choose the attributes fields to create a report.





Figure 12. PAVER™ overview.

### 3.2 Pavement Performance Model

A PMS is only useful for making decisions if performance models can be established, validated, and relied upon to accurately forecast pavement conditions into the future. A pavement performance model is developed based on the date of construction for new pavement and date of resurfacing for an overlay or mill and overlay, the types and thicknesses of pavement materials, the traffic level, and the pavement condition. The pavement performance model becomes more accurate with multiple pavement condition ratings, as the model gets calibrated and adjusted to match the conditions present at the time in a pavement's life cycle.

The PCI Family Models module in PAVER™ helps to identify and group pavements of similar construction that are subjected to similar traffic, weather, and other factors affecting pavement performance. The pavement condition historical data are used to build a model that can accurately predict the future performance of a group of pavements with similar attributes.

For the City of Crystal Lake, a PCI family model was developed for the asphalt surfaced pavement as shown in Figure 13. The pavement performance model for the City of Crystal Lake was developed based on the surface age data provided by the agency. The reliability of the pavement performance model is expected to increase with future pavement inspection and age data.



**Figure 13.** PCI family model for asphalt surfaced streets.

### 3.3 Treatment Matrix

Based on the pavement preservation and rehabilitation techniques currently used in the City of Crystal Lake, and discussion with the City, ARA developed a treatment matrix that defines when a treatment will be performed based on PCI values and functional class. In PAVER™, critical PCI is defined as the PCI value at which the rate of PCI loss increases with time and the cost of applying localized preventive maintenance increases significantly. The M&R Family Assignment Tool is used to designate sections to receive specific M&R work, including:

- Localized Stopgap
- Localized Preventive, and
- Major M&R

The *Localized Stopgap* (PCI<Critical) option is used to indicate the use of Safety M&R policies, which allows PAVER™ to plan localized stopgap M&R work (pothole filling, etc.) on areas where the PCI is below the critical level. The *Localized Preventive M&R* (PCI>= Critical) option allows PAVER™ to plan M&R work in localized areas where the PCI is above critical. In this option, life-extending credit, in years, can be given to any localized preventive work. Applying any preventive work where the PCI is still above critical will save money and improve the pavement life. The *Major M&R* option allows PAVER™ to plan any overlay or other major work where the resulting pavement has a PCI of 100.

**Table 3. Treatment matrix for the City of Crystal Lake's Residential Roads.**

Treatment Matrix for Residential Roads				
PCI	Localized Preventive	Localized Stop Gap	Pavement Preservation	Major M&R
0 10	No Localized Preventive Treatment Recommended	Patching and Repair	No Preservation Work Recommended	Full Reconstruction
40				4.0" Reconstruct
55				2.0" Mill & Overlay
65		No Localized Stop Gap/ Major M&R Recommended	Rejuvenator & Microsurfacing	No Major M&R Recommended
80				
100				

**Table 4. Treatment matrix for the City of Crystal Lake's Arterial/Collector Roads.**

Treatment Matrix for Arterial/Collector Roads				
PCI	Localized Preventive	Localized Stop Gap	Pavement Preservation	Major M&R
0 10	No Localized Preventive Treatment Recommended	Patching and Repair	No Preservation Work Recommended	Full Reconstruction
45				4.0" Reconstruct
60				2.0" Mill & Overlay
65		No Localized Stop Gap/ Major M&R Recommended	Rejuvenator & Microsurfacing	No Major M&R Recommended
80				
100				

As observed in Table 3 and Table 4, Residential pavement sections with PCI greater than the critical PCI of 55, and Collector pavement sections with PCI greater than the critical PCI of 60 are selected for localized preventive treatment such as crack sealing or patching. Sections with PCI values less than critical PCI are assigned to stopgap policies related M&R work such as patching and repair and pavement preservation activities. Under major M&R category, 2-inch and 4-inch Mill and Overlays are considered for the Residential Roads below PCI of 55 and 45 respectively. The Collector roads are set to receive the 2-inch Mill and overlay a little earlier (below PCI of 60) and 4-inch Mill and Overlay below 45.

### 3.4 Unit Costs

ARA determined the unit costs for each M&R treatments listed in Table 5, based on our experience with agencies in the Chicagoland area. These costs were discussed with the City during the PMS analysis results meeting on June 23, 2021 and the City reviewed and approved the unit costs. Costs were determined based on a square yard or linear foot basis. The unit costs used for PAVER™ analysis for 2021, are shown in Table 5. To run the PMS analysis in the future, the unit costs can be updated based on the available unit price of materials and construction.

**Table 5. Treatment unit costs for the City of Crystal Lake.**

Treatment Type	Unit Cost	Notes
Crack Seal-AC	\$ 0.60/ft.	Crystal Lake Specific
2.00" Mill and Overlay • 0.75" Leveling 1.5" Surface	\$ 10.48/SY	Crystal Lake Specific
4.00" Reconstruct • Base preparation • Aggregate base • 2.5" Binder • 1.5" Surface	\$ 19.95/SY	Crystal Lake Specific
Partial Depth Patching-AC	\$ 25.02/SY	Typical
Full Depth Patching-AC	\$ 50.04/SY	Typical
Full Depth Reconstruction-AC	\$ 99.00/SY	Typical
Rejuvenator (Reclamite)	\$ 0.90/SY	Crystal Lake Specific
Microsurfacing	\$ 3.15/SY	Typical

### 3.5 Annual Budget

The City of Crystal Lake provided their annual M&R budget from 2021-2031 to be \$1.68M/year. ARA allocated \$1.4M/year to major M&R activities, \$83,000/yr for localized maintenance activities, and \$200,000 for pavement preservation. The assumed budget allocation from 2022 to 2031 is shown below in Figure 14.




Figure 14. Assumed budget allocation for 10 years (2022-2031).

## 4. MAINTENANCE AND REHABILITATION ANALYSIS

Maintenance and rehabilitation (M&R) analysis can be performed in PAVER™ to generate an optimized work plan by assuming an annual funding level or by specifying a target PCI.

For the City of Crystal Lake, the M&R funding analyses were based on the roadway inventory approved by the City, unit costs discussed with the City, and the City's existing Major M&R policies were used in the analyses. An inflation rate of 3% was used for all analyses. PCI family curves were developed based on existing pavement age and collected condition data. The critical PCI value was set to 55 for Residential and 60 for Arterial & Collector roads. The critical PCI value represents the condition at or below which Major M&R is recommended. The following five-year M&R funding scenarios were evaluated:

- Eliminate backlogs (pavements in fair or better condition at the end of the analysis period)
- Add moderate funding relative to current levels (\$2.5 M/year)
- Add moderate funding relative to current levels (\$2.1 M/year)
- Add moderate funding relative to current levels (\$1.75 M/year)
- Current funding (\$1.4 M/year)
- Reduced funding (\$1.0 M/year)
- Do nothing (\$0/year)

---

## 4.1 Funding Scenario Results

Using the M&R Working Plans module, the funding level scenarios were generated. Based on the current funding level, \$83,000 per year is allocated for localized maintenance activities, \$200,000 for pavement preservation, and \$1.4 M/year is allocated for major M&R activities. Table 6 and Figure 15 display the effect of different funding levels on the average pavement condition of the City network. From Table 6 and Figure 15, it can be observed that the current major M&R funding level (\$1.4 M /year) is slightly insufficient to maintain the current condition over ten years. Increasing the major M&R funding to \$1.7M/year will closely maintain the average network PCI whereas increasing the budget to \$2.1M/year will improve the PCI by 3.3 points after 10 years. Providing a budget to eliminate backlogs results in an average PCI of 80.8 after ten years, while not spending any funds on the M&R program will deteriorate the network to an average PCI of 47.7 after ten years. Additional budget scenarios with increased (\$2.5M/year) and reduced (\$1M/year) funding level are provided in the table for reference.

**Table 6. Predicted PCI based on funding scenarios.**

Year	Eliminate Backlogs (\$3.1M/year)	Increase Current Fund (\$2.5M/year)	Increase Current Fund (\$2.1M/year)	Increase Current Fund (\$1.7M/year)	Maintain Current Funding (\$1.4M/year)	Reduced Funding (\$1.0M/year)	Do Nothing
2021	72.5	72.5	72.5	72.5	72.5	72.5	72.5
2022	76.2	74.8	74.1	73.6	73.8	72.7	71.0
2023	78.9	76.6	74.9	73.9	73.9	71.2	68.1
2024	80.5	76.9	75.4	73.9	73.8	69.5	65.2
2025	79.6	77.4	75.1	73.1	73.6	68.1	62.1
2026	80.0	77.3	75.9	73.1	73.4	67.2	59.0
2027	79.9	77.0	75.4	73.1	73.1	66.2	56.2
2028	80.1	77.1	75.4	72.9	73.0	65.3	53.7
2029	80.1	77.0	75.2	72.7	72.4	64.6	51.5
2030	80.3	77.2	75.4	72.9	71.4	64.0	49.5
2031	80.8	77.9	75.8	72.9	70.2	63.0	47.7



**Figure 15. Effect of funding level on City's pavement condition.**

Table 7 and Figure 16 show the amount of funding required to achieve target PCI values for the various funding scenarios. To eliminate backlogs, it is required to invest about \$3.1M/year for the major M&R over the next ten years. Maintaining the current funding of \$1.4M/year will result in a PCI of 70.2 by 2031.

**Table 7. Total funded budget requirements based on funding scenarios.**

Year	Eliminate Backlogs (\$3.1M/year)	Increase Current Fund (\$2.5M/year)	Increase Current Fund (\$2.1M/year)	Increase Current Fund (\$1.7M/year)	Maintain Current Funding (\$1.4M/year)	Reduced Funding (\$1.0M/year)	Do Nothing
2022	\$3,314,617	\$2,499,623	\$2,099,609	1,749,533	\$1,399,485	\$1,014,927	\$0.00
2023	\$3,311,279	\$2,499,361	\$2,098,739	\$1,748,064	\$1,398,966	\$1,014,063	\$0.00
2024	\$3,307,578	\$2,497,347	\$2,096,139	\$1,747,491	\$1,399,142	\$1,014,221	\$0.00
2025	\$3,302,253	\$2,495,141	\$2,097,985	\$1,748,348	\$1,398,701	\$1,013,967	\$0.00
2026	\$3,288,604	\$2,494,561	\$2,098,238	\$1,749,046	\$1,397,126	\$1,010,625	\$0.00
2027	\$3,305,801	\$2,482,603	\$2,093,047	\$1,741,874	\$1,395,780	\$1,014,183	\$0.00
2028	\$3,296,360	\$2,493,868	\$2,082,035	\$1,741,998	\$1,396,597	\$1,014,147	\$0.00
2029	\$3,308,044	\$2,483,002	\$2,067,650	\$1,741,205	\$1,396,918	\$1,014,948	\$0.00
2030	\$2,647,430	\$2,491,956	\$2,071,005	\$1,744,575	\$1,392,940	\$1,014,117	\$0.00
2031	\$2,309,054	\$2,494,966	\$2,099,697	\$1,748,951	\$1,399,886	\$1,014,368	\$0.00




**Figure 16. Total funded budget requirements per year based on funding scenarios.**

Table 8 and Figure 17 shows the total unfunded budget per year based on the funding scenarios. It can be seen that about \$7.0 M is required in 2022 to eliminate the backlog, while doing nothing will generate a backlog of \$85.0 M by 2031. Current major M&R funding will sustain a backlog of \$42.5 M by 2031.


**Table 8. Total unfunded budget requirements per year based on funding scenarios.**

Year	Eliminate Backlogs (\$3.1M/year)	Increase Current Fund (\$2.5M/year)	Increase Current Fund (\$2.1M/year)	Increase Current Fund (\$1.7M/year)	Maintain Current Funding (\$1.4M/year)	Reduced Funding (\$1.0M/year)	Do Nothing
2022	\$7,034,919	\$7,849,913	\$8,159,050	\$8,600,004	\$8,924,873	\$9,334,609	\$10,349,536
2023	\$5,826,069	\$7,470,895	\$8,372,599	\$9,037,039	\$9,858,042	\$10,618,689	\$12,795,462
2024	\$5,346,473	\$8,289,895	\$9,628,902	\$10,652,878	\$11,849,287	\$13,476,200	\$17,782,147
2025	\$9,584,188	\$14,338,290	\$16,129,378	\$18,073,785	\$19,657,264	\$21,719,599	\$27,517,587
2026	\$7,526,492	\$16,637,603	\$19,506,682	\$21,791,689	\$24,327,401	\$26,771,182	\$34,440,134
2027	\$5,330,211	\$15,537,852	\$21,492,235	\$30,239,271	\$33,100,429	\$36,437,176	\$47,467,128
2028	\$3,466,069	\$14,782,432	\$21,327,278	\$30,676,762	\$38,107,103	\$42,406,244	\$55,263,279
2029	\$1,287,804	\$13,768,700	\$20,925,243	\$30,881,656	\$41,030,196	\$46,129,497	\$62,139,727
2030	\$0	\$13,010,796	\$20,802,988	\$31,384,524	\$41,832,364	\$57,221,472	\$75,616,164
2031	\$0	\$13,215,208	\$21,636,434	\$32,886,162	\$42,497,221	\$62,820,019	\$85,418,716



**Figure 17. Total unfunded budget requirements per year based on funding scenarios.**

The 10-Year major M&R plan based on the current funding and 2021 localized distress maintenance plans are provided in Appendix A. Figure 18 shows the network condition distribution for the next ten years with the current funding level. Currently, about 7% of the pavement network is in ‘very poor’ or ‘serious’ condition and about 77% in “Fair” or better condition. With current funding, the average PCI of the network is expected to be 70.2 in 2031. Although the network PCI is predicted to decline slightly, 89% of the network will still be in “Fair” or better condition by 2031 with the City’s current major M&R and pavement preservation funding. PAVER™ recommends projects by adhering to the principles of achieving the best possible outcomes within budgetary limitations.



**Figure 18. Pavement condition by year with current major M&R funding.**

Table 9 presents the total ten year costs for the funded projects and the remaining M&R backlogs in 2030.

**Table 9. Total 10-Year Costs for Various Funding Scenarios**

Funding Scenario	Total 10-Year M&R Costs (2022-2031)	Remaining M&R Backlogs in 2031	Total 10-Year Costs	Predicted PCI 2031
\$3.1M/year - Eliminate Backlogs	\$31.4	\$0.0	\$31.4	81
\$2.5M/year - Increase Current Fund	\$24.9	\$13.2	\$38.1	78
\$2.1M/year - Increase Current Fund	\$20.9	\$21.6	\$42.5	76
\$1.7M/year - Increase Current Fund	\$17.5	\$32.9	\$50.3	73
\$1.4M/year - Maintain Current Fund	\$14.0	\$42.5	\$56.5	70
\$1.0M/year - Reduced Funding	\$10.1	\$62.8	\$73.0	63
\$0/year - Do Nothing	\$0.0	\$85.4	\$85.4	48

1. 'M&R Backlogs' refers to the amount required to resurface/reconstruct all pavements at or below their critical PCI value.  
 2. 'Total 10-Year Costs' refers to the sum of 10-year major M&R expenses and remaining backlogs at the end of 10-year period.

## 4.2 Consequence of Local Distress Maintenance

The consequence of a localized distress maintenance plan calculates the cost and resulting condition of immediate implementation of local M&R, for the year of the most recent inspection. Based on the 2021 pavement condition survey, the localized preventive plan estimated that PCI of 422 sections would increase by 3.5 points with an investment of \$443,740. Similarly, the localized stopgap plan estimated that PCI of 87 sections would increase by 1.3 points with an investment of \$8,825. The details of the localized distress maintenance plan based on the 2021 condition survey can be found in Appendix A. Table 10 shows the cost and pavement condition data of the consequence of the local distress maintenance plan. Table 11 shows the details of the local distress maintenance plan 2022.

**Table 10. Details of the consequence of local distress maintenance plan**

Number Sections	Policy Cost	Wt. Avg. of PCI before Maintenance	Wt. Avg. of PCI after Maintenance
422 (Localized Preventive)	\$321,355	81.6	85.1
87 (Localized Stopgap)	\$8,825	45.5	46.2

**Table 11. Details of the local distress maintenance plan 2022**

Local Distress Maintenance-2022			
Work Description	Work Quantity	Work Units	Work Cost
Crack Sealing	135,982	Ft	\$81,589
Patching - Shallow	45,594	SqFt	\$126,752
Patching - Deep	21,913	SqFt	\$121,839
	Total =		\$330,180

### **4.3 Pavement Preservation**

Pavement preservation considers all work types that are applied over a larger area of pavement. The Global M&R table in PAVER includes the application interval that work would be reapplied, and the change in age of the pavement. This change is the time (in years) it would take for the condition of the pavement to return to where it was prior to application of the global treatment. The current analysis chose pavement preservation candidates based on a PCI range 65-80. ARA recommends using PCI=65-75 as a suitable range for Microsurfacing treatments and PCI>75 for rejuvenation.

## **5. SUMMARY AND RECOMMENDATION**

### **5.1 Summary**

Pavement management can be defined as the systematic process of maintaining pavements cost-effectively. The investment in pavement management system is rational considering pavement management not only provides a consistent and rational management method to make decisions but also helps in optimal use of funds and reduces pavement rehabilitation, which results in extended pavement life and increased credibility with stakeholders.

In this effort to implement a pavement management system for the City of Crystal Lake, pavement data was collected with a state-of-the-art digital survey vehicle equipped with a laser crack measurement system. Pavement images were used in an automated condition survey process to assess the type, severity, and extent of the distresses. The pavement inspection data was imported to the PAVER™ software to determine the pavement condition index (PCI) and analyze the pavement network. This PAVER database provides a comprehensive inventory of pavement sections with all attributes that are required for pavement management.

Based on the April 2021 survey, the average pavement condition index (PCI) value for the City is about 72.5, which indicates the pavement network is in overall ‘Satisfactory’ condition.

### **5.2 Recommendations**

#### **5.2.1 Better utilization of available funds by performing timely repairs**

The City is already on track toward a better performing pavement network. Currently about 34% of the network is in ‘Good’ condition, 23% is in ‘Satisfactory’, and 20% is in ‘Fair’ condition. Overall, about 77% of the network is in ‘Fair’ or better condition. Only 1% of the network is in ‘serious’ condition, 23% of the pavement area is in ‘very poor’ or ‘poor’ condition. The analysis suggested that the current funding is slightly inadequate to maintain the current overall condition of the pavement network. It is recommended that the City should focus on applying routine preventive maintenance to the pavement sections in ‘satisfactory’ and ‘good’ condition. Preventive maintenance activities, such as crack sealing and localized patching, can cost-effectively extend the life of a pavement.

---

### 5.2.2 Routine update of PAVER™ pavement management system

ARA recommends updating the PAVER pavement management system annually to record the major M&R, stopgap and localized preventive maintenance activities, and pavement inventory changes (i.e., section split, new roads, jurisdictional changes, etc.). Based on the yearly updates of M&R activities, the City can perform M&R analysis with an updated funding level (if available), accounting for the previous year(s) actual projects.

### 5.2.3 Routine pavement condition survey

For the City of Crystal Lake, it is an excellent initiative to establish a pavement management system with the cooperation of the Chicago Metropolitan Agency for Planning (CMAP). To realize the greatest benefit from this holistic effort, it is recommended that the City of Crystal Lake continue to perform pavement condition surveys on a three to a four-year cycle. The benefits of performing routine PCI surveys are many folded including:

- (a) A survey provides the current condition of the pavement network and helps to determine the effectiveness of completed M&R activities performed in the last few years,
- (b) Pavement performance models would be more accurate to predict the future condition, and
- (c) Appropriate treatment and optimal funding allocation are possible to repair localized distresses based on the survey

## 6. PAVEMENT PRESERVATION

Pavement preservation is a proactive method to keep pavements in good condition with lower costs. This approach includes work that is planned and performed to improve or retain the condition of the pavement in a state of good repair. The various pavement preservation techniques used in the state are also available in the local roads and streets manual (<https://idot.illinois.gov/Assets/uploads/files/Doing-Business/Manuals-Split/Local-Roads-and-Streets/Chapter%2045.pdf>) of IDOT. Preservation activities generally do not increase the structural strength but do restore pavements' overall condition. The intended purpose of a pavement preservation program is to maintain or restore the surface characteristics of pavements and to extend service life of the pavements being managed. However, the improvements are such that there is no increase in strength but they can have a positive impact on the structural capacity by slowing deterioration. The Federal Highway Administration (FHWA) Office of Asset Management provided the following guidance regarding pavement preservation definitions in a memorandum dated September 12, 2005:

Pavement preservation represents a proactive approach to maintain our existing highways. It enables State Transportation agencies (STAs) to reduce costly, time-consuming rehabilitation and reconstruction projects and the associated traffic disruptions. With timely preservation, we can provide the traveling public with improved safety and mobility, reduced congestion, and smoother, longer-lasting pavements. This is the true goal of pavement preservation, a goal in which the FHWA, through its partnership with the States, local agencies, industry organizations, and other interested stakeholders, is committed to achieving.

---

The main component of pavement preservation is preventive maintenance. As defined by FHWA, preventive maintenance is a planned strategy of cost-effective treatments to an existing roadway system and its appurtenances that preserves the system, retards future deterioration, and maintains or improves the functional condition of the system (without significantly increasing the structural capacity). The general philosophy of the use of preventive maintenance treatments is to “apply the right treatment, to the right pavement, at the right time.” These practices result in an outcome of “keeping good roads in good condition.”

When activities (e.g., crack sealing, filling, application of seal coats) are placed on the pavement at the right time they are examples of preventive maintenance treatments. Preventive maintenance should be applied to pavements in good condition having significant remaining service life (RSL). It applies cost-effective treatments to the surface or near-surface of structurally sound pavements. Examples include the following:

- Crack sealing
- Patching (Partial and Full depth)
- Rejuvenator/ Reclamite
- Microsurfacing

Based on the pavement condition assessment results the following treatment has been selected to describe in this section:

- Bituminous-Surfaced Pavements
  - Asphalt Rejuvenator i.e. reclamite
    - This treatment can be applied globally in the Village of Lyons network at the very early stage of newly constructed pavement or after placing a new surface.
  - Crack Filling/Crack Sealing
    - Sealing/filling cracks in asphalt and pavement prevent the intrusion of water into the pavement structure and decrease the deterioration of pavement conditions.
  - Microsurfacing
    - This treatment can be applied to pavements having relatively higher PCI and minimal distresses.
  - Patching
    - Asphalt patches are used for treating localized distresses from worsening.

<b>AC - Crack Filling and Crack Sealing</b>	Evaluation Factors			
	Climate	Traffic	Pavement Condition	Not Applicable To
These treatments are intended primarily to prevent the intrusion of moisture through existing cracks. Crack sealing refers to a sealant operation that addresses "working" cracks, i.e., those that open and close with changes in temperature. It typically implies high-quality materials and good preparation. Crack filling is for cracks that undergo little movement. Sealants used are typically thermo-plastic (bituminous) materials that soften upon heating and harden upon cooling.	Treatment can perform well in all climatic conditions. However, sealants perform best in the dryer and warmer environments that do not undergo large daily temperature changes.	Performance is not significantly affected by varying ADT or truck levels.	<b>Functional/Other:</b> <ul style="list-style-type: none"> <li>• Longitudinal cracking</li> <li>• Minor block cracking</li> <li>• Transverse cracking</li> </ul> <b>Structural:</b> Adds no structural benefit, but does reduce moisture infiltration through cracks. Only practical if the extent of cracking is minimal and if there is little to no structural cracking.	<ul style="list-style-type: none"> <li>• Structural failure (i.e., extensive fatigue cracking or high severity rutting)</li> <li>• Extensive pavement deterioration, little remaining life</li> </ul>
<b>Construction Considerations</b>	Placement should be done during cool, dry weather conditions. Proper crack cleaning is essential to a good bond and maximum performance. Some agencies also use hot compressed air lance prior to sealing.			
<b>Expected Life</b>	2 to 6 years.			
<b>Typical Costs</b>	\$0.30 to \$1.50 per linear ft for crack sealing, including routing; \$0.30 per linear ft for crack filling. Costs are slightly higher for small jobs.			

<b>Asphalt Patching</b>	Evaluation Factors			
	Climate	Traffic	Pavement Condition	Not Applicable To
Asphalt Patches are common method of treating localized distress. HMA patches can either be Full-depth or partial-depth. Full-depth patches are necessary where the entire depth of pavement is distressed. Partial-depth patches are necessary where the distress is only limited to the pavement surface	Preferably during dryer and warmer months. Cold patches can be used for temporary pothole fixes.	Traffic control is needed. Reduced roadway capacity should be evaluated. Traffic can return to a patched pavement once it cools off to 140°F	<b>Partial Depth Repairs</b> <ul style="list-style-type: none"> <li>Shallow potholes</li> <li>Weathering and Ravelling</li> <li>Block Cracking</li> </ul> <b>Full Depth Repairs</b> <ul style="list-style-type: none"> <li>Depressions</li> <li>Pumping</li> <li>Bottom-up fatigue cracking (thin pavement structure)</li> <li>Underlying stripping</li> </ul>	<ul style="list-style-type: none"> <li>Thermal cracking</li> <li>Extensive pavement deterioration, little or no remaining life</li> </ul>
<b>Site Restrictions</b>	Appropriate traffic control			
<b>Construction Considerations</b>	<ul style="list-style-type: none"> <li>Patch boundary should be clearly defined</li> <li>Remove distressed materials and repair saturated subgrade soil or correct the main cause of distress</li> <li>Repair should extend 12 inches into the non-distressed pavement</li> <li>Apply tack coat on all the vertical and horizontal surfaces before placing the patch and compact the patch.</li> <li>Compact quickly after placing the patch to ensure maximum compaction</li> <li>Avoiding vibratory compaction under 175°F</li> <li>Maximum lift thickness is 3 inch.</li> <li>Avoid leaving a thin strip of asphalt pavement (less than 18 inches wide) along the pavement edge. It is better to extend the repair to the pavement edge.</li> <li>For small patches, use a jackhammer with a spade bit or a masonry saw. Make vertical cuts through the full depth of the asphalt pavement surface. If a jackhammer is used, work from the center of the patch area outward to avoid damaging good pavement.</li> <li>For medium to large patches, use a diamond-bladed saw to cut the edges. If the distress is only at the surface and the pavement is thick enough, consider a partial-depth cut for thick asphalt pavement surfaces to retain some interlock with the remaining structure.</li> </ul>			
<b>Expected Life</b>	A provisional maintenance before major M&R. A patch itself can last longer without increasing the overall life of an entire pavement section. Therefore, the expected life should be evaluated on a case by case basis.			
<b>Typical Costs</b>	<ul style="list-style-type: none"> <li>AC Patch –Partial Depth - \$20.00-25.00/SY</li> <li>AC Patch –Full depth - \$40.00-50.00/SY</li> </ul>			

<b>Asphalt Rejuvenator/Reclamite</b>	<b>Evaluation Factors</b>			
	<b>Climate</b>	<b>Traffic</b>	<b>Pavement Condition</b>	<b>Not Applicable To</b>
According to the National Center for Pavement Preservation, "a true asphalt rejuvenator is a maltene-based petroleum product which has the ability to absorb or penetrate into an asphaltic concrete pavement and restore those reactive components (maltenes) that have been lost from the asphalt cement binder due to the natural process of oxidation. Reclamite is an asphalt pavement rejuvenator which is a maltene-based petroleum product.	<ul style="list-style-type: none"> <li>shall not be applied to a wet surface or when rain is occurring</li> <li>shall not be applied when the temperature is less than 40° in the shade</li> </ul>	Traffic control shall continue until the area has been sanded and the resultant surface is not slippery or dangerous to vehicular travel	Newly constructed pavements (0-3 years)	On older pavements, it will reverse the effects of aging due to environmental damage from sunlight and water intrusion.
<b>Construction Considerations</b>	All manufactured sand used during the treatment must be removed no later than 24 hours after the treatment of a roadway.			
<b>Expected Life</b>	Add 5 to 10 years of extra service life to the treated pavement			
<b>Typical Costs</b>	\$0.79-0.84/Sq. Yd.			


<b>Microsurfacing</b>	<b>Evaluation Factors</b>			
	<b>Climate</b>	<b>Traffic</b>	<b>Pavement Condition</b>	<b>Not Applicable To</b>
Microsurfacing is basically a slurry seal with an accelerated setting capability. It consists of the application of a mixture of water, asphalt emulsion, aggregate (very small crushed rock), and <u>chemical additives</u> to an existing asphalt concrete pavement surface. Polymer is commonly added to the asphalt emulsion to provide better mixture properties. The major difference between slurry seal and Microsurfacing is in how they "break" or harden.	<ul style="list-style-type: none"> <li>Not applicable during a rain event.</li> <li>Not applicable in excessively cold temperature.</li> <li>Atmospheric temperature is at least 10°C (50°F) and rising.</li> <li>Pavement that have a lot of shade.</li> </ul>	<ul style="list-style-type: none"> <li>Applicable to high traffic situations.</li> <li>Traffic can be allowed to roll when a person's full weight can be placed on the pavement without the aggregates sticking to the shoe.</li> </ul>	<ul style="list-style-type: none"> <li>Low to Moderate level of distress.</li> <li>Structurally sound pavement.</li> </ul>	<ul style="list-style-type: none"> <li>Highly distressed pavement.</li> <li>High longitudinal roughness.</li> <li>Structurally deficient pavement.</li> <li>Subgrade rut.</li> <li>Ruts above 2-in deep.</li> </ul>
<b>Site Restrictions</b>	Lane closure is needed.			
<b>Construction Considerations</b>	<ul style="list-style-type: none"> <li>Spread microsurfacing materials only when the atmospheric temperature is at least 10°C (50°F) and rising.</li> <li>Throughly cleaned surface and slightly dampened prior placing the mixture.</li> <li>Ruts deeper than ½-in shall be filled separately.</li> </ul>			
<b>Expected Life</b>	6-8 years			
<b>Typical Costs</b>	\$2.75/ yd <sup>2</sup>			

## Reference

1. Arhin, Stephen, and Errol C. Noel. *Establishing IRI Thresholds for the District of Columbia*. No. DDOT-IPMA-IRI-001. 2009. [Link to the report](#)

## Appendix — A

1. 2022-2031 Major M&R Plan Based on Current Funding
2. 2022 Localized Distress Maintenance Plan
3. 2022-2031 Major M&R Plan Based on “Eliminate Backlog” Funding
4. 2022-2031 Pavement Preservation Plan Based on Current Funding
5. Pavement Surface Type
6. 2021 International Roughness Index (IRI)
7. Pavement Condition Index (PCI) 2021
8. List of Pavement Sections with 2021 PCI and IRI values
9. Details of the 2022 Localized Distress Maintenance Plan




0 3,600 7,200 Feet

Major M&R 2022-2031  
Based on Current Funding

## City of Crystal Lake



**ARA**




0 3,600 7,200 Feet

Localized Maintenance Plan 2022

City of Crystal Lake



**ARA**




0 3,600 7,200 Feet

**Major M&R 2022-2031**  
Based on  
Eliminate Backlog Funding

## City of Crystal Lake



**ARA**




0 3,600 7,200 Feet

Pavement Preservation  
2022-2031 Based on  
Current Funding

City of Crystal Lake



**ARA**




0 3,600 7,200 Feet

Pavement Surface Type

**City of Crystal Lake**



**ARA**




0 3,600 7,200 Feet

IRI 2021

City of Crystal Lake



**ARA**



0 3,600 7,200 Feet

PCI 2021

City of Crystal Lake



**ARA**

**List of Pavement Section with 2021 PCI and IRI Values**

Branch ID	Section ID	Surface Type	Length (ft)	Width (ft)	Functional Class	Date	IRI (in/mi)	PCI	PCI Category
ABBEYDR	0364	AC	1,326	24	Residential	06-02-2021	280	41.0	Poor
ABBINGTOND	0378	AC	2,230	26	Residential	06-02-2021	397	50.0	Poor
ABERDEENDR	0255	AC	2,167	26	Residential	06-02-2021	143	76.0	Satisfactory
ACHILLESCT	0463	AC	242	28	Residential	06-02-2021	255	67.0	Fair
ACHILLESLN	0103	AC	1,717	28	Residential	06-02-2021	261	58.0	Fair
AJAXST	0616	AC	1,172	28	Residential	06-02-2021	242	52.0	Poor
ALEXANDRAB	0038	AC	5,471	34	Collector	06-02-2021	208	75.0	Satisfactory
ALEXANDRAB	0058	AC	1,255	34	Collector	06-02-2021	192	80.0	Satisfactory
ALEXANDRAB	0093	AC	2,912	26	Residential	06-02-2021	348	48.0	Poor
ALEXANDRAB	0179	AC	2,924	36	Residential	06-02-2021	224	42.0	Poor
AMBERWOODD	0035	AC	3,041	34	Residential	06-02-2021	155	99.0	Good
AMBERWOODD	0114	AC	2,413	26	Residential	06-02-2021	220	58.0	Fair
AMBERWOODD	0138	AC	1,535	34	Residential	06-02-2021	135	96.0	Good
ANDOVERLN	0113	AC	2,053	24	Residential	06-02-2021	167	62.0	Fair
ANGELALN	0181	AC	498	26	Residential	06-02-2021	265	37.0	Very Poor
ANGELALN	0775	AC	151	26	Residential	06-02-2021	319	46.0	Poor
ARROWHEADL	0282	AC	1,008	24	Residential	06-02-2021	117	99.0	Good
ASCOTDR	0046	AC	709	24	Residential	06-02-2021	276	77.0	Satisfactory
ASHFORDLN	0199	AC	2,106	26	Residential	06-02-2021	127	99.0	Good
ASHST	0148	AC	1,313	24	Residential	06-02-2021	306	74.0	Satisfactory
ASHTONLN	0064	AC	1,307	36	Residential	06-02-2021	196	72.0	Satisfactory
ASHTONLN	0734	AC	24	36	Residential	06-02-2021	194	76.0	Satisfactory
AUBURNCT	0339	AC	678	26	Residential	06-02-2021	168	98.0	Good
AUGUSTADR	0301	AC	612	24	Residential	06-02-2021	388	65.0	Fair
AUTUMNCRES	0130	AC	2,261	24	Residential	06-02-2021	383	83.0	Satisfactory
AUTUMNCRES	0511	AC	392	24	Residential	06-02-2021	388	41.0	Poor
AUTUMNCRES	0545	AC	1,288	24	Residential	06-02-2021	233	96.0	Good
AUTUMNDR	0003	AC	2,402	26	Residential	06-02-2021	279	46.0	Poor
AUTUMNDR	0724	AC	361	26	Residential	06-02-2021	479	33.0	Very Poor
AVALONCT	0169	AC	167	24	Residential	06-02-2021	246	54.0	Poor
BALLARDRD	0640	AC	1,326	22	Residential	06-02-2021	127	98.0	Good
BARBERRYDR	0533	AC	618	22	Residential	06-02-2021	300	71.0	Satisfactory
BARBERRYDR	0559	AC	699	22	Residential	06-02-2021	235	92.0	Good
BARDRD	0644	AC	1,289	26	Residential	06-02-2021	109	83.0	Satisfactory
BARLINARD	0146	AC	2,979	38	Collector	06-02-2021	157	86.0	Good
BARLINARD	0187	AC	4,080	38	Collector	06-02-2021	144	80.0	Satisfactory
BARLINARD	0296	AC	1,294	38	Collector	06-02-2021	321	58.0	Fair
BARLINARD	0751	AC	128	38	Collector	06-02-2021	381	99.0	Good
BARROWDR	0053	AC	880	26	Residential	06-02-2021	185	52.0	Poor
BARTONLN	0531	AC	390	26	Residential	06-02-2021	217	77.0	Satisfactory
BAYBERRYDR	0421	AC	351	22	Residential	06-02-2021	247	81.0	Satisfactory
BEARDSLEYS	0589	AC	681	24	Residential	06-02-2021	192	66.0	Fair
BECKERCT	0085	AC	390	26	Residential	06-02-2021	212	79.0	Satisfactory
BEDFORDDR	0156	AC	1,680	26	Residential	06-02-2021	129	83.0	Satisfactory
BEECHCRAFT	0392	AC	539	36	Residential	06-02-2021	112	92.0	Good
BENNINGTON	0349	AC	2,148	24	Residential	06-02-2021	319	65.0	Fair

**List of Pavement Section with 2021 PCI and IRI Values**

Branch ID	Section ID	Surface Type	Length (ft)	Width (ft)	Functional Class	Date	IRI (in/mi)	PCI	PCI Category
BENNINGTON	0514	AC	1,321	24	Residential	06-02-2021	214	92.0	Good
BERKSHIRE	0293	AC	3,031	38	Collector	06-02-2021	200	51.0	Poor
BIRCHST	0678	AC	518	24	Residential	06-02-2021	131	72.0	Satisfactory
BIRCHST	0685	AC	590	24	Residential	06-02-2021	142	65.0	Fair
BIRMINGHAM	0137	AC	2,530	24	Residential	06-02-2021	192	69.0	Fair
BIRMINGHAM	0400	AC	446	24	Residential	06-02-2021	271	66.0	Fair
BITTERSWEET	0391	AC	617	26	Residential	06-02-2021	118	100.0	Good
BLACKTHORN	0207	AC	1,872	26	Residential	06-02-2021	173	96.0	Good
BLACKTHORN	0384	AC	969	24	Residential	06-02-2021	167	62.0	Fair
BLUEHEROND	0610	AC	1,040	26	Residential	06-02-2021	201	89.0	Good
BLUEHEROND	0668	AC	778	26	Residential	06-02-2021	177	94.0	Good
BLUEHEROND	0669	AC	210	26	Residential	06-02-2021	137	100.0	Good
BLUEHEROND	0670	AC	188	26	Residential	06-02-2021	243	84.0	Satisfactory
BLUEHEROND	0671	AC	76	26	Residential	07-19-2021	140	86.0	Good
BLUEMOUNDD	0369	AC	722	26	Residential	06-02-2021	151	83.0	Satisfactory
BONESETDR	0201	AC	905	26	Residential	06-02-2021	202	85.0	Satisfactory
BOXWOODCT	0338	AC	395	24	Residential	06-02-2021	335	33.0	Very Poor
BOXWOODDR	0062	AC	1,415	24	Residential	06-02-2021	380	41.0	Poor
BOXWOODDR	0292	AC	2,742	24	Residential	06-02-2021	246	66.0	Fair
BOXWOODDR	0517	AC	1,968	24	Residential	06-02-2021	176	98.0	Good
BRADFORDLN	0266	AC	1,266	32	Residential	06-02-2021	106	99.0	Good
BRIARWOODC	0480	AC	1,240	22	Residential	06-02-2021	135	89.0	Good
BRIARWOODR	0010	AC	4,088	28	Collector	06-02-2021	195	51.0	Poor
BRIARWOODR	0050	AC	1,786	22	Residential	07-19-2021	385	100.0	Good
BRIARWOODR	0625	AC	1,333	28	Collector	07-19-2021	254	100.0	Good
BRIARWOODR	0657	AC	872	28	Collector	06-02-2021	129	71.0	Satisfactory
BRIDGEDALE	0411	AC	214	26	Residential	06-02-2021	295	65.0	Fair
BRIDGEDALE	0431	AC	1,711	26	Residential	06-02-2021	170	53.0	Poor
BRIGHAMLN	0604	AC	932	24	Residential	06-02-2021	204	68.0	Fair
BRINKST	0417	AC	1,147	40	Residential	06-02-2021	230	61.0	Fair
BRINKST	0647	AC	557	40	Residential	06-02-2021	540	27.0	Very Poor
BRISTOLDR	0122	AC	289	22	Residential	06-02-2021	187	65.0	Fair
BROADWAYAV	0228	AC	648	22	Residential	06-02-2021	200	96.0	Good
BROADWAYAV	0450	AC	1,176	26	Residential	06-02-2021	196	85.0	Satisfactory
BROADWAYAV	0652	AC	2,085	28	Residential	06-02-2021	172	90.0	Good
BROMPTONCT	0312	AC	372	26	Residential	06-02-2021	331	82.0	Satisfactory
BROMPTONLN	0124	AC	808	34	Residential	06-02-2021	215	66.0	Fair
BROMPTONLN	0274	AC	1,546	34	Residential	06-02-2021	152	77.0	Satisfactory
BROMPTONLN	0760	AC	217	34	Residential	06-02-2021	507	78.0	Satisfactory
BROOKDR	0167	AC	673	26	Residential	06-02-2021	171	88.0	Good
BRYNMAWRNL	0300	AC	2,412	32	Residential	06-02-2021	136	76.0	Satisfactory
BUCKINGHAM	0218	AC	1,820	26	Residential	06-02-2021	239	46.0	Poor
BUCKINGHAM	0570	AC	217	26	Residential	06-02-2021	264	74.0	Satisfactory
BURDENTDR	0310	AC	365	24	Residential	06-02-2021	330	39.0	Very Poor
BURNINGBUS	0346	AC	2,664	24	Residential	06-02-2021	130	99.0	Good
BURROAKDR	0099	AC	920	22	Residential	06-02-2021	147	90.0	Good

**List of Pavement Section with 2021 PCI and IRI Values**

Branch ID	Section ID	Surface Type	Length (ft)	Width (ft)	Functional Class	Date	IRI (in/mi)	PCI	PCI Category
BUTLERDR	0260	AC	1,513	26	Residential	06-02-2021	174	86.0	Good
BUTTERNUTD	0641	AC	1,491	22	Residential	06-02-2021	143	90.0	Good
CALEDONIAL	0595	AC	616	24	Residential	06-02-2021	368	58.0	Fair
CAMBRIDGEEL	0552	AC	1,486	26	Residential	06-02-2021	127	92.0	Good
CAMELOTCT	0376	AC	389	24	Residential	06-02-2021	187	100.0	Good
CAMELOTDR	0258	AC	2,600	24	Residential	06-02-2021	101	98.0	Good
CAMELOTPL	0478	AC	386	24	Residential	06-02-2021	162	100.0	Good
CANDLEWOOD	0177	AC	1,743	26	Residential	06-02-2021	199	75.0	Satisfactory
CANDLEWOOD	0325	AC	1,270	26	Residential	06-02-2021	197	60.0	Fair
CANTERBURY	0402	AC	1,981	26	Residential	06-02-2021	180	86.0	Good
CARDIFFDR	0182	AC	1,202	26	Residential	06-02-2021	178	93.0	Good
CARLEMONTD	0393	AC	2,481	36	Residential	06-02-2021	279	55.0	Poor
CARMELLADR	0377	AC	1,029	24	Residential	06-02-2021	149	100.0	Good
CARMELLADR	0665	AC	244	24	Residential	06-02-2021	150	100.0	Good
CARMELLADR	0666	AC	283	24	Residential	06-02-2021	128	100.0	Good
CARPENTERS	0098	AC	360	24	Residential	06-02-2021	243	29.0	Very Poor
CASCADEDR	0358	AC	1,702	24	Residential	06-02-2021	298	55.0	Poor
CASCADEDR	0551	AC	337	24	Residential	06-02-2021	265	72.0	Satisfactory
CASTLEFIEL	0575	AC	195	26	Residential	06-02-2021	202	93.0	Good
CATHERINEC	0131	AC	759	24	Residential	06-02-2021	160	42.0	Poor
CEDARCREST	0170	AC	2,065	26	Residential	06-02-2021	214	70.0	Fair
CEDARDR	0483	AC	358	22	Residential	06-02-2021	224	90.0	Good
CENTERST	0076	AC	877	26	Residential	06-02-2021	404	50.0	Poor
CENTERST	0196	AC	1,203	22	Residential	06-02-2021	278	53.0	Poor
CENTERST	0752	AC	395	22	Residential	06-02-2021	202	79.0	Satisfactory
CENTRALPAR	0404	AC	1,431	36	Residential	06-02-2021	250	77.0	Satisfactory
CENTRALPAR	0769	AC	299	36	Residential	06-02-2021	181	66.0	Fair
CERESIADR	0528	AC	531	24	Residential	06-02-2021	201	64.0	Fair
CHARDONNAY	0594	AC	928	30	Residential	06-02-2021	141	78.0	Satisfactory
CHARLOTTEA	0290	AC	2,601	22	Residential	06-02-2021	181	67.0	Fair
CHURCHST	0650	AC	666	24	Residential	06-02-2021	272	38.0	Very Poor
CIRCLEDR	0614	AC	541	22	Residential	06-02-2021	550	32.0	Very Poor
CLOVERDR	0011	AC	586	22	Residential	06-02-2021	425	31.0	Very Poor
CLOVERDR	0151	AC	752	22	Residential	06-02-2021	395	67.0	Fair
CLOVERDR	0658	AC	699	22	Residential	06-02-2021	261	85.0	Satisfactory
CLOWCT	0522	AC	168	24	Residential	06-02-2021	139	72.0	Satisfactory
COGCIR	0068	AC	3,218	24	Residential	06-02-2021	276	49.0	Poor
COGCIR	0736	AC	269	24	Residential	N/A	N/A	N/A	N/A
COLLEGEST	0198	AC	2,293	22	Residential	06-02-2021	226	51.0	Poor
COLLEGEST	0419	AC	391	22	Residential	06-02-2021	291	83.0	Satisfactory
COLONIALAV	0447	AC	864	24	Residential	06-02-2021	133	65.0	Fair
COLONYDR	0468	AC	1,193	24	Residential	06-02-2021	281	38.0	Very Poor
COMMERCEDR	0543	AC	583	36	Residential	06-02-2021	359	46.0	Poor
COMMERCIAL	0526	AC	1,325	22	Residential	07-19-2021	206	100.0	Good
COMMONWEAL	0347	AC	726	36	Residential	07-19-2021	263	100.0	Good
CONCORDDR	0554	AC	1,603	26	Residential	06-02-2021	164	50.0	Poor

**List of Pavement Section with 2021 PCI and IRI Values**

Branch ID	Section ID	Surface Type	Length (ft)	Width (ft)	Functional Class	Date	IRI (in/mi)	PCI	PCI Category
CONGRESSPK	0306	AC	2,417	34	Collector	07-19-2021	183	100.0	Good
CONGRESSPK	0544	AC	1,160	34	Collector	06-02-2021	131	66.0	Fair
CONGRESSPK	0776	AC	2,304	34	Collector	07-19-2021	183	100.0	Good
COPPERFIEL	0165	AC	1,219	26	Residential	06-02-2021	148	79.0	Satisfactory
CORRINEAVE	0084	AC	907	22	Residential	06-02-2021	228	43.0	Poor
CORRINEAVE	0743	AC	89	22	Residential	07-19-2021	300	51.0	Poor
COTTONWOOD	0027	AC	1,112	22	Residential	06-02-2021	278	73.0	Satisfactory
COUNTRYCLU	0115	AC	1,180	22	Residential	06-02-2021	244	97.0	Good
COUNTRYCLU	0512	AC	2,908	26	Residential	06-02-2021	145	99.0	Good
COUNTRYCLU	0633	AC	1,007	26	Residential	06-02-2021	165	97.0	Good
COUNTRYHIL	0566	AC	370	24	Residential	06-02-2021	131	85.0	Satisfactory
COUNTRYLN	0370	AC	1,159	24	Residential	06-02-2021	177	94.0	Good
COVENTRYCT	0484	AC	105	22	Residential	06-02-2021	231	63.0	Fair
COVENTRYLN	0028	AC	3,147	38	Residential	06-02-2021	194	36.0	Very Poor
COVENTRYLN	0253	AC	3,525	26	Residential	06-02-2021	148	70.0	Fair
COVINGTONC	0281	AC	902	26	Residential	06-02-2021	203	58.0	Fair
COWLINST	0689	AC	715	24	Residential	06-02-2021	127	62.0	Fair
CRABAPPLED	0413	AC	1,961	26	Residential	06-02-2021	293	58.0	Fair
CRABTREEDR	0520	AC	581	24	Residential	06-02-2021	208	89.0	Good
CRANDALLAV	0438	AC	402	24	Residential	06-02-2021	84	100.0	Good
CRANDONPL	0361	AC	858	24	Residential	06-02-2021	167	93.0	Good
CRANDONPL	0764	AC	200	24	Residential	06-02-2021	221	92.0	Good
CRESSCREEK	0127	AC	1,249	26	Residential	06-02-2021	133	99.0	Good
CRESSCREEK	0397	AC	1,008	26	Residential	06-02-2021	130	99.0	Good
CRIMSONDR	0314	AC	1,371	26	Residential	06-02-2021	196	78.0	Satisfactory
CRIMSONDR	0761	AC	163	26	Residential	06-02-2021	412	100.0	Good
CRYSTALBEA	0284	AC	919	22	Residential	06-02-2021	134	97.0	Good
CRYSTALPOI	0176	AC	895	36	Residential	06-02-2021	219	67.0	Fair
CRYSTALRID	0020	AC	1,597	34	Residential	06-02-2021	116	93.0	Good
CRYSTALRID	0327	AC	1,516	34	Residential	06-02-2021	222	51.0	Poor
CRYSTALRID	0425	AC	1,621	34	Residential	06-02-2021	294	64.0	Fair
CUMBERLAND	0407	AC	1,154	22	Residential	06-02-2021	212	89.0	Good
CUNNINGHAM	0465	AC	958	24	Residential	06-02-2021	180	77.0	Satisfactory
DAKOTAST	0386	AC	1,351	36	Residential	06-02-2021	166	49.0	Poor
DARBYCT	0612	AC	95	26	Residential	06-02-2021	499	82.0	Satisfactory
DARLINGTON	0001	AC	1,707	22	Residential	06-02-2021	164	99.0	Good
DARLINGTON	0074	AC	3,152	28	Residential	06-02-2021	273	89.0	Good
DARLINGTON	0723	AC	394	22	Residential	06-02-2021	191	87.0	Good
DARLINGTON	0739	AC	490	28	Residential	06-02-2021	239	76.0	Satisfactory
DARLINGTON	0740	AC	353	28	Residential	06-02-2021	353	57.0	Fair
DARLINGTON	0741	AC	473	28	Residential	06-02-2021	324	61.0	Fair
DARTMOORDR	0033	AC	3,229	36	Collector	06-02-2021	130	90.0	Good
DARTMOORDR	0063	AC	688	40	Collector	06-02-2021	296	29.0	Very Poor
DARTMOORDR	0079	AC	4,565	40	Collector	06-02-2021	117	68.0	Fair
DARTMOORDR	0219	AC	1,449	36	Residential	06-02-2021	248	38.0	Very Poor
DARTMOORDR	0546	AC	1,184	24	Residential	06-02-2021	303	58.0	Fair

**List of Pavement Section with 2021 PCI and IRI Values**

Branch ID	Section ID	Surface Type	Length (ft)	Width (ft)	Functional Class	Date	IRI (in/mi)	PCI	PCI Category
DARTMOORDR	0742	AC	282	40	Collector	07-19-2021	200	27.0	Very Poor
DEARBORNCT	0619	AC	692	26	Residential	06-02-2021	308	72.0	Satisfactory
DEERHAVEND	0045	AC	2,466	24	Residential	06-02-2021	231	86.0	Good
DEERHAVEND	0189	AC	1,492	24	Residential	06-02-2021	158	83.0	Satisfactory
DEERHAVEND	0731	AC	60	24	Residential	07-19-2021	200	57.0	Fair
DEERRUN	0318	AC	1,128	24	Residential	06-02-2021	229	49.0	Poor
DEERRUN	0609	AC	1,321	24	Residential	06-02-2021	174	100.0	Good
DENTONCT	0548	AC	537	26	Residential	06-02-2021	101	99.0	Good
DEVONSHIRE	0007	AC	2,725	28	Residential	06-02-2021	216	36.0	Very Poor
DIAMANDOST	0490	AC	732	24	Residential	06-02-2021	150	100.0	Good
DOGWOODDR	0141	AC	2,358	24	Residential	06-02-2021	136	99.0	Good
DOLLELN	0353	AC	450	24	Residential	06-02-2021	248	84.0	Satisfactory
DOLOROSAVI	0311	AC	999	28	Residential	06-02-2021	273	54.0	Poor
DOUGLASAVE	0352	AC	1,807	24	Residential	06-02-2021	311	59.0	Fair
DOVERCLIFF	0025	AC	3,232	24	Residential	06-02-2021	320	42.0	Poor
DOVERCT	0345	AC	900	26	Residential	06-02-2021	248	60.0	Fair
DRIFTWOODC	0368	AC	404	24	Residential	06-02-2021	402	71.0	Satisfactory
DRIFTWOODL	0118	AC	2,628	32	Residential	06-02-2021	212	83.0	Satisfactory
DRIVEINLN	0674	AC	320	24	Residential	06-02-2021	116	64.0	Fair
DRIVEINLN	0675	AC	313	24	Residential	06-02-2021	94	57.0	Fair
DRIVEINLN	0676	AC	313	24	Residential	06-02-2021	89	55.0	Poor
DRIVEINLN	0677	AC	370	24	Residential	06-02-2021	141	61.0	Fair
DUFFYDR	0542	AC	980	36	Residential	06-02-2021	219	54.0	Poor
DURHAMCT	0006	AC	479	24	Residential	06-02-2021	251	46.0	Poor
EAGLEST	0211	AC	890	24	Residential	06-02-2021	245	74.0	Satisfactory
EASTENDAVE	0157	AC	1,030	22	Residential	06-02-2021	126	95.0	Good
EASTGATERD	0250	AC	2,162	22	Residential	06-02-2021	114	100.0	Good
EASTST	0221	AC	1,363	24	Residential	06-02-2021	158	85.0	Satisfactory
EASTST	0305	AC	176	24	Residential	06-02-2021	215	100.0	Good
EASTVIEWAV	0495	AC	804	22	Residential	06-02-2021	190	92.0	Good
EBERKSHIRE	0242	AC	2,522	40	Collector	06-02-2021	160	77.0	Satisfactory
EBERKSHIRE	0560	AC	842	36	Residential	06-02-2021	263	70.0	Fair
EBERKSHIRE	0757	AC	430	40	Collector	06-02-2021	228	80.0	Satisfactory
ECRANDONCT	0482	AC	1,043	24	Residential	06-02-2021	230	97.0	Good
ECRYSTALLA	0222	AC	1,304	36	Arterial	06-02-2021	170	58.0	Fair
ECRYSTALLA	0654	AC	2,678	36	Arterial	06-02-2021	177	52.0	Poor
ECRYSTALLA	0656	AC	2,657	22	Arterial	06-02-2021	191	80.0	Satisfactory
EDGEBROOKD	0180	AC	699	26	Residential	06-02-2021	269	75.0	Satisfactory
EDGEWATERD	0287	AC	468	22	Residential	06-02-2021	248	78.0	Satisfactory
EDGEWATERD	0360	AC	2,220	26	Residential	06-02-2021	256	45.0	Poor
EDGEWOODAV	0613	AC	1,048	22	Residential	06-02-2021	120	96.0	Good
EFRANKLINA	0423	AC	552	22	Residential	06-02-2021	182	82.0	Satisfactory
ELETSONDR	0175	AC	3,091	30	Residential	06-02-2021	181	58.0	Fair
ELLSWORTHS	0070	AC	1,883	24	Residential	06-02-2021	272	69.0	Fair
ELMHURSTST	0193	AC	1,233	26	Collector	06-02-2021	345	41.0	Poor
ELMHURSTST	0584	AC	443	36	Residential	06-02-2021	167	81.0	Satisfactory

**List of Pavement Section with 2021 PCI and IRI Values**

<b>Branch ID</b>	<b>Section ID</b>	<b>Surface Type</b>	<b>Length (ft)</b>	<b>Width (ft)</b>	<b>Functional Class</b>	<b>Date</b>	<b>IRI (in/mi)</b>	<b>PCI</b>	<b>PCI Category</b>
ELMST	0332	AC	772	24	Residential	06-02-2021	262	95.0	Good
ELMWODDAVE	0082	AC	1,585	22	Residential	06-02-2021	318	36.0	Very Poor
ELSINOORLN	0366	AC	1,540	22	Residential	06-02-2021	144	89.0	Good
EMONTICELL	0399	AC	992	24	Residential	07-19-2021	367	100.0	Good
EPADDOCKST	0569	AC	545	22	Residential	06-02-2021	237	33.0	Very Poor
EPALMERCT	0547	AC	959	26	Residential	06-02-2021	280	82.0	Satisfactory
ERICKST	0134	AC	2,642	36	Collector	06-02-2021	139	89.0	Good
ESSEXLN	0095	AC	1,206	22	Residential	06-02-2021	207	93.0	Good
ESTHERST	0298	AC	1,195	22	Residential	06-02-2021	141	93.0	Good
ESTONECREE	0174	AC	1,881	24	Residential	06-02-2021	146	93.0	Good
ESTONECREE	0750	AC	39	24	Residential	06-02-2021	235	100.0	Good
EUGENEST	0556	AC	777	24	Residential	06-02-2021	204	94.0	Good
EVERETTAVE	0051	AC	882	26	Residential	06-02-2021	191	87.0	Good
EVERETTAVE	0168	AC	1,793	22	Residential	06-02-2021	173	73.0	Satisfactory
EVERGREENP	0576	AC	1,272	24	Residential	06-02-2021	190	93.0	Good
EWOODSTOCK	0231	AC	1,483	40	Residential	06-02-2021	247	58.0	Fair
EXCHANGEDR	0248	AC	2,049	36	Residential	06-02-2021	190	68.0	Fair
EXCHANGEDR	0383	AC	2,328	36	Residential	06-02-2021	185	69.0	Fair
EXMOORCT	0256	AC	477	26	Residential	06-02-2021	253	78.0	Satisfactory
EXMOORTER	0302	AC	729	26	Residential	06-02-2021	302	76.0	Satisfactory
FABIUSST	0133	AC	266	28	Residential	06-02-2021	445	52.0	Poor
FACTORYRD	0429	AC	1,238	22	Residential	07-19-2021	293	100.0	Good
FAIRFAXDR	0192	AC	776	24	Residential	07-19-2021	262	100.0	Good
FAIROAKSAV	0420	AC	950	22	Residential	06-02-2021	280	46.0	Poor
FAIRVIEWPA	0502	AC	693	26	Residential	06-02-2021	129	77.0	Satisfactory
FARINGDOND	0415	AC	1,412	26	Residential	06-02-2021	340	57.0	Fair
FARINGDOND	0770	AC	274	26	Residential	06-02-2021	342	50.0	Poor
FEDERALDR	0621	AC	589	36	Residential	06-02-2021	284	28.0	Very Poor
FEDERALDR	0622	AC	1,511	36	Residential	06-02-2021	168	80.0	Satisfactory
FENIMORERD	0245	AC	871	24	Residential	06-02-2021	167	100.0	Good
FERNLEAFDR	0445	AC	749	26	Residential	06-02-2021	150	93.0	Good
FIELDSTONE	0213	AC	1,447	24	Residential	06-02-2021	133	96.0	Good
FIRSTCT	0553	AC	391	22	Residential	06-02-2021	257	91.0	Good
FIRSTCT	0660	AC	379	22	Residential	06-02-2021	264	42.0	Poor
FIRSTST	0308	AC	997	24	Residential	06-02-2021	367	65.0	Fair
FLAGSTONED	0071	AC	1,080	24	Residential	06-02-2021	130	99.0	Good
FLAGSTONED	0737	AC	208	24	Residential	06-02-2021	262	100.0	Good
FLAGSTONED	0738	AC	207	24	Residential	06-02-2021	245	100.0	Good
FLINTTRL	0295	AC	733	24	Residential	06-02-2021	166	66.0	Fair
FLORENCEST	0229	AC	333	24	Residential	06-02-2021	474	37.0	Very Poor
FLORESTAVI	0288	AC	849	22	Residential	06-02-2021	327	69.0	Fair
FORESTLN	0083	AC	1,329	24	Residential	06-02-2021	177	98.0	Good
FOUNTAINGR	0452	AC	1,595	26	Residential	06-02-2021	155	64.0	Fair
FRANCISAVE	0573	AC	325	26	Residential	06-02-2021	189	90.0	Good
GAILCT	0481	AC	160	22	Residential	06-02-2021	359	62.0	Fair
GANDERCT	0414	AC	559	26	Residential	06-02-2021	417	46.0	Poor

**List of Pavement Section with 2021 PCI and IRI Values**

Branch ID	Section ID	Surface Type	Length (ft)	Width (ft)	Functional Class	Date	IRI (in/mi)	PCI	PCI Category
GANDERLN	0055	AC	778	26	Residential	06-02-2021	245	61.0	Fair
GARDINAVIS	0142	AC	1,073	22	Residential	06-02-2021	308	50.0	Poor
GATESST	0220	AC	1,589	24	Residential	06-02-2021	234	80.0	Satisfactory
GEORGIANCT	0496	AC	172	24	Residential	06-02-2021	244	99.0	Good
GILBERTAVE	0382	AC	1,143	22	Residential	06-02-2021	298	53.0	Poor
GLASGOWLN	0580	AC	351	24	Residential	06-02-2021	186	85.0	Satisfactory
GLENNAVE	0283	AC	1,059	24	Residential	06-02-2021	238	76.0	Satisfactory
GLENBROOKR	0110	AC	1,788	24	Residential	06-02-2021	292	56.0	Fair
GLENDALEDR	0519	AC	561	26	Residential	06-02-2021	195	87.0	Good
GLENNNRDG	0505	AC	216	26	Residential	06-02-2021	342	38.0	Very Poor
GLENNNRDG	0577	AC	293	26	Residential	06-02-2021	217	72.0	Satisfactory
GOLDENRODC	0102	AC	467	26	Residential	06-02-2021	241	100.0	Good
GOLDSBOROL	0599	AC	908	24	Residential	06-02-2021	173	72.0	Satisfactory
GOLFCOURSE	0119	AC	5,239	36	Collector	06-02-2021	122	78.0	Satisfactory
GOLFCOURSE	0159	AC	2,353	36	Collector	06-02-2021	123	84.0	Satisfactory
GOLFCOURSE	0197	AC	2,780	36	Collector	06-02-2021	148	66.0	Fair
GOLFRD	0279	AC	1,291	26	Residential	06-02-2021	196	86.0	Good
GOLFRD	0600	AC	967	26	Residential	06-02-2021	150	86.0	Good
GRANDAVE	0539	AC	238	22	Residential	06-02-2021	406	56.0	Fair
GRANDVIEWWD	0303	AC	2,094	24	Residential	06-02-2021	185	98.0	Good
GRANTST	0049	AC	1,280	40	Residential	06-02-2021	228	42.0	Poor
GRANTST	0380	AC	624	40	Residential	06-02-2021	339	54.0	Poor
GREENBRIER	0257	AC	1,950	26	Residential	06-02-2021	163	76.0	Satisfactory
GREENBRIER	0437	AC	528	26	Residential	06-02-2021	255	78.0	Satisfactory
GREENBRIER	0563	AC	531	26	Residential	06-02-2021	211	73.0	Satisfactory
GREENFIELD	0014	AC	1,010	22	Residential	06-02-2021	112	97.0	Good
GREENMEADO	0389	AC	290	26	Residential	06-02-2021	230	60.0	Fair
GREENOAKSD	0477	AC	1,281	30	Residential	06-02-2021	216	47.0	Poor
GREENVIEWC	0516	AC	454	24	Residential	06-02-2021	185	100.0	Good
GREENVIEWD	0059	AC	2,419	24	Residential	06-02-2021	121	100.0	Good
GREENVIEWD	0733	AC	224	24	Residential	06-02-2021	498	100.0	Good
GROUSEWAY	0603	AC	567	26	Residential	06-02-2021	278	49.0	Poor
GROVEST	0299	AC	1,699	24	Residential	06-02-2021	263	50.0	Poor
HALIGUSRD	0636	AC	1,995	22	Collector	07-19-2021	141	100.0	Good
HAMPTONCT	0720	AC	505	24	Residential	06-02-2021	333	91.0	Good
HAROLDST	0406	AC	1,685	24	Residential	06-02-2021	188	87.0	Good
HARPERLN	0367	AC	674	24	Residential	06-02-2021	114	100.0	Good
HARTFORDLN	0562	AC	1,315	26	Residential	06-02-2021	133	98.0	Good
HARVESTCIR	0191	AC	1,453	26	Residential	06-02-2021	425	51.0	Poor
HARVESTCT	0461	AC	439	26	Residential	06-02-2021	569	37.0	Very Poor
HASTINGSAV	0416	AC	602	24	Residential	06-02-2021	194	100.0	Good
HAWTHORNERD	0246	AC	1,631	24	Residential	06-02-2021	330	34.0	Very Poor
HEATHERDR	0212	AC	1,937	22	Residential	06-02-2021	150	89.0	Good
HEATHERDR	0412	AC	822	22	Residential	06-02-2021	165	95.0	Good
HEATHERDR	0632	AC	206	22	Residential	06-02-2021	187	86.0	Good
HEDRICKST	0340	AC	184	24	Residential	06-02-2021	204	100.0	Good

**List of Pavement Section with 2021 PCI and IRI Values**

Branch ID	Section ID	Surface Type	Length (ft)	Width (ft)	Functional Class	Date	IRI (in/mi)	PCI	PCI Category
HEISLERCT	0208	AC	240	26	Residential	06-02-2021	262	78.0	Satisfactory
HELENST	0269	AC	1,233	28	Residential	06-02-2021	224	66.0	Fair
HEMLOCKST	0680	AC	519	24	Residential	06-02-2021	158	59.0	Fair
HEMLOCKST	0687	AC	589	24	Residential	06-02-2021	198	58.0	Fair
HERITAGEDR	0475	AC	913	36	Residential	06-02-2021	221	63.0	Fair
HICKORYDR	0427	AC	1,109	26	Residential	06-02-2021	424	45.0	Poor
HICKORYDR	0555	AC	1,307	26	Residential	06-02-2021	348	56.0	Fair
HIGHLANDAV	0289	AC	1,231	26	Residential	06-02-2021	250	76.0	Satisfactory
HIGHPLAINE	0581	AC	616	26	Residential	06-02-2021	264	52.0	Poor
HILKERTCT	0574	AC	940	24	Residential	06-02-2021	172	77.0	Satisfactory
HILLDR	0036	AC	1,069	24	Residential	06-02-2021	183	40.0	Very Poor
HILLDR	0729	AC	225	24	Residential	06-02-2021	333	37.0	Very Poor
HILLSIDERD	0297	AC	1,336	22	Residential	06-02-2021	114	70.0	Fair
HOLLYDR	0326	AC	699	22	Residential	06-02-2021	195	91.0	Good
HOLLYTREEEL	0202	AC	952	26	Residential	06-02-2021	257	73.0	Satisfactory
HOLLYTREEEL	0753	AC	55	26	Residential	06-02-2021	685	78.0	Satisfactory
HONEYSUCKL	0462	AC	522	22	Residential	06-02-2021	245	86.0	Good
HULLLN	0410	AC	300	26	Residential	06-02-2021	219	76.0	Satisfactory
HUNTERSTR	0097	AC	1,559	24	Residential	06-02-2021	132	95.0	Good
HUNTERSTR	0264	AC	1,262	26	Residential	06-02-2021	502	25.0	Serious
HUNTINGTON	0194	AC	559	26	Residential	06-02-2021	176	81.0	Satisfactory
HUNTLEYRD	0105	AC	3,951	24	Collector	06-02-2021	186	56.0	Fair
HUNTLEYRD	0205	AC	2,819	24	Collector	06-02-2021	119	80.0	Satisfactory
HUNTLEYRD	0351	AC	1,042	24	Collector	06-02-2021	142	53.0	Poor
HUNTLEYRD	0643	AC	138	24	Collector	06-02-2021	164	27.0	Very Poor
ILLINOISST	0209	AC	1,414	24	Residential	06-02-2021	220	78.0	Satisfactory
ILLINOISST	0487	AC	659	24	Residential	06-02-2021	357	45.0	Poor
INDIANHILL	0161	AC	1,565	24	Residential	06-02-2021	181	60.0	Fair
INDUSTRIAL	0092	AC	1,283	24	Residential	06-02-2021	269	37.0	Very Poor
IRISCT	0436	AC	1,008	26	Residential	06-02-2021	156	100.0	Good
IVYLN	0401	AC	1,397	28	Residential	06-02-2021	199	43.0	Poor
JACKMANDR	0602	AC	842	24	Residential	06-02-2021	240	49.0	Poor
JAMESST	0500	AC	486	26	Residential	06-02-2021	112	90.0	Good
JOHNST	0147	AC	828	26	Residential	06-02-2021	287	26.0	Very Poor
JUNIPERLN	0348	AC	800	24	Residential	06-02-2021	138	98.0	Good
KAYST	0443	AC	1,249	28	Residential	06-02-2021	213	57.0	Fair
KEITHAVE	0009	AC	1,714	28	Residential	06-02-2021	179	80.0	Satisfactory
KELLYLN	0470	AC	2,899	24	Residential	06-02-2021	186	84.0	Satisfactory
KELSEYCT	0596	AC	78	24	Residential	06-02-2021	258	49.0	Poor
KENDALLWOO	0005	AC	656	26	Residential	06-02-2021	344	71.0	Satisfactory
KENDALLWOO	0172	AC	657	26	Residential	06-02-2021	236	56.0	Fair
KENNSINGTO	0030	AC	2,418	26	Residential	06-02-2021	180	77.0	Satisfactory
KENNSINGTO	0728	AC	302	26	Residential	06-02-2021	304	71.0	Satisfactory
KENTAVE	0418	AC	876	26	Residential	06-02-2021	303	49.0	Poor
KIMERCT	0466	AC	618	26	Residential	06-02-2021	303	61.0	Fair
KINGSGATEL	0294	AC	1,296	34	Residential	06-02-2021	378	43.0	Poor

**List of Pavement Section with 2021 PCI and IRI Values**

<b>Branch ID</b>	<b>Section ID</b>	<b>Surface Type</b>	<b>Length (ft)</b>	<b>Width (ft)</b>	<b>Functional Class</b>	<b>Date</b>	<b>IRI (in/mi)</b>	<b>PCI</b>	<b>PCI Category</b>
KINGSPORTC	0506	AC	920	26	Residential	06-02-2021	320	64.0	Fair
KINGST	0540	AC	334	24	Residential	06-02-2021	211	80.0	Satisfactory
KINGSTONLN	0385	AC	1,126	26	Residential	06-02-2021	167	90.0	Good
KINGSTONLN	0767	AC	30	26	Residential	06-02-2021	271	81.0	Satisfactory
KNAACKBLVD	0155	AC	1,909	36	Residential	06-02-2021	165	53.0	Poor
KNOLLWOODDC	0089	AC	1,010	24	Residential	06-02-2021	168	98.0	Good
KNOLLWOODDC	0164	AC	1,639	24	Residential	06-02-2021	131	99.0	Good
LAGUNARD	0561	AC	691	26	Residential	06-02-2021	203	75.0	Satisfactory
LAKEAVE	0623	AC	2,443	30	Collector	06-02-2021	179	75.0	Satisfactory
LAKEAVE	0642	AC	1,025	38	Collector	06-02-2021	140	96.0	Good
LAKECT	0550	AC	374	24	Residential	06-02-2021	182	77.0	Satisfactory
LAKESHORED	0143	AC	1,636	32	Residential	06-02-2021	219	73.0	Satisfactory
LAKESHORED	0748	AC	509	32	Residential	06-02-2021	191	89.0	Good
LAKESIDEAV	0507	AC	806	22	Residential	06-02-2021	211	95.0	Good
LAKEST	0184	AC	2,472	24	Residential	06-02-2021	255	84.0	Satisfactory
LAKEST	0313	AC	1,451	22	Residential	06-02-2021	239	64.0	Fair
LAKEVIEWDR	0523	AC	656	26	Residential	06-02-2021	173	98.0	Good
LAKEWOODAV	0435	AC	1,000	22	Residential	06-02-2021	99	97.0	Good
LANCASTERD	0237	AC	1,163	26	Residential	06-02-2021	199	87.0	Good
LARIUMLN	0013	AC	1,113	24	Residential	06-02-2021	332	48.0	Poor
LEEDR	0493	AC	1,493	30	Residential	06-02-2021	365	41.0	Poor
LEONARDPKW	0190	AC	1,137	26	Residential	06-02-2021	252	91.0	Good
LIBERTYRD	0244	AC	2,200	36	Residential	06-02-2021	262	50.0	Poor
LILACDR	0018	AC	1,536	24	Residential	06-02-2021	169	97.0	Good
LILLAVE	0464	AC	730	22	Residential	06-02-2021	151	92.0	Good
LINCOLNPKW	0571	AC	1,273	24	Residential	06-02-2021	174	65.0	Fair
LINCOLNPKW	0583	AC	1,312	26	Residential	06-02-2021	161	94.0	Good
LINCOLNSHI	0094	AC	1,210	22	Residential	06-02-2021	137	92.0	Good
LINNAVE	0081	AC	1,762	22	Residential	06-02-2021	263	50.0	Poor
LOCHLOMOND	0476	AC	1,894	26	Residential	06-02-2021	177	57.0	Fair
LOCHWOODDR	0031	AC	622	24	Residential	06-02-2021	224	65.0	Fair
LOCHWOODDR	0565	AC	1,142	26	Residential	06-02-2021	277	57.0	Fair
LOMBARDDR	0432	AC	336	26	Residential	06-02-2021	296	77.0	Satisfactory
LORRAINEDR	0226	AC	1,034	24	Residential	06-02-2021	228	57.0	Fair
LOUAVE	0271	AC	1,000	22	Residential	06-02-2021	125	95.0	Good
LOUISVILLE	0362	AC	1,065	24	Residential	06-02-2021	148	100.0	Good
LOUISVILLE	0765	AC	196	24	Residential	06-02-2021	338	100.0	Good
LUCASRD	0637	AC	371	22	Collector	06-02-2021	73	70.0	Fair
LUCASRD	0638	AC	1,317	22	Collector	06-02-2021	98	64.0	Fair
LUCASRD	0639	AC	1,315	22	Collector	06-02-2021	173	75.0	Satisfactory
LUCERNEDR	0488	AC	596	26	Residential	06-02-2021	211	49.0	Poor
LUTTERDR	0185	AC	3,119	36	Residential	06-02-2021	197	64.0	Fair
MAGNOLIADR	0215	AC	864	26	Residential	07-19-2021	120	90.0	Good
MAGNOLIADR	0624	AC	561	24	Residential	07-19-2021	300	12.0	Serious
MANCHESTER	0210	AC	1,126	24	Residential	06-02-2021	143	99.0	Good
MANCHESTER	0503	AC	403	24	Residential	06-02-2021	180	96.0	Good

**List of Pavement Section with 2021 PCI and IRI Values**

Branch ID	Section ID	Surface Type	Length (ft)	Width (ft)	Functional Class	Date	IRI (in/mi)	PCI	PCI Category
MANORRD	0135	AC	2,229	24	Residential	06-02-2021	147	53.0	Poor
MANORRD	0474	AC	358	24	Residential	06-02-2021	237	62.0	Fair
MAPLEST	0439	AC	1,124	24	Residential	06-02-2021	204	46.0	Poor
MAPLEST	0648	AC	1,062	24	Residential	06-02-2021	128	92.0	Good
MAPLEWOODL	0469	AC	992	24	Residential	06-02-2021	232	53.0	Poor
MARHILCT	0203	AC	360	45	Residential	06-02-2021	202	87.0	Good
MARIANPKWY	0040	AC	1,270	28	Residential	06-02-2021	183	90.0	Good
MARYLN	0067	AC	2,045	24	Residential	06-02-2021	161	92.0	Good
MARYLN	0123	AC	196	24	Residential	06-02-2021	292	72.0	Satisfactory
MAYFIELDAV	0200	AC	1,010	22	Residential	06-02-2021	88	100.0	Good
MCARDLEDR	0442	AC	951	36	Residential	06-02-2021	196	41.0	Poor
MCCULLOMST	0331	AC	669	24	Residential	06-02-2021	239	85.0	Satisfactory
MCHENRYAVE	0088	AC	9,703	48	Arterial	06-02-2021	117	86.0	Good
MCHENRYAVE	0140	AC	4,225	34	Collector	06-02-2021	136	87.0	Good
MELROSELN	0060	AC	1,090	22	Residential	06-02-2021	185	93.0	Good
MEMORIALCT	0186	AC	226	36	Residential	07-19-2021	322	100.0	Good
MEMORIALDR	0075	AC	1,932	36	Residential	07-19-2021	245	100.0	Good
MERIDIANST	0471	AC	1,050	22	Residential	06-02-2021	198	99.0	Good
MERRIMACKC	0371	AC	179	26	Residential	06-02-2021	147	81.0	Satisfactory
MEYERDR	0479	AC	405	36	Residential	07-16-2021	200	55.0	Poor
MIDLANEDR	0139	AC	2,871	24	Residential	06-02-2021	200	72.0	Satisfactory
MIDWAYCT	0359	AC	468	24	Residential	06-02-2021	371	50.0	Poor
MILLARDAVE	0467	AC	1,610	22	Residential	06-02-2021	249	41.0	Poor
MILLENNIUM	0304	AC	1,248	36	Residential	06-02-2021	155	59.0	Fair
MILLERRD	0150	AC	3,865	40	Collector	06-02-2021	145	65.0	Fair
MILLERRD	0267	AC	3,194	40	Collector	06-02-2021	134	72.0	Satisfactory
MINNIEST	0261	AC	726	24	Residential	06-02-2021	268	81.0	Satisfactory
MIRAST	0448	AC	1,345	24	Residential	06-02-2021	176	97.0	Good
MISTWOODLN	0048	AC	879	28	Residential	06-02-2021	370	42.0	Poor
MITCHELLCT	0440	AC	565	34	Residential	06-02-2021	179	79.0	Satisfactory
MITCHELLCT	0606	AC	219	34	Residential	06-02-2021	220	68.0	Fair
MONTEREYDR	0309	AC	1,447	26	Residential	06-02-2021	128	99.0	Good
MOORLANDLN	0042	AC	947	24	Residential	06-02-2021	174	82.0	Satisfactory
MOORLANDLN	0120	AC	1,155	24	Residential	06-02-2021	473	40.0	Very Poor
MOORLANDLN	0747	AC	241	24	Residential	06-02-2021	548	24.0	Serious
MORGANST	0597	AC	658	24	Residential	06-02-2021	230	65.0	Fair
MTTHABORRD	0635	AC	1,319	20	Residential	07-19-2021	161	100.0	Good
MULBERRYLN	0403	AC	1,570	22	Residential	06-02-2021	241	53.0	Poor
MUNSHAWLN	0029	AC	1,117	36	Residential	06-02-2021	165	74.0	Satisfactory
N/A	0590	AC	98	22	Residential	06-02-2021	385	56.0	Fair
N/A	0620	AC	235	36	Residential	06-02-2021	267	63.0	Fair
N/A	0628	AC	319	26	Residential	06-02-2021	312	74.0	Satisfactory
N/A	0664	AC	314	24	Residential	06-02-2021	236	54.0	Poor
NARRAGANSE	0713	AC	544	24	Residential	06-02-2021	305	69.0	Fair
NASHRD	0054	AC	2,959	34	Residential	06-02-2021	112	95.0	Good
NASHRD	0629	AC	280	34	Residential	06-02-2021	223	81.0	Satisfactory

**List of Pavement Section with 2021 PCI and IRI Values**

Branch ID	Section ID	Surface Type	Length (ft)	Width (ft)	Functional Class	Date	IRI (in/mi)	PCI	PCI Category
NASHUACT	0718	AC	546	24	Residential	06-02-2021	242	90.0	Good
NASHUACT	0719	AC	216	24	Residential	06-02-2021	262	78.0	Satisfactory
NASHVILLEL	0272	AC	1,940	24	Residential	06-02-2021	125	100.0	Good
NASHVILLEL	0758	AC	187	24	Residential	06-02-2021	255	95.0	Good
NASHVILLEL	0759	AC	262	24	Residential	06-02-2021	136	100.0	Good
NCAROLINES	0280	AC	1,307	26	Residential	06-02-2021	221	70.0	Fair
NDOLEAVE	0329	AC	2,064	30	Collector	06-02-2021	125	88.0	Good
NEWBURYDR	0605	AC	510	24	Residential	06-02-2021	196	72.0	Satisfactory
NEWCASTLEC	0066	AC	1,055	24	Residential	06-02-2021	457	96.0	Good
NIMCODR	0268	AC	1,017	36	Residential	06-02-2021	182	33.0	Very Poor
NMAINST	0128	AC	1,717	24	Residential	06-02-2021	268	18.0	Serious
NMAINST	0363	AC	663	24	Residential	06-02-2021	187	74.0	Satisfactory
NMAINST	0460	AC	914	36	Collector	06-02-2021	272	50.0	Poor
NOAKST	0056	AC	1,310	30	Collector	06-02-2021	166	97.0	Good
NOAKST	0451	AC	1,658	30	Collector	06-02-2021	220	39.0	Very Poor
NOAKST	0626	AC	1,471	30	Collector	06-02-2021	150	67.0	Fair
NOAKST	0627	AC	1,436	30	Collector	06-02-2021	221	70.0	Fair
NORIOLETRL	0498	AC	745	26	Residential	06-02-2021	142	87.0	Good
NORTHAMPTO	0337	AC	1,504	26	Residential	06-02-2021	200	38.0	Very Poor
NORTHAVE	0077	AC	1,218	26	Collector	06-02-2021	148	65.0	Fair
NORTHSHORE	0032	AC	4,145	24	Residential	06-02-2021	113	94.0	Good
NORTHSHORE	0249	AC	2,574	26	Residential	06-02-2021	83	98.0	Good
NORTHSHORE	0591	AC	390	22	Residential	06-02-2021	154	88.0	Good
NORWICHCT	0716	AC	160	24	Residential	06-02-2021	313	80.0	Satisfactory
NORWICHCT	0717	AC	730	24	Residential	06-02-2021	183	66.0	Fair
NOTTINGHAM	0238	AC	3,283	36	Residential	06-02-2021	111	96.0	Good
NOTTINGHAM	0426	AC	187	26	Residential	06-02-2021	282	63.0	Fair
NOTTINGHAM	0515	AC	1,240	38	Residential	06-02-2021	147	97.0	Good
NUNDATRL	0486	AC	1,346	24	Residential	06-02-2021	366	47.0	Poor
NWALKUPAVE	0149	AC	1,940	36	Arterial	06-02-2021	305	72.0	Satisfactory
NWALKUPAVE	0374	AC	653	60	Arterial	06-02-2021	278	91.0	Good
NWILLIAMSS	0291	AC	1,001	40	Residential	06-02-2021	184	55.0	Poor
OAKCT	0508	AC	881	24	Residential	06-02-2021	188	83.0	Satisfactory
OAKHOLLOWC	0615	AC	210	36	Residential	06-02-2021	285	83.0	Satisfactory
OAKHOLLOWR	0012	AC	1,067	26	Residential	06-02-2021	323	43.0	Poor
OAKHOLLOWR	0243	AC	1,925	36	Residential	06-02-2021	246	83.0	Satisfactory
OAKHOLLOWR	0387	AC	235	26	Residential	06-02-2021	442	41.0	Poor
OAKHOLLOWR	0768	AC	271	26	Residential	06-02-2021	364	67.0	Fair
OAKVALLEYC	0373	AC	380	24	Residential	06-02-2021	193	100.0	Good
OAKVALLEYD	0057	AC	1,353	24	Residential	06-02-2021	137	97.0	Good
OFFICIALRD	0582	AC	1,136	22	Residential	06-02-2021	119	97.0	Good
OLDEPOSTRD	0357	AC	980	24	Residential	07-19-2021	244	100.0	Good
OLDWESTBUR	0178	AC	1,718	24	Residential	06-02-2021	128	98.0	Good
OLDWESTBUR	0379	AC	485	24	Residential	06-02-2021	223	98.0	Good
ORCHARDROW	0592	AC	358	26	Residential	06-02-2021	274	64.0	Fair
OXFORDLN	0286	AC	1,191	22	Residential	06-02-2021	211	93.0	Good

**List of Pavement Section with 2021 PCI and IRI Values**

<b>Branch ID</b>	<b>Section ID</b>	<b>Surface Type</b>	<b>Length (ft)</b>	<b>Width (ft)</b>	<b>Functional Class</b>	<b>Date</b>	<b>IRI (in/mi)</b>	<b>PCI</b>	<b>PCI Category</b>
PARKBLVD	0101	AC	1,015	24	Residential	06-02-2021	143	81.0	Satisfactory
PARKLN	0529	AC	368	24	Residential	06-02-2021	208	64.0	Fair
PARKRIDGECEC	0618	AC	359	26	Residential	06-02-2021	317	68.0	Fair
PARKRIDGED	0021	AC	1,033	26	Residential	06-02-2021	182	55.0	Poor
PARKSIDECT	0365	AC	610	24	Residential	06-02-2021	275	75.0	Satisfactory
PARKSIDETE	0601	AC	460	24	Residential	06-02-2021	412	75.0	Satisfactory
PARKVIEWCT	0494	AC	1,467	24	Residential	06-02-2021	119	99.0	Good
PATHWAYCT	0004	AC	759	36	Residential	06-02-2021	216	65.0	Fair
PEBBLELN	0158	AC	610	26	Residential	06-02-2021	297	85.0	Satisfactory
PENNYLN	0112	AC	1,738	26	Residential	06-02-2021	258	90.0	Good
PENNYLN	0744	AC	250	26	Residential	06-02-2021	328	87.0	Good
PENNYLN	0745	AC	236	26	Residential	06-02-2021	249	79.0	Satisfactory
PETERSONPK	0527	AC	1,271	24	Residential	06-02-2021	178	88.0	Good
PHEASANTLN	0019	AC	326	26	Residential	06-02-2021	252	62.0	Fair
PIERSONST	0034	AC	2,366	24	Residential	06-02-2021	302	75.0	Satisfactory
PINECT	0223	AC	1,130	22	Residential	06-02-2021	168	64.0	Fair
PINEST	0510	AC	509	24	Residential	06-02-2021	408	49.0	Poor
PINEWOODDR	0136	AC	498	22	Residential	06-02-2021	303	71.0	Satisfactory
PINGREERD	0072	AC	2,406	36	Collector	06-02-2021	154	88.0	Good
PINGREERD	0080	AC	4,730	36	Collector	06-02-2021	130	89.0	Good
PINGREERD	0341	AC	1,719	56	Collector	06-02-2021	231	42.0	Poor
PINGREERD	0530	AC	1,550	28	Collector	06-02-2021	182	63.0	Fair
PINGREERD	0630	AC	492	36	Collector	06-02-2021	222	42.0	Poor
PIPERCT	0073	AC	205	26	Residential	06-02-2021	317	84.0	Satisfactory
PLUMTREEDR	0333	AC	2,113	24	Residential	06-02-2021	301	33.0	Very Poor
PLYMOUTHLN	0558	AC	1,045	22	Residential	06-02-2021	206	78.0	Satisfactory
POINTEDR	0458	AC	1,417	24	Residential	06-02-2021	278	40.0	Very Poor
POMEROYAVE	0270	AC	2,685	24	Residential	06-02-2021	195	80.0	Satisfactory
POMEROYAVE	0568	AC	830	24	Residential	06-02-2021	168	92.0	Good
POPLARST	0107	AC	1,321	24	Residential	06-02-2021	179	86.0	Good
PORTERAVE	0501	AC	1,040	26	Residential	06-02-2021	155	95.0	Good
PRAIRIEST	0336	AC	1,720	24	Residential	06-02-2021	287	36.0	Very Poor
PRAIRIEST	0504	AC	1,088	24	Residential	06-02-2021	284	41.0	Poor
PRESCOLTLN	0225	AC	1,255	24	Residential	06-02-2021	399	56.0	Fair
PRIMROSELN	0109	AC	394	26	Residential	06-02-2021	231	46.0	Poor
PRIMROSELN	0388	AC	872	26	Residential	06-02-2021	310	52.0	Poor
PROVIDENCE	0216	AC	2,635	34	Residential	06-02-2021	191	65.0	Fair
PROVIDENCE	0711	AC	95	24	Residential	06-02-2021	377	48.0	Poor
PROVIDENCE	0712	AC	362	24	Residential	06-02-2021	412	50.0	Poor
PROVIDENCE	0754	AC	237	34	Residential	06-02-2021	317	59.0	Fair
QUAILWAY	0424	AC	572	26	Residential	06-02-2021	304	29.0	Very Poor
QUEENSPORT	0434	AC	899	24	Residential	06-02-2021	174	74.0	Satisfactory
RAILROADST	0259	AC	1,593	24	Residential	06-02-2021	334	34.0	Very Poor
RAYMONDDR	0557	AC	1,045	36	Residential	06-02-2021	131	87.0	Good
RAYST	0509	AC	562	24	Residential	06-02-2021	241	48.0	Poor
REBECCAST	0578	AC	700	24	Residential	06-02-2021	198	95.0	Good

**List of Pavement Section with 2021 PCI and IRI Values**

Branch ID	Section ID	Surface Type	Length (ft)	Width (ft)	Functional Class	Date	IRI (in/mi)	PCI	PCI Category
REDWOODST	0679	AC	519	24	Residential	06-02-2021	97	67.0	Fair
REDWOODST	0686	AC	591	24	Residential	06-02-2021	192	55.0	Poor
REGALDR	0235	AC	1,184	36	Residential	06-02-2021	198	74.0	Satisfactory
REGALDR	0756	AC	36	36	Residential	06-02-2021	192	82.0	Satisfactory
REGENTDR	0015	AC	2,484	26	Residential	06-02-2021	188	51.0	Poor
REILANDDR	0538	AC	1,046	28	Residential	06-02-2021	368	64.0	Fair
RESERVEDR	0521	AC	1,616	26	Residential	06-02-2021	268	59.0	Fair
REVEREDR	0564	AC	730	24	Residential	06-02-2021	181	100.0	Good
RICHARDDR	0646	AC	190	24	Residential	06-02-2021	185	60.0	Fair
RICKERTRD	0285	AC	656	24	Residential	06-02-2021	204	68.0	Fair
RIDGEAVE	0153	AC	1,307	26	Residential	06-02-2021	242	100.0	Good
RIDGEAVE	0330	AC	1,349	26	Residential	06-02-2021	367	37.0	Very Poor
RIDGEWOODL	0041	AC	1,040	24	Residential	06-02-2021	355	43.0	Poor
RINGLINGRD	0022	AC	1,102	26	Residential	06-02-2021	230	61.0	Fair
RIVERSIDED	0323	AC	927	22	Residential	06-02-2021	112	100.0	Good
RIVERSIDED	0762	AC	1,264	22	Residential	06-02-2021	146	99.0	Good
ROCKLANDRD	0572	AC	1,585	26	Residential	06-02-2021	148	95.0	Good
ROLLINGHIL	0408	AC	3,316	26	Residential	06-02-2021	427	44.0	Poor
ROSEDALEAV	0052	AC	1,154	22	Residential	06-02-2021	275	87.0	Good
ROSENTHALD	0593	AC	460	36	Residential	06-02-2021	325	35.0	Very Poor
ROSENTHALD	0772	AC	149	36	Residential	06-02-2021	513	17.0	Serious
ROEST	0241	AC	1,243	24	Residential	06-02-2021	181	49.0	Poor
ROSEWOODLN	0251	AC	713	26	Residential	06-02-2021	173	76.0	Satisfactory
RUDATCT	0342	AC	452	30	Residential	06-02-2021	377	34.0	Very Poor
RYANWAY	0607	AC	650	26	Residential	06-02-2021	326	29.0	Very Poor
RYANWAY	0659	AC	323	26	Residential	06-02-2021	278	44.0	Poor
SADDLECREE	0344	AC	994	24	Residential	06-02-2021	159	86.0	Good
SADDLERDG	0433	AC	1,749	24	Residential	06-02-2021	244	54.0	Poor
SADDLERDG	0453	AC	1,242	24	Residential	06-02-2021	249	72.0	Satisfactory
SAGGERSLN	0681	AC	321	24	Residential	06-02-2021	328	67.0	Fair
SAGGERSLN	0682	AC	313	24	Residential	06-02-2021	174	55.0	Poor
SAGGERSLN	0683	AC	313	24	Residential	06-02-2021	196	74.0	Satisfactory
SAGGERSLN	0684	AC	346	24	Residential	06-02-2021	201	56.0	Fair
SANDALWOOD	0230	AC	1,604	24	Residential	06-02-2021	468	37.0	Very Poor
SANDALWOOD	0398	AC	1,814	24	Residential	06-02-2021	253	73.0	Satisfactory
SANDSRD	0532	AC	2,265	34	Residential	06-02-2021	203	59.0	Fair
SANDSRD	0645	AC	2,265	34	Residential	06-02-2021	277	36.0	Very Poor
SARASOTALN	0129	AC	1,589	24	Residential	06-02-2021	189	65.0	Fair
SAVANNAHLN	0459	AC	1,267	24	Residential	06-02-2021	316	41.0	Poor
SBRENTWOOD	0126	AC	2,112	26	Residential	06-02-2021	196	50.0	Poor
SCAROLINES	0455	AC	1,136	24	Residential	06-02-2021	267	76.0	Satisfactory
SDOLEAVE	0132	AC	2,969	30	Collector	06-02-2021	257	30.0	Very Poor
SDOLEAVE	0489	AC	1,715	30	Collector	06-02-2021	252	47.0	Poor
SECONDCT	0023	AC	767	22	Residential	06-02-2021	340	78.0	Satisfactory
SECONDST	0277	AC	1,069	24	Residential	06-02-2021	322	51.0	Poor
SEDGEWICKC	0721	AC	319	24	Residential	06-02-2021	365	57.0	Fair

**List of Pavement Section with 2021 PCI and IRI Values**

Branch ID	Section ID	Surface Type	Length (ft)	Width (ft)	Functional Class	Date	IRI (in/mi)	PCI	PCI Category
SEGEWICKC	0722	AC	142	24	Residential	06-02-2021	325	84.0	Satisfactory
SEYBROOKEC	0651	AC	1,376	24	Residential	06-02-2021	173	95.0	Good
SHADOWOODL	0321	AC	1,028	24	Residential	06-02-2021	252	67.0	Fair
SHALESST	0688	AC	758	24	Residential	06-02-2021	132	67.0	Fair
SHARONDRL	0204	AC	894	30	Residential	06-02-2021	175	79.0	Satisfactory
SHEFFIELDDD	0375	AC	1,486	26	Residential	06-02-2021	203	54.0	Poor
SHEFFIELDDD	0766	AC	496	26	Residential	06-02-2021	266	63.0	Fair
SHELTONLN	0320	AC	1,113	26	Residential	06-02-2021	159	73.0	Satisfactory
SHERBONLN	0276	AC	851	26	Residential	06-02-2021	184	53.0	Poor
SHERBROOKE	0714	AC	289	24	Residential	06-02-2021	224	95.0	Good
SHERBROOKE	0715	AC	141	24	Residential	06-02-2021	384	97.0	Good
SHERMANST	0163	AC	1,082	24	Residential	06-02-2021	304	70.0	Fair
SHERMANST	0334	AC	650	24	Residential	06-02-2021	248	59.0	Fair
SHIPLANDDR	0217	AC	1,970	26	Residential	06-02-2021	256	34.0	Very Poor
SHORTST	0002	AC	387	24	Residential	06-02-2021	199	47.0	Poor
SHORTST	0587	AC	162	24	Residential	06-02-2021	246	96.0	Good
SILKOAKLN	0111	AC	1,623	24	Residential	06-02-2021	373	36.0	Very Poor
SILVERBERR	0535	AC	714	26	Residential	06-02-2021	148	99.0	Good
SKYRIDGEDR	0087	AC	1,552	26	Residential	06-02-2021	176	75.0	Satisfactory
SMAINST	0171	AC	5,450	42	Arterial	07-19-2021	183	100.0	Good
SMAINST	0449	AC	2,679	58	Arterial	06-02-2021	180	64.0	Fair
SMAINST	0777	AC	785	58	Arterial	07-19-2021	180	100.0	Good
SMITANARD	0233	AC	1,717	24	Residential	06-02-2021	414	17.0	Serious
SNOWBERRYL	0446	AC	1,292	22	Residential	06-02-2021	256	46.0	Poor
SOAKST	0263	AC	1,239	30	Collector	06-02-2021	130	81.0	Satisfactory
SOMERFIELD	0047	AC	2,355	26	Residential	06-02-2021	158	81.0	Satisfactory
SOMERFIELD	0732	AC	269	26	Residential	06-02-2021	263	81.0	Satisfactory
SORIOLETRL	0016	AC	3,586	24	Residential	06-02-2021	231	65.0	Fair
SOUTHST	0394	AC	560	22	Residential	06-02-2021	254	87.0	Good
SPRINGRIDG	0026	AC	1,732	24	Residential	06-02-2021	353	53.0	Poor
SPRINGRIDG	0727	AC	30	24	Residential	06-02-2021	635	24.0	Serious
SPRUCELN	0144	AC	942	26	Residential	06-02-2021	188	50.0	Poor
STANDREWSL	0214	AC	2,765	34	Residential	06-02-2021	126	80.0	Satisfactory
STATEST	0372	AC	1,698	24	Residential	06-02-2021	135	56.0	Fair
STOCKTONLN	0117	AC	2,629	26	Residential	06-02-2021	159	78.0	Satisfactory
STOCKTONLN	0746	AC	195	26	Residential	06-02-2021	403	66.0	Fair
STONEBRIDG	0534	AC	880	26	Residential	06-02-2021	390	64.0	Fair
STONEBRIDG	0585	AC	1,324	24	Residential	06-02-2021	220	70.0	Fair
STONEHEDGE	0518	AC	374	24	Residential	06-02-2021	256	69.0	Fair
STONYHILL	0152	AC	1,432	24	Residential	06-02-2021	175	90.0	Good
STONYHILL	0774	AC	202	24	Residential	06-02-2021	368	87.0	Good
SUFFOLKDR	0116	AC	1,208	26	Residential	06-02-2021	312	28.0	Very Poor
SUNNYSIDEA	0395	AC	1,027	22	Residential	06-02-2021	128	81.0	Satisfactory
SUNSETTER	0166	AC	108	24	Residential	06-02-2021	287	31.0	Very Poor
SUNSETTER	0430	AC	381	24	Residential	06-02-2021	166	44.0	Poor
SUNSETTER	0771	AC	72	24	Residential	07-16-2021	182	33.0	Very Poor

**List of Pavement Section with 2021 PCI and IRI Values**

Branch ID	Section ID	Surface Type	Length (ft)	Width (ft)	Functional Class	Date	IRI (in/mi)	PCI	PCI Category
SURREYLN	0236	AC	2,040	26	Residential	06-02-2021	126	93.0	Good
SUSSEXLN	0173	AC	1,075	26	Residential	06-02-2021	200	89.0	Good
SUSSEXLN	0617	AC	1,405	22	Residential	06-02-2021	244	49.0	Poor
SUTHERLAND	0100	AC	1,259	26	Residential	06-02-2021	227	75.0	Satisfactory
SUTTONDR	0497	AC	288	26	Residential	06-02-2021	230	81.0	Satisfactory
SWALKUPAVE	0160	AC	1,201	34	Residential	06-02-2021	208	81.0	Satisfactory
SWALKUPAVE	0307	AC	1,109	22	Residential	06-02-2021	194	94.0	Good
SWANSONRD	0106	AC	5,220	36	Collector	06-02-2021	184	84.0	Satisfactory
SWILLIAMSS	0473	AC	1,597	30	Residential	06-02-2021	208	67.0	Fair
SYCAMORELN	0234	AC	346	26	Residential	06-02-2021	257	62.0	Fair
TALCOTTAVE	0154	AC	2,058	26	Residential	06-02-2021	342	64.0	Fair
TALCOTTAVE	0749	AC	211	26	Residential	06-02-2021	661	56.0	Fair
TALCOTTCT	0252	AC	333	26	Residential	06-02-2021	417	83.0	Satisfactory
TALISMONCT	0322	AC	1,152	24	Residential	06-02-2021	132	96.0	Good
TALISMONDR	0017	AC	4,163	24	Residential	06-02-2021	179	99.0	Good
TAMARISKLN	0356	AC	1,062	26	Residential	06-02-2021	127	86.0	Good
TAMARISKTE	0541	AC	689	26	Residential	06-02-2021	216	86.0	Good
TANGLEWOOD	0043	AC	1,073	24	Residential	06-02-2021	455	45.0	Poor
TANGLEWOOD	0086	AC	798	26	Residential	06-02-2021	306	77.0	Satisfactory
TANGLEWOOD	0730	AC	222	24	Residential	06-02-2021	513	42.0	Poor
TEAKWOODLN	0537	AC	984	22	Residential	06-02-2021	298	79.0	Satisfactory
TECKLERBLV	0262	AC	1,882	38	Collector	06-02-2021	258	48.0	Poor
TECKLERBLV	0324	AC	1,140	36	Residential	06-02-2021	326	36.0	Very Poor
TECKLERBLV	0422	AC	1,304	36	Residential	06-02-2021	208	71.0	Satisfactory
TEKDR	0405	AC	2,630	36	Residential	06-02-2021	157	87.0	Good
TERRACOTTA	0145	AC	2,876	24	Collector	06-02-2021	117	91.0	Good
TERRACOTTA	0247	AC	2,581	24	Collector	06-02-2021	187	58.0	Fair
TERRACOTTA	0631	AC	982	24	Collector	06-02-2021	159	85.0	Satisfactory
TEVERTONLN	0108	AC	1,106	26	Residential	06-02-2021	238	49.0	Poor
THIRDST	0598	AC	446	24	Residential	06-02-2021	280	74.0	Satisfactory
THOMASVILL	0316	AC	1,027	24	Residential	06-02-2021	164	90.0	Good
THORNWOODL	0350	AC	2,211	22	Residential	06-02-2021	139	88.0	Good
THREEOAKSR	0090	AC	5,675	30	Collector	06-02-2021	167	62.0	Fair
TIMBERHILL	0457	AC	843	22	Residential	06-02-2021	193	73.0	Satisfactory
TOMAHAWKLN	0121	AC	964	24	Residential	06-02-2021	240	55.0	Poor
TOMAHAWKLN	0491	AC	507	24	Residential	06-02-2021	165	98.0	Good
TRACYTRL	0586	AC	656	36	Residential	06-02-2021	281	70.0	Fair
TRAILWOODC	0239	AC	361	26	Residential	06-02-2021	327	76.0	Satisfactory
TRAILWOODD	0354	AC	1,033	24	Residential	06-02-2021	384	51.0	Poor
TRAILWOODD	0454	AC	854	26	Residential	06-02-2021	264	69.0	Fair
UNIONST	0275	AC	2,952	30	Residential	06-02-2021	273	49.0	Poor
UNIVERSITY	0265	AC	949	22	Residential	06-02-2021	300	78.0	Satisfactory
UTEGST	0315	AC	959	22	Residential	06-02-2021	205	84.0	Satisfactory
VANBURENST	0428	AC	946	30	Residential	06-02-2021	289	81.0	Satisfactory
VICTORPKWY	0485	AC	916	26	Residential	06-02-2021	177	68.0	Fair
VIEWST	0024	AC	971	24	Residential	06-02-2021	160	94.0	Good

**List of Pavement Section with 2021 PCI and IRI Values**

Branch ID	Section ID	Surface Type	Length (ft)	Width (ft)	Functional Class	Date	IRI (in/mi)	PCI	PCI Category
VILLAGECT	0125	AC	541	26	Residential	06-02-2021	199	92.0	Good
VILLAGERD	0061	AC	3,961	34	Collector	06-02-2021	155	82.0	Satisfactory
VILLAGERD	0091	AC	958	34	Collector	06-02-2021	104	77.0	Satisfactory
VILLAGERD	0195	AC	1,533	34	Collector	06-02-2021	163	94.0	Good
VILLAGERD	0224	AC	673	26	Residential	06-02-2021	318	89.0	Good
VILLAGERD	0444	AC	2,887	34	Collector	06-02-2021	219	56.0	Fair
VILLAGERD	0672	AC	83	24	Residential	06-02-2021	336	100.0	Good
VILLAGERD	0673	AC	300	24	Residential	06-02-2021	211	97.0	Good
WALLACEAVE	0278	AC	2,504	30	Residential	06-02-2021	128	97.0	Good
WALLACEAVE	0456	AC	384	22	Residential	06-02-2021	185	86.0	Good
WARRINGTON	0232	AC	1,223	26	Residential	06-02-2021	156	82.0	Satisfactory
WASHINGTON	0162	AC	666	24	Residential	07-19-2021	300	100.0	Good
WATERFORDC	0254	AC	4,075	32	Residential	06-02-2021	185	78.0	Satisfactory
WCRYSTALLA	0039	AC	1,596	32	Arterial	06-02-2021	118	78.0	Satisfactory
WCRYSTALLA	0206	AC	1,388	34	Residential	06-02-2021	195	88.0	Good
WCRYSTALLA	0567	AC	473	26	Residential	06-02-2021	357	57.0	Fair
WCRYSTALLA	0655	AC	2,414	30	Arterial	06-02-2021	194	85.0	Satisfactory
WEDGEWOODD	0008	AC	4,802	26	Residential	06-02-2021	140	96.0	Good
WEDGEWOODD	0317	AC	2,699	26	Residential	06-02-2021	148	88.0	Good
WEDGEWOODD	0725	AC	357	26	Residential	06-02-2021	216	100.0	Good
WEDGEWOODD	0726	AC	336	26	Residential	06-02-2021	270	95.0	Good
WELLINGTON	0065	AC	2,023	26	Residential	06-02-2021	260	46.0	Poor
WELLINGTON	0735	AC	425	26	Residential	07-16-2021	300	33.0	Very Poor
WESLEYDR	0667	AC	509	24	Residential	06-02-2021	212	72.0	Satisfactory
WESTOND'R	0396	AC	848	26	Residential	06-02-2021	184	84.0	Satisfactory
WESTPORTCT	0441	AC	151	26	Residential	06-02-2021	315	76.0	Satisfactory
WESTPORTRD	0037	AC	1,657	24	Residential	06-02-2021	224	75.0	Satisfactory
WESTPORTRD	0328	AC	2,671	26	Residential	06-02-2021	270	44.0	Poor
WESTPORTRD	0649	AC	1,393	26	Residential	06-02-2021	232	62.0	Fair
WESTPORTRD	0773	AC	190	26	Residential	06-02-2021	307	62.0	Fair
WFANKLINA	0513	AC	555	34	Residential	06-02-2021	204	63.0	Fair
WFANKLINA	0524	AC	1,103	34	Residential	06-02-2021	249	31.0	Very Poor
WHEATLANDC	0588	AC	465	26	Residential	06-02-2021	494	34.0	Very Poor
WHEATLANDD	0319	AC	1,962	26	Residential	06-02-2021	435	33.0	Very Poor
WHITEHALLW	0183	AC	1,008	24	Residential	06-02-2021	308	48.0	Poor
WIGGINTOND	0390	AC	1,059	26	Residential	06-02-2021	189	82.0	Satisfactory
WILDFLOWER	0499	AC	900	24	Residential	06-02-2021	258	53.0	Poor
WILLIAMSBU	0549	AC	1,477	24	Residential	06-02-2021	153	96.0	Good
WILLOWTREE	0078	AC	1,669	26	Residential	06-02-2021	177	89.0	Good
WILTSIREC	0188	AC	1,249	22	Residential	06-02-2021	225	56.0	Fair
WIMBLETONL	0525	AC	539	24	Residential	07-16-2021	90	100.0	Good
WINDHAMCOV	0343	AC	1,553	26	Residential	06-02-2021	244	66.0	Fair
WINDHAMCOV	0579	AC	533	26	Residential	06-02-2021	170	71.0	Satisfactory
WINDRIDGED	0536	AC	1,069	24	Residential	07-16-2021	330	51.0	Poor
WINDSLOWCI	0096	AC	1,023	26	Residential	06-02-2021	280	53.0	Poor
WINDSORDR	0240	AC	1,659	26	Residential	06-02-2021	110	89.0	Good

**List of Pavement Section with 2021 PCI and IRI Values**

Branch ID	Section ID	Surface Type	Length (ft)	Width (ft)	Functional Class	Date	IRI (in/mi)	PCI	PCI Category
WOODBINEDR	0608	AC	699	22	Residential	06-02-2021	261	89.0	Good
WOODHAVEND	0409	AC	1,554	24	Residential	06-02-2021	141	81.0	Satisfactory
WOODLANDDR	0611	AC	2,914	24	Residential	06-02-2021	212	94.0	Good
WOODMARDR	0044	AC	444	26	Residential	06-02-2021	233	100.0	Good
WOODMARDR	0227	AC	866	26	Residential	06-02-2021	191	99.0	Good
WOODMARDR	0755	AC	58	26	Residential	06-02-2021	351	100.0	Good
WOODSCREEK	0381	AC	2,626	26	Residential	06-02-2021	198	96.0	Good
WPADDOCKST	0472	AC	1,419	24	Residential	06-02-2021	271	64.0	Fair
WSTONECREE	0355	AC	1,718	24	Residential	06-02-2021	131	90.0	Good
WSTONECREE	0763	AC	24	24	Residential	06-02-2021	988	85.0	Satisfactory
WTERRACOTT	0653	AC	879	24	Residential	06-02-2021	226	52.0	Poor
WUPLANDDR	0069	AC	708	26	Residential	06-02-2021	239	75.0	Satisfactory
WWOODSTOCK	0104	AC	5,808	30	Collector	06-02-2021	166	78.0	Satisfactory
WYNDMUIRDR	0273	AC	1,455	28	Residential	06-02-2021	178	97.0	Good
WYNDMUIRDR	0661	AC	342	24	Residential	06-02-2021	200	95.0	Good
YELLOWSTON	0335	AC	462	26	Residential	06-02-2021	284	46.0	Poor
YORKSHIREL	0492	AC	1,522	26	Collector	06-02-2021	116	94.0	Good

## Details of the 2022 Localized Distress Maintenance Plan

BranchID	SectionID	Description	Severity	Distress Qty	Distress Unit	Percent Distress	Work Description	Surface Type	Section Length (Ft)	Section Width (Ft)	Work Qty	Work Unit	Unit Cost	Work Cost
ABBEYDR	0364	RUTTING	High	9	SqFt	0.0	Patching - AC Shallow	AC	1326	24	9	SqFt	\$2.78	\$25.19
ABERDEENDR	0255	L & T CR	Medium	501	Ft	0.9	Crack Sealing - AC	AC	2167	26	501	Ft	\$0.60	\$300.88
ABERDEENDR	0255	RUTTING	Medium	49	SqFt	0.1	Patching - AC Shallow	AC	2167	26	50	SqFt	\$2.78	\$136.75
ABERDEENDR	0255	POTHOLE	Low	3	Count	0.0	Patching - AC Deep	AC	2167	26	9	SqFt	\$5.56	\$49.25
ACHILLESCT	0463	L & T CR	Medium	129	Ft	1.9	Crack Sealing - AC	AC	242	28	130	Ft	\$0.60	\$77.69
ACHILLESCT	0463	L & T CR	High	5	Ft	0.1	Patching - AC Shallow	AC	242	28	16	SqFt	\$2.78	\$44.30
ALEXANDRAB	0038	ALLIGATOR CR	Medium	51	SqFt	0.0	Patching - AC Deep	AC	5471	34	84	SqFt	\$5.56	\$465.80
ALEXANDRAB	0038	L & T CR	Medium	3509	Ft	1.9	Crack Sealing - AC	AC	5471	34	3509	Ft	\$0.60	\$2,105.30
ALEXANDRAB	0038	RUTTING	Medium	50	SqFt	0.0	Patching - AC Shallow	AC	5471	34	51	SqFt	\$2.78	\$140.27
ALEXANDRAB	0038	L & T CR	High	5	Ft	0.0	Patching - AC Shallow	AC	5471	34	16	SqFt	\$2.78	\$44.54
ALEXANDRAB	0058	L & T CR	Medium	58	Ft	0.1	Crack Sealing - AC	AC	1255	34	58	Ft	\$0.60	\$34.73
ALEXANDRAB	0093	RUTTING	High	20	SqFt	0.0	Patching - AC Shallow	AC	2912	26	19	SqFt	\$2.78	\$54.46
AMBERWOODD	0035	L & T CR	High	0	Ft	0.0	Patching - AC Shallow	AC	3041	34	1	SqFt	\$2.78	\$2.11
AMBERWOODD	0035	L & T CR	Medium	14	Ft	0.0	Crack Sealing - AC	AC	3041	34	14	Ft	\$0.60	\$8.37
AMBERWOODD	0138	L & T CR	High	5	Ft	0.0	Patching - AC Shallow	AC	1535	34	15	SqFt	\$2.78	\$42.80
AMBERWOODD	0138	L & T CR	Medium	26	Ft	0.1	Crack Sealing - AC	AC	1535	34	26	Ft	\$0.60	\$15.61
ANDOVERLN	0113	RUTTING	Medium	186	SqFt	0.4	Patching - AC Shallow	AC	2053	24	186	SqFt	\$2.78	\$517.82
ANDOVERLN	0113	L & T CR	Medium	1159	Ft	2.4	Crack Sealing - AC	AC	2053	24	1159	Ft	\$0.60	\$695.29
ANDOVERLN	0113	L & T CR	High	0	Ft	0.0	Patching - AC Shallow	AC	2053	24	1	SqFt	\$2.78	\$3.00
ANDOVERLN	0113	ALLIGATOR CR	Medium	149	SqFt	0.3	Patching - AC Deep	AC	2053	24	202	SqFt	\$5.56	\$1,123.43
ANGELALN	0181	RUTTING	High	44	SqFt	0.3	Patching - AC Shallow	AC	498	26	44	SqFt	\$2.78	\$121.22
ANGELALN	0775	RUTTING	High	18	SqFt	0.5	Patching - AC Shallow	AC	151	26	18	SqFt	\$2.78	\$50.44
ARROWHEADL	0282	L & T CR	High	3	Ft	0.0	Patching - AC Shallow	AC	1008	24	9	SqFt	\$2.78	\$23.99
ASHFORDLN	0199	L & T CR	Medium	22	Ft	0.0	Crack Sealing - AC	AC	2106	26	22	Ft	\$0.60	\$13.37
ASHST	0148	ALLIGATOR CR	Medium	197	SqFt	0.6	Patching - AC Deep	AC	1313	24	258	SqFt	\$5.56	\$1,434.59
ASHST	0148	L & T CR	High	14	Ft	0.0	Patching - AC Shallow	AC	1313	24	45	SqFt	\$2.78	\$125.70
ASHST	0148	L & T CR	Medium	323	Ft	1.0	Crack Sealing - AC	AC	1313	24	323	Ft	\$0.60	\$193.72
ASHST	0148	POTHOLE	Low	3	Count	0.0	Patching - AC Deep	AC	1313	24	9	SqFt	\$5.56	\$45.61
ASHTONLN	0064	L & T CR	High	0	Ft	0.0	Patching - AC Shallow	AC	1307	36	1	SqFt	\$2.78	\$1.70
ASHTONLN	0064	L & T CR	Medium	893	Ft	1.9	Crack Sealing - AC	AC	1307	36	893	Ft	\$0.60	\$535.61
ASHTONLN	0064	RUTTING	High	37	SqFt	0.1	Patching - AC Deep	AC	1307	36	38	SqFt	\$5.56	\$207.46
ASHTONLN	0734	L & T CR	Medium	2	Ft	0.2	Crack Sealing - AC	AC	24	36	2	Ft	\$0.60	\$1.03
AUGUSTADR	0301	L & T CR	Medium	182	Ft	1.2	Crack Sealing - AC	AC	612	24	182	Ft	\$0.60	\$109.09
AUGUSTADR	0301	ALLIGATOR CR	Medium	52	SqFt	0.4	Patching - AC Deep	AC	612	24	85	SqFt	\$5.56	\$471.17
AUGUSTADR	0301	POTHOLE	Low	3	Count	0.0	Patching - AC Deep	AC	612	24	9	SqFt	\$5.56	\$48.63
AUGUSTADR	0301	RUTTING	Medium	57	SqFt	0.4	Patching - AC Shallow	AC	612	24	57	SqFt	\$2.78	\$158.13

## Details of the 2022 Localized Distress Maintenance Plan

BranchID	SectionID	Description	Severity	Distress Qty	Distress Unit	Percent Distress	Work Description	Surface Type	Section Length (Ft)	Section Width (Ft)	Work Qty	Work Unit	Unit Cost	Work Cost
AUGUSTADR	0301	L & T CR	High	51	Ft	0.4	Patching - AC Shallow	AC	612	24	167	SqFt	\$2.78	\$463.77
AUTUMNCRES	0130	RUTTING	High	27	SqFt	0.1	Patching - AC Deep	AC	2261	24	27	SqFt	\$5.56	\$150.83
AUTUMNCRES	0130	RUTTING	Medium	109	SqFt	0.2	Patching - AC Shallow	AC	2261	24	109	SqFt	\$2.78	\$301.66
AUTUMNCRES	0545	RUTTING	Medium	9	SqFt	0.0	Patching - AC Shallow	AC	1288	24	9	SqFt	\$2.78	\$25.24
AUTUMNDR	0003	RUTTING	High	39	SqFt	0.1	Patching - AC Shallow	AC	2402	26	39	SqFt	\$2.78	\$107.97
BARBERRYDR	0533	L & T CR	Medium	20	Ft	0.2	Crack Sealing - AC	AC	618	22	20	Ft	\$0.60	\$11.97
BARBERRYDR	0533	ALLIGATOR CR	Medium	13	SqFt	0.1	Patching - AC Deep	AC	618	22	32	SqFt	\$5.56	\$179.41
BARBERRYDR	0533	RUTTING	Medium	26	SqFt	0.2	Patching - AC Shallow	AC	618	22	26	SqFt	\$2.78	\$72.31
BARBERRYDR	0533	POTHOLE	Low	3	Count	0.0	Patching - AC Deep	AC	618	22	8	SqFt	\$5.56	\$43.43
BARBERRYDR	0559	RUTTING	Medium	8	SqFt	0.1	Patching - AC Shallow	AC	699	22	9	SqFt	\$2.78	\$23.27
BARBERRYDR	0559	L & T CR	Medium	1	Ft	0.0	Crack Sealing - AC	AC	699	22	1	Ft	\$0.60	\$0.77
BARDRD	0644	POTHOLE	Low	9	Count	0.0	Patching - AC Deep	AC	1289	26	27	SqFt	\$5.56	\$147.89
BARDRD	0644	RUTTING	Medium	20	SqFt	0.1	Patching - AC Shallow	AC	1289	26	19	SqFt	\$2.78	\$54.72
BARDRD	0644	L & T CR	High	122	Ft	0.4	Patching - AC Shallow	AC	1289	26	400	SqFt	\$2.78	\$1,113.52
BARDRD	0644	L & T CR	Medium	198	Ft	0.6	Crack Sealing - AC	AC	1289	26	198	Ft	\$0.60	\$118.98
BARDRD	0644	RUTTING	High	39	SqFt	0.1	Patching - AC Deep	AC	1289	26	40	SqFt	\$5.56	\$218.87
BARLINARD	0146	L & T CR	High	11	Ft	0.0	Patching - AC Shallow	AC	2979	38	37	SqFt	\$2.78	\$101.17
BARLINARD	0146	RUTTING	Medium	28	SqFt	0.0	Patching - AC Shallow	AC	2979	38	28	SqFt	\$2.78	\$78.68
BARLINARD	0146	L & T CR	Medium	513	Ft	0.5	Crack Sealing - AC	AC	2979	38	513	Ft	\$0.60	\$307.92
BARLINARD	0146	POTHOLE	Low	4	Count	0.0	Patching - AC Deep	AC	2979	38	13	SqFt	\$5.56	\$70.89
BARLINARD	0187	L & T CR	Medium	1213	Ft	0.8	Crack Sealing - AC	AC	4080	38	1213	Ft	\$0.60	\$727.52
BARLINARD	0187	RUTTING	Medium	14	SqFt	0.0	Patching - AC Shallow	AC	4080	38	14	SqFt	\$2.78	\$39.28
BARLINARD	0187	L & T CR	High	13	Ft	0.0	Patching - AC Shallow	AC	4080	38	43	SqFt	\$2.78	\$119.98
BARTONLN	0531	RUTTING	Medium	32	SqFt	0.3	Patching - AC Shallow	AC	390	26	31	SqFt	\$2.78	\$87.75
BARTONLN	0531	L & T CR	Medium	2	Ft	0.0	Crack Sealing - AC	AC	390	26	2	Ft	\$0.60	\$1.19
BAYBERRYDR	0421	L & T CR	High	5	Ft	0.1	Patching - AC Shallow	AC	351	22	17	SqFt	\$2.78	\$47.17
BAYBERRYDR	0421	ALLIGATOR CR	Medium	36	SqFt	0.5	Patching - AC Deep	AC	351	22	65	SqFt	\$5.56	\$359.36
BAYBERRYDR	0421	L & T CR	Medium	25	Ft	0.3	Crack Sealing - AC	AC	351	22	25	Ft	\$0.60	\$14.84
BAYBERRYDR	0421	RUTTING	Medium	9	SqFt	0.1	Patching - AC Shallow	AC	351	22	9	SqFt	\$2.78	\$24.81
BEARDSLEYS	0589	L & T CR	High	64	Ft	0.4	Patching - AC Shallow	AC	681	24	209	SqFt	\$2.78	\$581.62
BEARDSLEYS	0589	RUTTING	Medium	18	SqFt	0.1	Patching - AC Shallow	AC	681	24	17	SqFt	\$2.78	\$48.86
BEARDSLEYS	0589	L & T CR	Medium	204	Ft	1.3	Crack Sealing - AC	AC	681	24	204	Ft	\$0.60	\$122.40
BECKERCT	0085	L & T CR	High	99	Ft	1.0	Patching - AC Shallow	AC	390	26	324	SqFt	\$2.78	\$901.50
BECKERCT	0085	L & T CR	Medium	43	Ft	0.4	Crack Sealing - AC	AC	390	26	43	Ft	\$0.60	\$25.59
BEDFORDDR	0156	L & T CR	Medium	33	Ft	0.1	Crack Sealing - AC	AC	1680	26	33	Ft	\$0.60	\$20.02
BEECHCRAFT	0392	L & T CR	Medium	15	Ft	0.1	Crack Sealing - AC	AC	539	36	15	Ft	\$0.60	\$8.94

## Details of the 2022 Localized Distress Maintenance Plan

BranchID	SectionID	Description	Severity	Distress Qty	Distress Unit	Percent Distress	Work Description	Surface Type	Section Length (Ft)	Section Width (Ft)	Work Qty	Work Unit	Unit Cost	Work Cost
BEECHCRAFT	0392	L & T CR	High	26	Ft	0.1	Patching - AC Shallow	AC	539	36	86	SqFt	\$2.78	\$239.46
BENNINGTON	0349	L & T CR	Medium	957	Ft	1.9	Crack Sealing - AC	AC	2148	24	957	Ft	\$0.60	\$574.31
BENNINGTON	0349	RUTTING	Medium	36	SqFt	0.1	Patching - AC Shallow	AC	2148	24	36	SqFt	\$2.78	\$100.05
BENNINGTON	0514	L & T CR	Medium	4	Ft	0.0	Crack Sealing - AC	AC	1321	24	4	Ft	\$0.60	\$2.38
BERKSHIRE	0293	RUTTING	High	143	SqFt	0.1	Patching - AC Shallow	AC	3031	38	143	SqFt	\$2.78	\$397.74
BIRCHST	0678	L & T CR	Medium	313	Ft	2.5	Crack Sealing - AC	AC	518	24	313	Ft	\$0.60	\$187.71
BIRCHST	0685	L & T CR	Medium	758	Ft	5.4	Crack Sealing - AC	AC	590	24	758	Ft	\$0.60	\$454.86
BIRMINGHAM	0137	POTHOLE	Low	3	Count	0.0	Patching - AC Deep	AC	2530	24	9	SqFt	\$5.56	\$45.38
BIRMINGHAM	0137	RUTTING	Medium	18	SqFt	0.0	Patching - AC Shallow	AC	2530	24	18	SqFt	\$2.78	\$50.38
BIRMINGHAM	0137	ALLIGATOR CR	Medium	11	SqFt	0.0	Patching - AC Deep	AC	2530	24	28	SqFt	\$5.56	\$156.33
BIRMINGHAM	0137	L & T CR	Medium	549	Ft	0.9	Crack Sealing - AC	AC	2530	24	549	Ft	\$0.60	\$329.52
BIRMINGHAM	0400	L & T CR	Medium	414	Ft	3.9	Crack Sealing - AC	AC	446	24	414	Ft	\$0.60	\$248.33
BIRMINGHAM	0400	L & T CR	High	1	Ft	0.0	Patching - AC Shallow	AC	446	24	3	SqFt	\$2.78	\$10.24
BLACKTHORN	0207	RUTTING	High	10	SqFt	0.0	Patching - AC Deep	AC	1872	26	10	SqFt	\$5.56	\$54.40
BLACKTHORN	0207	L & T CR	Medium	26	Ft	0.1	Crack Sealing - AC	AC	1872	26	26	Ft	\$0.60	\$15.62
BLACKTHORN	0207	RUTTING	Medium	10	SqFt	0.0	Patching - AC Shallow	AC	1872	26	10	SqFt	\$2.78	\$27.20
BLACKTHORN	0207	L & T CR	High	7	Ft	0.0	Patching - AC Shallow	AC	1872	26	22	SqFt	\$2.78	\$59.76
BLACKTHORN	0384	L & T CR	Medium	333	Ft	1.4	Crack Sealing - AC	AC	969	24	333	Ft	\$0.60	\$199.53
BLACKTHORN	0384	L & T CR	High	5	Ft	0.0	Patching - AC Shallow	AC	969	24	15	SqFt	\$2.78	\$41.24
BLACKTHORN	0384	ALLIGATOR CR	Medium	12	SqFt	0.1	Patching - AC Deep	AC	969	24	29	SqFt	\$5.56	\$163.69
BLACKTHORN	0384	ALLIGATOR CR	High	12	SqFt	0.1	Patching - AC Deep	AC	969	24	30	SqFt	\$5.56	\$165.18
BLUEHEROND	0610	L & T CR	High	6	Ft	0.0	Patching - AC Shallow	AC	1040	26	18	SqFt	\$2.78	\$50.42
BLUEHEROND	0610	L & T CR	Medium	8	Ft	0.0	Crack Sealing - AC	AC	1040	26	8	Ft	\$0.60	\$4.52
BLUEHEROND	0610	RUTTING	Medium	10	SqFt	0.0	Patching - AC Shallow	AC	1040	26	10	SqFt	\$2.78	\$27.81
BLUEHEROND	0670	L & T CR	Medium	2	Ft	0.0	Crack Sealing - AC	AC	188	26	2	Ft	\$0.60	\$1.27
BLUEHEROND	0670	ALLIGATOR CR	Medium	23	SqFt	0.5	Patching - AC Deep	AC	188	26	46	SqFt	\$5.56	\$260.19
BLUEMOUNDD	0369	L & T CR	Medium	41	Ft	0.2	Crack Sealing - AC	AC	722	26	41	Ft	\$0.60	\$24.85
BLUEMOUNDD	0369	L & T CR	High	14	Ft	0.1	Patching - AC Shallow	AC	722	26	45	SqFt	\$2.78	\$126.30
BONESETDR	0201	RUTTING	Medium	10	SqFt	0.0	Patching - AC Shallow	AC	905	26	11	SqFt	\$2.78	\$28.81
BONESETDR	0201	L & T CR	High	57	Ft	0.2	Patching - AC Shallow	AC	905	26	188	SqFt	\$2.78	\$523.50
BONESETDR	0201	L & T CR	Medium	30	Ft	0.1	Crack Sealing - AC	AC	905	26	30	Ft	\$0.60	\$18.15
BOXWOODDR	0292	POTHOLE	Low	16	Count	0.0	Patching - AC Deep	AC	2742	24	48	SqFt	\$5.56	\$269.08
BOXWOODDR	0292	ALLIGATOR CR	High	39	SqFt	0.1	Patching - AC Deep	AC	2742	24	68	SqFt	\$5.56	\$379.72
BOXWOODDR	0292	RUTTING	Medium	188	SqFt	0.3	Patching - AC Shallow	AC	2742	24	188	SqFt	\$2.78	\$522.92
BOXWOODDR	0292	L & T CR	High	76	Ft	0.1	Patching - AC Shallow	AC	2742	24	250	SqFt	\$2.78	\$695.22
BOXWOODDR	0292	RUTTING	High	9	SqFt	0.0	Patching - AC Deep	AC	2742	24	9	SqFt	\$5.56	\$49.78

## Details of the 2022 Localized Distress Maintenance Plan

BranchID	SectionID	Description	Severity	Distress Qty	Distress Unit	Percent Distress	Work Description	Surface Type	Section Length (Ft)	Section Width (Ft)	Work Qty	Work Unit	Unit Cost	Work Cost
BOXWOODDR	0292	ALLIGATOR CR	Medium	869	SqFt	1.3	Patching - AC Deep	AC	2742	24	992	SqFt	\$5.56	\$5,515.23
BOXWOODDR	0292	L & T CR	Medium	908	Ft	1.4	Crack Sealing - AC	AC	2742	24	908	Ft	\$0.60	\$544.75
BOXWOODDR	0517	POTHOLE	Low	3	Count	0.0	Patching - AC Deep	AC	1968	24	9	SqFt	\$5.56	\$45.59
BRADFORDLN	0266	L & T CR	Medium	7	Ft	0.0	Crack Sealing - AC	AC	1266	32	7	Ft	\$0.60	\$4.03
BRADFORDLN	0266	L & T CR	High	8	Ft	0.0	Patching - AC Shallow	AC	1266	32	27	SqFt	\$2.78	\$73.55
BRIARWOODC	0480	L & T CR	Medium	70	Ft	0.3	Crack Sealing - AC	AC	1240	22	71	Ft	\$0.60	\$42.27
BRIARWOODC	0480	RUTTING	Medium	17	SqFt	0.1	Patching - AC Shallow	AC	1240	22	17	SqFt	\$2.78	\$46.77
BRIARWOODR	0010	RUTTING	High	10	SqFt	0.0	Patching - AC Shallow	AC	4088	28	11	SqFt	\$2.78	\$29.00
BRIARWOODR	0657	RUTTING	Medium	11	SqFt	0.0	Patching - AC Shallow	AC	872	28	11	SqFt	\$2.78	\$29.90
BRIARWOODR	0657	L & T CR	Medium	279	Ft	1.1	Crack Sealing - AC	AC	872	28	279	Ft	\$0.60	\$167.56
BRIDGEDEALE	0411	L & T CR	Medium	240	Ft	4.3	Crack Sealing - AC	AC	214	26	240	Ft	\$0.60	\$144.20
BRIDGEDEALE	0431	RUTTING	High	49	SqFt	0.1	Patching - AC Shallow	AC	1711	26	50	SqFt	\$2.78	\$136.30
BRIGHAMLN	0604	RUTTING	Medium	19	SqFt	0.1	Patching - AC Shallow	AC	932	24	18	SqFt	\$2.78	\$52.27
BRIGHAMLN	0604	L & T CR	Medium	98	Ft	0.4	Crack Sealing - AC	AC	932	24	98	Ft	\$0.60	\$58.68
BRIGHAMLN	0604	ALLIGATOR CR	Medium	31	SqFt	0.1	Patching - AC Deep	AC	932	24	58	SqFt	\$5.56	\$320.68
BRINKST	0417	RUTTING	Medium	68	SqFt	0.2	Patching - AC Shallow	AC	1147	40	68	SqFt	\$2.78	\$188.73
BRINKST	0417	L & T CR	Medium	1976	Ft	4.3	Crack Sealing - AC	AC	1147	40	1976	Ft	\$0.60	\$1,185.41
BRINKST	0417	ALLIGATOR CR	Medium	202	SqFt	0.4	Patching - AC Deep	AC	1147	40	264	SqFt	\$5.56	\$1,463.31
BRINKST	0417	ALLIGATOR CR	High	5	SqFt	0.0	Patching - AC Deep	AC	1147	40	19	SqFt	\$5.56	\$105.35
BRINKST	0417	L & T CR	High	38	Ft	0.1	Patching - AC Shallow	AC	1147	40	124	SqFt	\$2.78	\$345.39
BRINKST	0417	POTHOLE	Low	5	Count	0.0	Patching - AC Deep	AC	1147	40	15	SqFt	\$5.56	\$85.01
BRINKST	0647	RUTTING	High	63	SqFt	0.3	Patching - AC Shallow	AC	557	40	64	SqFt	\$2.78	\$176.24
BRISTOLDL	0122	L & T CR	Medium	222	Ft	3.5	Crack Sealing - AC	AC	289	22	222	Ft	\$0.60	\$133.46
BRISTOLDL	0122	ALLIGATOR CR	Medium	12	SqFt	0.2	Patching - AC Deep	AC	289	22	29	SqFt	\$5.56	\$163.69
BROADWAYAV	0228	RUTTING	Medium	9	SqFt	0.1	Patching - AC Shallow	AC	648	22	9	SqFt	\$2.78	\$23.66
BROADWAYAV	0450	L & T CR	Medium	38	Ft	0.1	Crack Sealing - AC	AC	1176	26	38	Ft	\$0.60	\$22.95
BROADWAYAV	0450	POTHOLE	Low	9	Count	0.0	Patching - AC Deep	AC	1176	26	28	SqFt	\$5.56	\$154.51
BROADWAYAV	0652	RUTTING	Medium	31	SqFt	0.1	Patching - AC Shallow	AC	2085	28	31	SqFt	\$2.78	\$85.81
BROADWAYAV	0652	POTHOLE	Low	13	Count	0.0	Patching - AC Deep	AC	2085	28	38	SqFt	\$5.56	\$211.12
BROADWAYAV	0652	L & T CR	High	77	Ft	0.1	Patching - AC Shallow	AC	2085	28	253	SqFt	\$2.78	\$703.19
BROADWAYAV	0652	L & T CR	Medium	245	Ft	0.4	Crack Sealing - AC	AC	2085	28	245	Ft	\$0.60	\$147.03
BROADWAYAV	0652	RUTTING	High	5	SqFt	0.0	Patching - AC Deep	AC	2085	28	5	SqFt	\$5.56	\$29.29
BROMPTONCT	0312	L & T CR	Medium	35	Ft	0.4	Crack Sealing - AC	AC	372	26	35	Ft	\$0.60	\$21.13
BROMPTONCT	0312	RUTTING	Medium	13	SqFt	0.1	Patching - AC Shallow	AC	372	26	13	SqFt	\$2.78	\$35.55
BROMPTONLN	0124	POTHOLE	Low	4	Count	0.0	Patching - AC Deep	AC	808	34	12	SqFt	\$5.56	\$65.27
BROMPTONLN	0124	L & T CR	High	19	Ft	0.1	Patching - AC Shallow	AC	808	34	61	SqFt	\$2.78	\$171.68

## Details of the 2022 Localized Distress Maintenance Plan

BranchID	SectionID	Description	Severity	Distress Qty	Distress Unit	Percent Distress	Work Description	Surface Type	Section Length (Ft)	Section Width (Ft)	Work Qty	Work Unit	Unit Cost	Work Cost
BROMPTONLN	0124	L & T CR	Medium	685	Ft	2.5	Crack Sealing - AC	AC	808	34	685	Ft	\$0.60	\$410.82
BROMPTONLN	0274	ALLIGATOR CR	Medium	23	SqFt	0.0	Patching - AC Deep	AC	1546	34	47	SqFt	\$5.56	\$261.26
BROMPTONLN	0274	RUTTING	Medium	13	SqFt	0.0	Patching - AC Shallow	AC	1546	34	13	SqFt	\$2.78	\$36.05
BROMPTONLN	0274	L & T CR	Medium	1001	Ft	1.9	Crack Sealing - AC	AC	1546	34	1001	Ft	\$0.60	\$600.38
BROMPTONLN	0760	L & T CR	Medium	22	Ft	0.3	Crack Sealing - AC	AC	217	34	22	Ft	\$0.60	\$13.32
BROOKDR	0167	L & T CR	High	7	Ft	0.0	Patching - AC Shallow	AC	673	26	22	SqFt	\$2.78	\$60.59
BROOKDR	0167	L & T CR	Medium	5	Ft	0.0	Crack Sealing - AC	AC	673	26	5	Ft	\$0.60	\$2.80
BRYNMAWRLN	0300	L & T CR	Medium	2448	Ft	3.2	Crack Sealing - AC	AC	2412	32	2448	Ft	\$0.60	\$1,468.74
BRYNMAWRLN	0300	ALLIGATOR CR	Medium	228	SqFt	0.3	Patching - AC Deep	AC	2412	32	293	SqFt	\$5.56	\$1,625.47
BRYNMAWRLN	0300	L & T CR	High	35	Ft	0.1	Patching - AC Shallow	AC	2412	32	114	SqFt	\$2.78	\$317.80
BUCKINGHAM	0218	RUTTING	High	20	SqFt	0.0	Patching - AC Shallow	AC	1820	26	19	SqFt	\$2.78	\$54.70
BUCKINGHAM	0570	L & T CR	High	1	Ft	0.0	Patching - AC Shallow	AC	217	26	2	SqFt	\$2.78	\$7.37
BUCKINGHAM	0570	L & T CR	Medium	73	Ft	1.3	Crack Sealing - AC	AC	217	26	73	Ft	\$0.60	\$43.51
BURDENTDR	0310	RUTTING	High	22	SqFt	0.3	Patching - AC Shallow	AC	365	24	22	SqFt	\$2.78	\$60.00
BURNINGBUS	0346	L & T CR	High	4	Ft	0.0	Patching - AC Shallow	AC	2664	24	13	SqFt	\$2.78	\$37.20
BURNINGBUS	0346	L & T CR	Medium	6	Ft	0.0	Crack Sealing - AC	AC	2664	24	6	Ft	\$0.60	\$3.45
BURROAKDR	0099	L & T CR	Medium	13	Ft	0.1	Crack Sealing - AC	AC	920	22	13	Ft	\$0.60	\$8.01
BURROAKDR	0099	L & T CR	High	1	Ft	0.0	Patching - AC Shallow	AC	920	22	3	SqFt	\$2.78	\$8.58
BUTLERDR	0260	L & T CR	Medium	80	Ft	0.2	Crack Sealing - AC	AC	1513	26	80	Ft	\$0.60	\$47.87
BUTLERDR	0260	L & T CR	High	14	Ft	0.0	Patching - AC Shallow	AC	1513	26	45	SqFt	\$2.78	\$126.43
BUTTERNUTD	0641	ALLIGATOR CR	Medium	60	SqFt	0.2	Patching - AC Deep	AC	1491	22	95	SqFt	\$5.56	\$528.81
BUTTERNUTD	0641	L & T CR	Medium	117	Ft	0.4	Crack Sealing - AC	AC	1491	22	117	Ft	\$0.60	\$70.45
BUTTERNUTD	0641	L & T CR	High	4	Ft	0.0	Patching - AC Shallow	AC	1491	22	14	SqFt	\$2.78	\$38.10
CAMBRIDGEL	0552	L & T CR	High	2	Ft	0.0	Patching - AC Shallow	AC	1486	26	8	SqFt	\$2.78	\$21.48
CAMBRIDGEL	0552	L & T CR	Medium	23	Ft	0.1	Crack Sealing - AC	AC	1486	26	23	Ft	\$0.60	\$13.54
CAMELOTDR	0258	RUTTING	Medium	27	SqFt	0.0	Patching - AC Shallow	AC	2600	24	27	SqFt	\$2.78	\$75.21
CAMELOTDR	0258	L & T CR	Medium	29	Ft	0.1	Crack Sealing - AC	AC	2600	24	29	Ft	\$0.60	\$17.22
CANDLEWOOD	0177	RUTTING	Medium	10	SqFt	0.0	Patching - AC Shallow	AC	1743	26	10	SqFt	\$2.78	\$27.42
CANDLEWOOD	0177	L & T CR	Medium	129	Ft	0.3	Crack Sealing - AC	AC	1743	26	129	Ft	\$0.60	\$77.10
CANDLEWOOD	0177	ALLIGATOR CR	Medium	0	SqFt	0.0	Patching - AC Deep	AC	1743	26	5	SqFt	\$5.56	\$28.02
CANTERBURY	0402	L & T CR	Medium	66	Ft	0.1	Crack Sealing - AC	AC	1981	26	66	Ft	\$0.60	\$39.80
CANTERBURY	0402	L & T CR	High	6	Ft	0.0	Patching - AC Shallow	AC	1981	26	20	SqFt	\$2.78	\$55.74
CANTERBURY	0402	RUTTING	Medium	9	SqFt	0.0	Patching - AC Shallow	AC	1981	26	9	SqFt	\$2.78	\$23.70
CARDIFFDR	0182	RUTTING	Medium	9	SqFt	0.0	Patching - AC Shallow	AC	1202	26	9	SqFt	\$2.78	\$23.80
CARDIFFDR	0182	POTHOLE	Low	3	Count	0.0	Patching - AC Deep	AC	1202	26	9	SqFt	\$5.56	\$49.92
CARDIFFDR	0182	L & T CR	Medium	66	Ft	0.2	Crack Sealing - AC	AC	1202	26	66	Ft	\$0.60	\$39.74

## Details of the 2022 Localized Distress Maintenance Plan

BranchID	SectionID	Description	Severity	Distress Qty	Distress Unit	Percent Distress	Work Description	Surface Type	Section Length (Ft)	Section Width (Ft)	Work Qty	Work Unit	Unit Cost	Work Cost
CASCADEDR	0551	L & T CR	Medium	47	Ft	0.6	Crack Sealing - AC	AC	337	24	47	Ft	\$0.60	\$28.32
CEDARCREST	0170	L & T CR	High	13	Ft	0.0	Patching - AC Shallow	AC	2065	26	41	SqFt	\$2.78	\$114.19
CEDARCREST	0170	L & T CR	Medium	925	Ft	1.7	Crack Sealing - AC	AC	2065	26	925	Ft	\$0.60	\$555.06
CEDARCREST	0170	ALLIGATOR CR	Medium	142	SqFt	0.3	Patching - AC Deep	AC	2065	26	194	SqFt	\$5.56	\$1,077.07
CEDARCREST	0170	RUTTING	Medium	18	SqFt	0.0	Patching - AC Shallow	AC	2065	26	18	SqFt	\$2.78	\$50.81
CEDARDR	0483	L & T CR	Medium	54	Ft	0.7	Crack Sealing - AC	AC	358	22	54	Ft	\$0.60	\$32.66
CENTERST	0076	RUTTING	High	165	SqFt	0.7	Patching - AC Shallow	AC	877	26	166	SqFt	\$2.78	\$459.99
CENTERST	0196	RUTTING	High	17	SqFt	0.1	Patching - AC Shallow	AC	1203	22	17	SqFt	\$2.78	\$46.95
CENTRALPAR	0404	L & T CR	High	23	Ft	0.0	Patching - AC Shallow	AC	1431	36	74	SqFt	\$2.78	\$207.78
CENTRALPAR	0404	RUTTING	Medium	91	SqFt	0.2	Patching - AC Shallow	AC	1431	36	91	SqFt	\$2.78	\$253.84
CENTRALPAR	0404	ALLIGATOR CR	Medium	31	SqFt	0.1	Patching - AC Deep	AC	1431	36	57	SqFt	\$5.56	\$319.46
CENTRALPAR	0404	L & T CR	Medium	408	Ft	0.8	Crack Sealing - AC	AC	1431	36	408	Ft	\$0.60	\$244.94
CENTRALPAR	0769	L & T CR	High	6	Ft	0.1	Patching - AC Shallow	AC	299	36	20	SqFt	\$2.78	\$55.60
CENTRALPAR	0769	L & T CR	Medium	738	Ft	6.9	Crack Sealing - AC	AC	299	36	738	Ft	\$0.60	\$442.60
CERESIADR	0528	L & T CR	Medium	802	Ft	6.3	Crack Sealing - AC	AC	531	24	802	Ft	\$0.60	\$481.19
CHARDONNAY	0594	RUTTING	Medium	12	SqFt	0.0	Patching - AC Shallow	AC	928	30	12	SqFt	\$2.78	\$32.56
CHARDONNAY	0594	POTHOLE	Low	7	Count	0.0	Patching - AC Deep	AC	928	30	22	SqFt	\$5.56	\$117.33
CHARDONNAY	0594	L & T CR	Medium	200	Ft	0.7	Crack Sealing - AC	AC	928	30	200	Ft	\$0.60	\$119.98
CHARDONNAY	0594	L & T CR	High	9	Ft	0.0	Patching - AC Shallow	AC	928	30	29	SqFt	\$2.78	\$82.12
CHARLOTTEA	0290	L & T CR	Medium	1653	Ft	2.9	Crack Sealing - AC	AC	2601	22	1653	Ft	\$0.60	\$991.71
CHARLOTTEA	0290	RUTTING	Medium	66	SqFt	0.1	Patching - AC Shallow	AC	2601	22	66	SqFt	\$2.78	\$182.11
CHARLOTTEA	0290	RUTTING	High	8	SqFt	0.0	Patching - AC Deep	AC	2601	22	9	SqFt	\$5.56	\$46.35
CHARLOTTEA	0290	POTHOLE	Low	3	Count	0.0	Patching - AC Deep	AC	2601	22	8	SqFt	\$5.56	\$41.75
CHARLOTTEA	0290	ALLIGATOR CR	Medium	82	SqFt	0.1	Patching - AC Deep	AC	2601	22	123	SqFt	\$5.56	\$683.21
CHARLOTTEA	0290	L & T CR	High	152	Ft	0.3	Patching - AC Shallow	AC	2601	22	498	SqFt	\$2.78	\$1,384.21
CIRCLED R	0614	RUTTING	High	84	SqFt	0.7	Patching - AC Shallow	AC	541	22	84	SqFt	\$2.78	\$233.07
CLOVERDR	0011	RUTTING	High	49	SqFt	0.4	Patching - AC Shallow	AC	586	22	50	SqFt	\$2.78	\$137.17
CLOVERDR	0151	RUTTING	Medium	72	SqFt	0.4	Patching - AC Shallow	AC	752	22	72	SqFt	\$2.78	\$199.31
CLOVERDR	0151	L & T CR	Medium	139	Ft	0.8	Crack Sealing - AC	AC	752	22	138	Ft	\$0.60	\$83.14
CLOVERDR	0151	POTHOLE	Low	5	Count	0.0	Patching - AC Deep	AC	752	22	15	SqFt	\$5.56	\$85.20
CLOVERDR	0151	ALLIGATOR CR	Medium	31	SqFt	0.2	Patching - AC Deep	AC	752	22	58	SqFt	\$5.56	\$321.95
CLOVERDR	0151	L & T CR	High	25	Ft	0.2	Patching - AC Shallow	AC	752	22	81	SqFt	\$2.78	\$225.03
CLOVERDR	0658	RUTTING	Medium	8	SqFt	0.1	Patching - AC Shallow	AC	699	22	9	SqFt	\$2.78	\$23.27
CLOVERDR	0658	ALLIGATOR CR	Medium	18	SqFt	0.1	Patching - AC Deep	AC	699	22	40	SqFt	\$5.56	\$218.66
CLOVERDR	0658	L & T CR	Medium	13	Ft	0.1	Crack Sealing - AC	AC	699	22	13	Ft	\$0.60	\$8.05
CLOWCT	0522	RUTTING	High	12	SqFt	0.3	Patching - AC Deep	AC	168	24	13	SqFt	\$5.56	\$69.21

## Details of the 2022 Localized Distress Maintenance Plan

BranchID	SectionID	Description	Severity	Distress Qty	Distress Unit	Percent Distress	Work Description	Surface Type	Section Length (Ft)	Section Width (Ft)	Work Qty	Work Unit	Unit Cost	Work Cost
CLOWCT	0522	RUTTING	Medium	50	SqFt	1.2	Patching - AC Shallow	AC	168	24	50	SqFt	\$2.78	\$138.53
CLOWCT	0522	L & T CR	Medium	3	Ft	0.1	Crack Sealing - AC	AC	168	24	3	Ft	\$0.60	\$1.93
COGCIR	0068	RUTTING	High	55	SqFt	0.1	Patching - AC Shallow	AC	3218	24	55	SqFt	\$2.78	\$153.77
COLLEGEST	0198	RUTTING	High	16	SqFt	0.0	Patching - AC Shallow	AC	2293	22	16	SqFt	\$2.78	\$45.92
COLLEGEST	0419	L & T CR	High	2	Ft	0.0	Patching - AC Shallow	AC	391	22	6	SqFt	\$2.78	\$17.20
COLLEGEST	0419	L & T CR	Medium	51	Ft	0.6	Crack Sealing - AC	AC	391	22	51	Ft	\$0.60	\$30.67
COLONIALAV	0447	L & T CR	High	3	Ft	0.0	Patching - AC Shallow	AC	864	24	9	SqFt	\$2.78	\$25.01
COLONIALAV	0447	POTHOLE	Low	11	Count	0.1	Patching - AC Deep	AC	864	24	33	SqFt	\$5.56	\$182.93
COLONIALAV	0447	L & T CR	Medium	878	Ft	4.2	Crack Sealing - AC	AC	864	24	878	Ft	\$0.60	\$526.57
COLONYDR	0468	RUTTING	High	9	SqFt	0.0	Patching - AC Shallow	AC	1193	24	10	SqFt	\$2.78	\$25.83
COMMERCEDR	0543	RUTTING	High	14	SqFt	0.1	Patching - AC Shallow	AC	583	36	14	SqFt	\$2.78	\$38.57
CONGRESSPK	0544	POTHOLE	Low	4	Count	0.0	Patching - AC Deep	AC	1160	34	12	SqFt	\$5.56	\$67.68
CONGRESSPK	0544	RUTTING	Medium	54	SqFt	0.1	Patching - AC Shallow	AC	1160	34	54	SqFt	\$2.78	\$150.25
CONGRESSPK	0544	L & T CR	Medium	741	Ft	1.9	Crack Sealing - AC	AC	1160	34	741	Ft	\$0.60	\$444.80
CONGRESSPK	0544	ALLIGATOR CR	High	2	SqFt	0.0	Patching - AC Deep	AC	1160	34	11	SqFt	\$5.56	\$58.60
CONGRESSPK	0544	L & T CR	High	23	Ft	0.1	Patching - AC Shallow	AC	1160	34	75	SqFt	\$2.78	\$208.73
CONGRESSPK	0544	ALLIGATOR CR	Medium	273	SqFt	0.7	Patching - AC Deep	AC	1160	34	343	SqFt	\$5.56	\$1,907.83
COPPERFIEL	0165	POTHOLE	Low	6	Count	0.0	Patching - AC Deep	AC	1219	26	18	SqFt	\$5.56	\$103.07
COPPERFIEL	0165	L & T CR	Medium	180	Ft	0.6	Crack Sealing - AC	AC	1219	26	179	Ft	\$0.60	\$107.72
COTTONWOOD	0027	ALLIGATOR CR	High	8	SqFt	0.0	Patching - AC Deep	AC	1112	22	24	SqFt	\$5.56	\$128.83
COTTONWOOD	0027	RUTTING	Medium	25	SqFt	0.1	Patching - AC Shallow	AC	1112	22	25	SqFt	\$2.78	\$69.88
COTTONWOOD	0027	L & T CR	Medium	211	Ft	0.9	Crack Sealing - AC	AC	1112	22	211	Ft	\$0.60	\$126.76
COTTONWOOD	0027	ALLIGATOR CR	Medium	16	SqFt	0.1	Patching - AC Deep	AC	1112	22	37	SqFt	\$5.56	\$201.80
COTTONWOOD	0027	POTHOLE	Low	5	Count	0.0	Patching - AC Deep	AC	1112	22	15	SqFt	\$5.56	\$83.94
COTTONWOOD	0027	L & T CR	High	18	Ft	0.1	Patching - AC Shallow	AC	1112	22	58	SqFt	\$2.78	\$160.43
COUNTRYCLU	0115	L & T CR	Medium	8	Ft	0.0	Crack Sealing - AC	AC	1180	22	8	Ft	\$0.60	\$4.96
COUNTRYCLU	0512	L & T CR	High	4	Ft	0.0	Patching - AC Shallow	AC	2908	26	15	SqFt	\$2.78	\$40.48
COUNTRYCLU	0512	L & T CR	Medium	28	Ft	0.0	Crack Sealing - AC	AC	2908	26	28	Ft	\$0.60	\$16.96
COUNTRYCLU	0633	L & T CR	Medium	31	Ft	0.1	Crack Sealing - AC	AC	1007	26	31	Ft	\$0.60	\$18.79
COVENTRYLN	0253	L & T CR	Medium	1847	Ft	2.0	Crack Sealing - AC	AC	3525	26	1847	Ft	\$0.60	\$1,108.08
COVENTRYLN	0253	POTHOLE	Low	3	Count	0.0	Patching - AC Deep	AC	3525	26	9	SqFt	\$5.56	\$48.54
COVENTRYLN	0253	RUTTING	Medium	10	SqFt	0.0	Patching - AC Shallow	AC	3525	26	10	SqFt	\$2.78	\$26.94
COVENTRYLN	0253	L & T CR	High	75	Ft	0.1	Patching - AC Shallow	AC	3525	26	246	SqFt	\$2.78	\$685.78
COVENTRYLN	0253	ALLIGATOR CR	Medium	37	SqFt	0.0	Patching - AC Deep	AC	3525	26	66	SqFt	\$5.56	\$367.83
COWLINST	0689	L & T CR	High	10	Ft	0.1	Patching - AC Shallow	AC	715	24	34	SqFt	\$2.78	\$95.35
COWLINST	0689	ALLIGATOR CR	Medium	67	SqFt	0.4	Patching - AC Deep	AC	715	24	103	SqFt	\$5.56	\$576.69

## Details of the 2022 Localized Distress Maintenance Plan

BranchID	SectionID	Description	Severity	Distress Qty	Distress Unit	Percent Distress	Work Description	Surface Type	Section Length (Ft)	Section Width (Ft)	Work Qty	Work Unit	Unit Cost	Work Cost
COWLINST	0689	L & T CR	Medium	1147	Ft	6.7	Crack Sealing - AC	AC	715	24	1147	Ft	\$0.60	\$687.97
CRABAPPLED	0413	RUTTING	High	10	SqFt	0.0	Patching - AC Shallow	AC	1961	26	10	SqFt	\$2.78	\$27.03
CRABTREEDR	0520	L & T CR	Medium	9	Ft	0.1	Crack Sealing - AC	AC	581	24	10	Ft	\$0.60	\$5.65
CRABTREEDR	0520	L & T CR	High	2	Ft	0.0	Patching - AC Shallow	AC	581	24	8	SqFt	\$2.78	\$20.06
CRANDONPL	0361	L & T CR	Medium	93	Ft	0.5	Crack Sealing - AC	AC	858	24	93	Ft	\$0.60	\$55.68
CRANDONPL	0764	RUTTING	Medium	13	SqFt	0.3	Patching - AC Shallow	AC	200	24	13	SqFt	\$2.78	\$35.25
CRIMSONDR	0314	ALLIGATOR CR	Medium	17	SqFt	0.1	Patching - AC Deep	AC	1371	26	37	SqFt	\$5.56	\$205.45
CRIMSONDR	0314	L & T CR	High	1	Ft	0.0	Patching - AC Shallow	AC	1371	26	3	SqFt	\$2.78	\$7.78
CRIMSONDR	0314	L & T CR	Medium	229	Ft	0.6	Crack Sealing - AC	AC	1371	26	229	Ft	\$0.60	\$137.69
CRYSTALBEA	0284	RUTTING	Medium	17	SqFt	0.1	Patching - AC Shallow	AC	919	22	16	SqFt	\$2.78	\$46.03
CRYSTALPOI	0176	RUTTING	Medium	29	SqFt	0.1	Patching - AC Shallow	AC	895	36	29	SqFt	\$2.78	\$80.81
CRYSTALPOI	0176	POTHOLE	Low	9	Count	0.0	Patching - AC Deep	AC	895	36	26	SqFt	\$5.56	\$145.60
CRYSTALPOI	0176	L & T CR	High	7	Ft	0.0	Patching - AC Shallow	AC	895	36	22	SqFt	\$2.78	\$61.31
CRYSTALPOI	0176	ALLIGATOR CR	High	17	SqFt	0.1	Patching - AC Deep	AC	895	36	38	SqFt	\$5.56	\$207.04
CRYSTALPOI	0176	L & T CR	Medium	586	Ft	1.8	Crack Sealing - AC	AC	895	36	586	Ft	\$0.60	\$351.86
CRYSTALPOI	0176	ALLIGATOR CR	Medium	138	SqFt	0.4	Patching - AC Deep	AC	895	36	189	SqFt	\$5.56	\$1,054.17
CRYSTALRID	0020	L & T CR	Medium	111	Ft	0.2	Crack Sealing - AC	AC	1597	34	111	Ft	\$0.60	\$66.30
CRYSTALRID	0020	L & T CR	High	338	Ft	0.6	Patching - AC Shallow	AC	1597	34	1108	SqFt	\$2.78	\$3,078.80
CRYSTALRID	0327	RUTTING	High	13	SqFt	0.0	Patching - AC Shallow	AC	1516	34	13	SqFt	\$2.78	\$36.82
CRYSTALRID	0425	L & T CR	High	33	Ft	0.1	Patching - AC Shallow	AC	1621	34	110	SqFt	\$2.78	\$303.99
CRYSTALRID	0425	RUTTING	Medium	129	SqFt	0.2	Patching - AC Shallow	AC	1621	34	129	SqFt	\$2.78	\$358.89
CRYSTALRID	0425	ALLIGATOR CR	Medium	139	SqFt	0.3	Patching - AC Deep	AC	1621	34	189	SqFt	\$5.56	\$1,056.00
CRYSTALRID	0425	L & T CR	Medium	1027	Ft	1.9	Crack Sealing - AC	AC	1621	34	1027	Ft	\$0.60	\$616.15
CRYSTALRID	0425	RUTTING	High	13	SqFt	0.0	Patching - AC Deep	AC	1621	34	13	SqFt	\$5.56	\$71.76
CRYSTALRID	0425	ALLIGATOR CR	High	22	SqFt	0.0	Patching - AC Deep	AC	1621	34	45	SqFt	\$5.56	\$248.40
CUMBERLAND	0407	L & T CR	High	4	Ft	0.0	Patching - AC Shallow	AC	1154	22	13	SqFt	\$2.78	\$35.32
CUMBERLAND	0407	RUTTING	Medium	17	SqFt	0.1	Patching - AC Shallow	AC	1154	22	17	SqFt	\$2.78	\$47.49
CUMBERLAND	0407	L & T CR	Medium	33	Ft	0.1	Crack Sealing - AC	AC	1154	22	32	Ft	\$0.60	\$19.51
CUMBERLAND	0407	POTHOLE	Low	13	Count	0.1	Patching - AC Deep	AC	1154	22	39	SqFt	\$5.56	\$213.90
CUNNINGHAM	0465	L & T CR	Medium	243	Ft	1.1	Crack Sealing - AC	AC	958	24	243	Ft	\$0.60	\$145.77
DARBYCT	0612	L & T CR	Medium	39	Ft	1.6	Crack Sealing - AC	AC	95	26	39	Ft	\$0.60	\$23.58
DARLINGTON	0074	RUTTING	Medium	135	SqFt	0.2	Patching - AC Shallow	AC	3152	28	135	SqFt	\$2.78	\$374.19
DARLINGTON	0074	POTHOLE	Low	9	Count	0.0	Patching - AC Deep	AC	3152	28	28	SqFt	\$5.56	\$157.29
DARLINGTON	0723	L & T CR	Medium	30	Ft	0.4	Crack Sealing - AC	AC	394	22	31	Ft	\$0.60	\$18.24
DARLINGTON	0739	ALLIGATOR CR	Medium	10	SqFt	0.1	Patching - AC Deep	AC	490	28	27	SqFt	\$5.56	\$150.17
DARLINGTON	0739	RUTTING	Medium	12	SqFt	0.1	Patching - AC Shallow	AC	490	28	12	SqFt	\$2.78	\$33.63

## Details of the 2022 Localized Distress Maintenance Plan

BranchID	SectionID	Description	Severity	Distress Qty	Distress Unit	Percent Distress	Work Description	Surface Type	Section Length (Ft)	Section Width (Ft)	Work Qty	Work Unit	Unit Cost	Work Cost
DARLINGTON	0739	L & T CR	Medium	250	Ft	1.8	Crack Sealing - AC	AC	490	28	250	Ft	\$0.60	\$150.12
DARLINGTON	0741	L & T CR	Medium	326	Ft	2.5	Crack Sealing - AC	AC	473	28	326	Ft	\$0.60	\$195.44
DARLINGTON	0741	RUTTING	Medium	12	SqFt	0.1	Patching - AC Shallow	AC	473	28	12	SqFt	\$2.78	\$32.41
DARLINGTON	0741	L & T CR	High	5	Ft	0.0	Patching - AC Shallow	AC	473	28	17	SqFt	\$2.78	\$48.54
DARLINGTON	0741	ALLIGATOR CR	Medium	6	SqFt	0.1	Patching - AC Deep	AC	473	28	20	SqFt	\$5.56	\$115.20
DARTMOORDR	0033	L & T CR	Medium	87	Ft	0.1	Crack Sealing - AC	AC	3229	36	87	Ft	\$0.60	\$52.43
DARTMOORDR	0063	RUTTING	High	15	SqFt	0.1	Patching - AC Shallow	AC	688	40	15	SqFt	\$2.78	\$42.90
DARTMOORDR	0079	POTHOLE	Low	22	Count	0.0	Patching - AC Deep	AC	4565	40	67	SqFt	\$5.56	\$372.74
DARTMOORDR	0079	L & T CR	Medium	1862	Ft	1.0	Crack Sealing - AC	AC	4565	40	1862	Ft	\$0.60	\$1,116.98
DARTMOORDR	0079	RUTTING	Medium	104	SqFt	0.1	Patching - AC Shallow	AC	4565	40	104	SqFt	\$2.78	\$289.62
DARTMOORDR	0079	ALLIGATOR CR	Medium	159	SqFt	0.1	Patching - AC Deep	AC	4565	40	213	SqFt	\$5.56	\$1,187.71
DARTMOORDR	0079	L & T CR	High	5	Ft	0.0	Patching - AC Shallow	AC	4565	40	16	SqFt	\$2.78	\$44.02
DEARBORNCT	0619	L & T CR	Medium	508	Ft	2.8	Crack Sealing - AC	AC	692	26	508	Ft	\$0.60	\$304.60
DEERHAVEND	0045	POTHOLE	Low	3	Count	0.0	Patching - AC Deep	AC	2466	24	9	SqFt	\$5.56	\$45.33
DEERHAVEND	0045	RUTTING	Medium	43	SqFt	0.1	Patching - AC Shallow	AC	2466	24	43	SqFt	\$2.78	\$118.70
DEERHAVEND	0045	L & T CR	Medium	133	Ft	0.2	Crack Sealing - AC	AC	2466	24	134	Ft	\$0.60	\$80.04
DEERHAVEND	0045	L & T CR	High	3	Ft	0.0	Patching - AC Shallow	AC	2466	24	10	SqFt	\$2.78	\$25.53
DEERHAVEND	0189	L & T CR	Medium	30	Ft	0.1	Crack Sealing - AC	AC	1492	24	30	Ft	\$0.60	\$18.01
DEERHAVEND	0189	RUTTING	Medium	9	SqFt	0.0	Patching - AC Shallow	AC	1492	24	10	SqFt	\$2.78	\$26.31
DOGWOODDR	0141	L & T CR	Medium	3	Ft	0.0	Crack Sealing - AC	AC	2358	24	3	Ft	\$0.60	\$1.74
DOGWOODDR	0141	RUTTING	Medium	9	SqFt	0.0	Patching - AC Shallow	AC	2358	24	9	SqFt	\$2.78	\$25.09
DOGWOODDR	0141	L & T CR	High	2	Ft	0.0	Patching - AC Shallow	AC	2358	24	6	SqFt	\$2.78	\$17.80
DOLLELN	0353	POTHOLE	Low	7	Count	0.1	Patching - AC Deep	AC	450	24	20	SqFt	\$5.56	\$111.08
DOLLELN	0353	L & T CR	Medium	15	Ft	0.1	Crack Sealing - AC	AC	450	24	15	Ft	\$0.60	\$9.13
DOLOROSAVI	0311	RUTTING	High	61	SqFt	0.2	Patching - AC Shallow	AC	999	28	61	SqFt	\$2.78	\$170.12
DOUGLASAVE	0352	RUTTING	High	18	SqFt	0.0	Patching - AC Shallow	AC	1807	24	18	SqFt	\$2.78	\$50.70
DRIFTWOODC	0368	RUTTING	High	30	SqFt	0.3	Patching - AC Deep	AC	404	24	30	SqFt	\$5.56	\$169.38
DRIFTWOODC	0368	RUTTING	Medium	10	SqFt	0.1	Patching - AC Shallow	AC	404	24	10	SqFt	\$2.78	\$26.79
DRIFTWOODC	0368	L & T CR	Medium	93	Ft	1.0	Crack Sealing - AC	AC	404	24	93	Ft	\$0.60	\$55.77
DRIFTWOODC	0368	L & T CR	High	49	Ft	0.5	Patching - AC Shallow	AC	404	24	159	SqFt	\$2.78	\$443.84
DRIFTWOODL	0118	L & T CR	Medium	334	Ft	0.4	Crack Sealing - AC	AC	2628	32	334	Ft	\$0.60	\$200.23
DRIFTWOODL	0118	L & T CR	High	6	Ft	0.0	Patching - AC Shallow	AC	2628	32	18	SqFt	\$2.78	\$52.27
DRIFTWOODL	0118	RUTTING	Medium	24	SqFt	0.0	Patching - AC Shallow	AC	2628	32	25	SqFt	\$2.78	\$67.58
DRIVEINLN	0674	L & T CR	Medium	473	Ft	6.2	Crack Sealing - AC	AC	320	24	472	Ft	\$0.60	\$283.54
DRIVEINLN	0677	L & T CR	Medium	515	Ft	5.8	Crack Sealing - AC	AC	370	24	514	Ft	\$0.60	\$308.69
DURHAMCT	0006	RUTTING	High	10	SqFt	0.1	Patching - AC Shallow	AC	479	24	10	SqFt	\$2.78	\$26.73

## Details of the 2022 Localized Distress Maintenance Plan

BranchID	SectionID	Description	Severity	Distress Qty	Distress Unit	Percent Distress	Work Description	Surface Type	Section Length (Ft)	Section Width (Ft)	Work Qty	Work Unit	Unit Cost	Work Cost
EAGLEST	0211	ALLIGATOR CR	Medium	0	SqFt	0.0	Patching - AC Deep	AC	890	24	6	SqFt	\$5.56	\$35.53
EAGLEST	0211	L & T CR	Medium	402	Ft	1.9	Crack Sealing - AC	AC	890	24	402	Ft	\$0.60	\$241.39
EAGLEST	0211	RUTTING	Medium	18	SqFt	0.1	Patching - AC Shallow	AC	890	24	18	SqFt	\$2.78	\$51.08
EAGLEST	0211	L & T CR	High	1	Ft	0.0	Patching - AC Shallow	AC	890	24	2	SqFt	\$2.78	\$5.03
EASTENDAVE	0157	L & T CR	Medium	13	Ft	0.1	Crack Sealing - AC	AC	1030	22	13	Ft	\$0.60	\$8.05
EASTENDAVE	0157	RUTTING	High	9	SqFt	0.0	Patching - AC Deep	AC	1030	22	9	SqFt	\$5.56	\$49.57
EASTENDAVE	0157	RUTTING	Medium	9	SqFt	0.0	Patching - AC Shallow	AC	1030	22	9	SqFt	\$2.78	\$24.78
EASTGATERD	0250	RUTTING	Medium	8	SqFt	0.0	Patching - AC Shallow	AC	2162	22	9	SqFt	\$2.78	\$23.30
EASTGATERD	0250	L & T CR	Medium	1	Ft	0.0	Crack Sealing - AC	AC	2162	22	1	Ft	\$0.60	\$0.72
EASTST	0221	L & T CR	Medium	112	Ft	0.3	Crack Sealing - AC	AC	1363	24	112	Ft	\$0.60	\$67.28
EASTST	0221	RUTTING	Medium	9	SqFt	0.0	Patching - AC Shallow	AC	1363	24	10	SqFt	\$2.78	\$26.28
EASTST	0221	L & T CR	High	48	Ft	0.2	Patching - AC Shallow	AC	1363	24	156	SqFt	\$2.78	\$435.25
EASTVIEWAV	0495	L & T CR	Medium	30	Ft	0.2	Crack Sealing - AC	AC	804	22	30	Ft	\$0.60	\$17.74
EBERKSHIRE	0242	L & T CR	Medium	449	Ft	0.5	Crack Sealing - AC	AC	2522	40	449	Ft	\$0.60	\$269.47
EBERKSHIRE	0242	RUTTING	Medium	75	SqFt	0.1	Patching - AC Shallow	AC	2522	40	74	SqFt	\$2.78	\$207.55
EBERKSHIRE	0242	L & T CR	High	11	Ft	0.0	Patching - AC Shallow	AC	2522	40	36	SqFt	\$2.78	\$97.75
EBERKSHIRE	0242	POTHOLE	Low	9	Count	0.0	Patching - AC Deep	AC	2522	40	27	SqFt	\$5.56	\$149.59
EBERKSHIRE	0560	ALLIGATOR CR	Medium	16	SqFt	0.1	Patching - AC Deep	AC	842	36	37	SqFt	\$5.56	\$201.62
EBERKSHIRE	0560	L & T CR	Medium	428	Ft	1.4	Crack Sealing - AC	AC	842	36	428	Ft	\$0.60	\$257.08
EBERKSHIRE	0560	RUTTING	High	27	SqFt	0.1	Patching - AC Deep	AC	842	36	27	SqFt	\$5.56	\$152.16
EBERKSHIRE	0560	RUTTING	Medium	370	SqFt	1.2	Patching - AC Shallow	AC	842	36	369	SqFt	\$2.78	\$1,027.66
EBERKSHIRE	0560	L & T CR	High	44	Ft	0.1	Patching - AC Shallow	AC	842	36	143	SqFt	\$2.78	\$398.03
EBERKSHIRE	0757	L & T CR	Medium	334	Ft	1.9	Crack Sealing - AC	AC	430	40	334	Ft	\$0.60	\$200.32
ECRANDONCT	0482	L & T CR	High	1	Ft	0.0	Patching - AC Shallow	AC	1043	24	4	SqFt	\$2.78	\$11.82
ECRANDONCT	0482	RUTTING	Medium	11	SqFt	0.0	Patching - AC Shallow	AC	1043	24	11	SqFt	\$2.78	\$29.26
ECRYSTALLA	0656	ALLIGATOR CR	Medium	37	SqFt	0.1	Patching - AC Deep	AC	2657	22	66	SqFt	\$5.56	\$364.52
ECRYSTALLA	0656	L & T CR	High	191	Ft	0.3	Patching - AC Shallow	AC	2657	22	626	SqFt	\$2.78	\$1,742.06
ECRYSTALLA	0656	RUTTING	Medium	116	SqFt	0.2	Patching - AC Shallow	AC	2657	22	115	SqFt	\$2.78	\$321.34
ECRYSTALLA	0656	RUTTING	High	91	SqFt	0.2	Patching - AC Deep	AC	2657	22	90	SqFt	\$5.56	\$505.00
ECRYSTALLA	0656	L & T CR	Medium	320	Ft	0.6	Crack Sealing - AC	AC	2657	22	320	Ft	\$0.60	\$191.97
ECRYSTALLA	0656	ALLIGATOR CR	High	239	SqFt	0.4	Patching - AC Deep	AC	2657	22	306	SqFt	\$5.56	\$1,697.45
EDGEBROOKD	0180	L & T CR	High	10	Ft	0.1	Patching - AC Shallow	AC	699	26	34	SqFt	\$2.78	\$94.65
EDGEBROOKD	0180	L & T CR	Medium	36	Ft	0.2	Crack Sealing - AC	AC	699	26	35	Ft	\$0.60	\$21.32
EDGEBROOKD	0180	ALLIGATOR CR	Medium	3	SqFt	0.0	Patching - AC Deep	AC	699	26	14	SqFt	\$5.56	\$79.14
EDGEBROOKD	0180	RUTTING	Medium	10	SqFt	0.1	Patching - AC Shallow	AC	699	26	10	SqFt	\$2.78	\$28.34
EDGEWATERD	0287	L & T CR	Medium	25	Ft	0.3	Crack Sealing - AC	AC	468	22	25	Ft	\$0.60	\$15.23

## Details of the 2022 Localized Distress Maintenance Plan

BranchID	SectionID	Description	Severity	Distress Qty	Distress Unit	Percent Distress	Work Description	Surface Type	Section Length (Ft)	Section Width (Ft)	Work Qty	Work Unit	Unit Cost	Work Cost
EDGEWATERD	0287	RUTTING	High	11	SqFt	0.1	Patching - AC Deep	AC	468	22	11	SqFt	\$5.56	\$62.24
EDGEWATERD	0287	L & T CR	High	1	Ft	0.0	Patching - AC Shallow	AC	468	22	3	SqFt	\$2.78	\$7.97
EDGWOODAV	0613	POTHOLE	Low	3	Count	0.0	Patching - AC Deep	AC	1048	22	8	SqFt	\$5.56	\$43.62
EFRANKLINA	0423	L & T CR	Medium	1	Ft	0.0	Crack Sealing - AC	AC	552	22	1	Ft	\$0.60	\$0.50
EFRANKLINA	0423	L & T CR	High	46	Ft	0.4	Patching - AC Shallow	AC	552	22	150	SqFt	\$2.78	\$416.78
ELLSWORTHS	0070	ALLIGATOR CR	High	2	SqFt	0.0	Patching - AC Deep	AC	1883	24	11	SqFt	\$5.56	\$62.76
ELLSWORTHS	0070	RUTTING	Medium	18	SqFt	0.0	Patching - AC Shallow	AC	1883	24	18	SqFt	\$2.78	\$49.97
ELLSWORTHS	0070	L & T CR	Medium	855	Ft	1.9	Crack Sealing - AC	AC	1883	24	855	Ft	\$0.60	\$513.02
ELLSWORTHS	0070	L & T CR	High	56	Ft	0.1	Patching - AC Shallow	AC	1883	24	183	SqFt	\$2.78	\$508.83
ELLSWORTHS	0070	ALLIGATOR CR	Medium	203	SqFt	0.5	Patching - AC Deep	AC	1883	24	265	SqFt	\$5.56	\$1,469.88
ELMHURSTST	0193	RUTTING	High	39	SqFt	0.1	Patching - AC Shallow	AC	1233	26	39	SqFt	\$2.78	\$107.85
ELMHURSTST	0584	ALLIGATOR CR	Medium	1	SqFt	0.0	Patching - AC Deep	AC	443	36	10	SqFt	\$5.56	\$56.50
ELMHURSTST	0584	L & T CR	High	16	Ft	0.1	Patching - AC Shallow	AC	443	36	53	SqFt	\$2.78	\$147.26
ELMHURSTST	0584	L & T CR	Medium	257	Ft	1.6	Crack Sealing - AC	AC	443	36	258	Ft	\$0.60	\$154.46
ELMST	0332	L & T CR	High	16	Ft	0.1	Patching - AC Shallow	AC	772	24	54	SqFt	\$2.78	\$149.77
ELMST	0332	RUTTING	High	8	SqFt	0.0	Patching - AC Deep	AC	772	24	9	SqFt	\$5.56	\$45.49
ELSINOORLN	0366	RUTTING	Medium	9	SqFt	0.0	Patching - AC Shallow	AC	1540	22	9	SqFt	\$2.78	\$23.54
ELSINOORLN	0366	L & T CR	Medium	17	Ft	0.1	Crack Sealing - AC	AC	1540	22	17	Ft	\$0.60	\$10.24
ELSINOORLN	0366	RUTTING	High	9	SqFt	0.0	Patching - AC Deep	AC	1540	22	9	SqFt	\$5.56	\$47.08
EPADDOCKST	0569	RUTTING	High	9	SqFt	0.1	Patching - AC Shallow	AC	545	22	9	SqFt	\$2.78	\$23.72
EPALMERCT	0547	RUTTING	Medium	11	SqFt	0.1	Patching - AC Shallow	AC	959	26	11	SqFt	\$2.78	\$31.28
EPALMERCT	0547	L & T CR	Medium	54	Ft	0.2	Crack Sealing - AC	AC	959	26	54	Ft	\$0.60	\$32.68
EPALMERCT	0547	L & T CR	High	1	Ft	0.0	Patching - AC Shallow	AC	959	26	4	SqFt	\$2.78	\$12.33
ERICKST	0134	L & T CR	Medium	343	Ft	0.4	Crack Sealing - AC	AC	2642	36	343	Ft	\$0.60	\$205.84
ERICKST	0134	L & T CR	High	120	Ft	0.1	Patching - AC Shallow	AC	2642	36	394	SqFt	\$2.78	\$1,093.80
ESSEXLN	0095	RUTTING	Medium	8	SqFt	0.0	Patching - AC Shallow	AC	1206	22	9	SqFt	\$2.78	\$23.13
ESSEXLN	0095	POTHOLE	Low	3	Count	0.0	Patching - AC Deep	AC	1206	22	8	SqFt	\$5.56	\$41.68
ESSEXLN	0095	L & T CR	High	3	Ft	0.0	Patching - AC Shallow	AC	1206	22	10	SqFt	\$2.78	\$25.53
ESSEXLN	0095	L & T CR	Medium	67	Ft	0.3	Crack Sealing - AC	AC	1206	22	67	Ft	\$0.60	\$40.44
ESTHERST	0298	L & T CR	Medium	31	Ft	0.1	Crack Sealing - AC	AC	1195	22	31	Ft	\$0.60	\$18.56
ESTONECREE	0174	L & T CR	Medium	47	Ft	0.1	Crack Sealing - AC	AC	1881	24	47	Ft	\$0.60	\$28.41
ESTONECREE	0174	L & T CR	High	22	Ft	0.1	Patching - AC Shallow	AC	1881	24	73	SqFt	\$2.78	\$202.69
ESTONECREE	0174	ALLIGATOR CR	Medium	2	SqFt	0.0	Patching - AC Deep	AC	1881	24	12	SqFt	\$5.56	\$63.11
ESTONECREE	0174	RUTTING	Medium	8	SqFt	0.0	Patching - AC Shallow	AC	1881	24	8	SqFt	\$2.78	\$21.44
EUGENEST	0556	L & T CR	Medium	52	Ft	0.3	Crack Sealing - AC	AC	777	24	52	Ft	\$0.60	\$31.38
EVERETTAVE	0051	ALLIGATOR CR	Medium	9	SqFt	0.0	Patching - AC Deep	AC	882	26	25	SqFt	\$5.56	\$138.36

## Details of the 2022 Localized Distress Maintenance Plan

BranchID	SectionID	Description	Severity	Distress Qty	Distress Unit	Percent Distress	Work Description	Surface Type	Section Length (Ft)	Section Width (Ft)	Work Qty	Work Unit	Unit Cost	Work Cost
EVERETTAV	0051	POTHOLE	Low	3	Count	0.0	Patching - AC Deep	AC	882	26	9	SqFt	\$5.56	\$50.59
EVERETTAV	0051	L & T CR	Medium	74	Ft	0.3	Crack Sealing - AC	AC	882	26	74	Ft	\$0.60	\$44.46
EVERETTAV	0051	RUTTING	Medium	30	SqFt	0.1	Patching - AC Shallow	AC	882	26	30	SqFt	\$2.78	\$84.24
EVERETTAV	0051	RUTTING	High	20	SqFt	0.1	Patching - AC Deep	AC	882	26	20	SqFt	\$5.56	\$112.31
EVERETTAV	0168	ALLIGATOR CR	Medium	0	SqFt	0.0	Patching - AC Deep	AC	1793	22	8	SqFt	\$5.56	\$39.83
EVERETTAV	0168	L & T CR	High	22	Ft	0.1	Patching - AC Shallow	AC	1793	22	71	SqFt	\$2.78	\$198.00
EVERETTAV	0168	RUTTING	Medium	8	SqFt	0.0	Patching - AC Shallow	AC	1793	22	9	SqFt	\$2.78	\$23.31
EVERETTAV	0168	RUTTING	High	8	SqFt	0.0	Patching - AC Deep	AC	1793	22	9	SqFt	\$5.56	\$46.63
EVERETTAV	0168	L & T CR	Medium	431	Ft	1.1	Crack Sealing - AC	AC	1793	22	430	Ft	\$0.60	\$258.35
EVERGREENP	0576	L & T CR	Medium	68	Ft	0.2	Crack Sealing - AC	AC	1272	24	68	Ft	\$0.60	\$40.89
EVERGREENP	0576	RUTTING	Medium	27	SqFt	0.1	Patching - AC Shallow	AC	1272	24	27	SqFt	\$2.78	\$75.94
EWOODSTOCK	0231	RUTTING	High	26	SqFt	0.0	Patching - AC Shallow	AC	1483	40	26	SqFt	\$2.78	\$72.79
EXCHANGEDR	0248	L & T CR	High	125	Ft	0.2	Patching - AC Shallow	AC	2049	36	411	SqFt	\$2.78	\$1,143.15
EXCHANGEDR	0248	RUTTING	Medium	66	SqFt	0.1	Patching - AC Shallow	AC	2049	36	67	SqFt	\$2.78	\$184.36
EXCHANGEDR	0248	L & T CR	Medium	1184	Ft	1.6	Crack Sealing - AC	AC	2049	36	1184	Ft	\$0.60	\$710.37
EXCHANGEDR	0248	ALLIGATOR CR	Medium	285	SqFt	0.4	Patching - AC Deep	AC	2049	36	357	SqFt	\$5.56	\$1,984.22
EXCHANGEDR	0248	RUTTING	High	41	SqFt	0.1	Patching - AC Deep	AC	2049	36	41	SqFt	\$5.56	\$227.65
EXCHANGEDR	0248	POTHOLE	Low	12	Count	0.0	Patching - AC Deep	AC	2049	36	37	SqFt	\$5.56	\$205.09
EXCHANGEDR	0248	ALLIGATOR CR	High	187	SqFt	0.3	Patching - AC Deep	AC	2049	36	245	SqFt	\$5.56	\$1,366.53
EXCHANGEDR	0383	L & T CR	Medium	1257	Ft	1.5	Crack Sealing - AC	AC	2328	36	1257	Ft	\$0.60	\$754.16
EXCHANGEDR	0383	L & T CR	High	156	Ft	0.2	Patching - AC Shallow	AC	2328	36	512	SqFt	\$2.78	\$1,423.02
EXCHANGEDR	0383	POTHOLE	Low	12	Count	0.0	Patching - AC Deep	AC	2328	36	37	SqFt	\$5.56	\$206.16
EXCHANGEDR	0383	RUTTING	Medium	94	SqFt	0.1	Patching - AC Shallow	AC	2328	36	94	SqFt	\$2.78	\$261.59
EXCHANGEDR	0383	ALLIGATOR CR	Medium	12	SqFt	0.0	Patching - AC Deep	AC	2328	36	30	SqFt	\$5.56	\$168.55
EXMOORT	0256	L & T CR	Medium	178	Ft	1.4	Crack Sealing - AC	AC	477	26	178	Ft	\$0.60	\$106.67
EXMOORT	0256	L & T CR	High	2	Ft	0.0	Patching - AC Shallow	AC	477	26	5	SqFt	\$2.78	\$15.37
EXMOORT	0302	L & T CR	Medium	213	Ft	1.1	Crack Sealing - AC	AC	729	26	213	Ft	\$0.60	\$127.81
EXMOORT	0302	ALLIGATOR CR	Medium	2	SqFt	0.0	Patching - AC Deep	AC	729	26	12	SqFt	\$5.56	\$62.87
EXMOORT	0302	L & T CR	High	15	Ft	0.1	Patching - AC Shallow	AC	729	26	47	SqFt	\$2.78	\$132.37
EXMOORT	0302	RUTTING	Medium	12	SqFt	0.1	Patching - AC Shallow	AC	729	26	12	SqFt	\$2.78	\$33.85
FAIRVIEWPA	0502	L & T CR	Medium	303	Ft	1.7	Crack Sealing - AC	AC	693	26	303	Ft	\$0.60	\$181.71
FAIRVIEWPA	0502	ALLIGATOR CR	Medium	23	SqFt	0.1	Patching - AC Deep	AC	693	26	46	SqFt	\$5.56	\$257.84
FEDERALDR	0622	L & T CR	High	2	Ft	0.0	Patching - AC Shallow	AC	1511	36	8	SqFt	\$2.78	\$21.14
FEDERALDR	0622	RUTTING	High	37	SqFt	0.1	Patching - AC Deep	AC	1511	36	38	SqFt	\$5.56	\$208.08
FEDERALDR	0622	L & T CR	Medium	201	Ft	0.4	Crack Sealing - AC	AC	1511	36	201	Ft	\$0.60	\$120.67
FERNLEAFDR	0445	RUTTING	Medium	13	SqFt	0.1	Patching - AC Shallow	AC	749	26	13	SqFt	\$2.78	\$35.75

## Details of the 2022 Localized Distress Maintenance Plan

BranchID	SectionID	Description	Severity	Distress Qty	Distress Unit	Percent Distress	Work Description	Surface Type	Section Length (Ft)	Section Width (Ft)	Work Qty	Work Unit	Unit Cost	Work Cost
FIELDSTONE	0213	RUTTING	Medium	9	SqFt	0.0	Patching - AC Shallow	AC	1447	24	10	SqFt	\$2.78	\$25.52
FIELDSTONE	0213	POTHOLE	Low	3	Count	0.0	Patching - AC Deep	AC	1447	24	9	SqFt	\$5.56	\$45.98
FIRSTST	0308	RUTTING	Medium	9	SqFt	0.0	Patching - AC Shallow	AC	997	24	10	SqFt	\$2.78	\$26.18
FIRSTST	0308	POTHOLE	Low	6	Count	0.0	Patching - AC Deep	AC	997	24	17	SqFt	\$5.56	\$94.35
FIRSTST	0308	L & T CR	Medium	231	Ft	1.0	Crack Sealing - AC	AC	997	24	231	Ft	\$0.60	\$138.44
FIRSTST	0308	ALLIGATOR CR	Medium	52	SqFt	0.2	Patching - AC Deep	AC	997	24	85	SqFt	\$5.56	\$473.42
FIRSTST	0308	RUTTING	High	9	SqFt	0.0	Patching - AC Deep	AC	997	24	10	SqFt	\$5.56	\$52.36
FIRSTST	0308	L & T CR	High	6	Ft	0.0	Patching - AC Shallow	AC	997	24	18	SqFt	\$2.78	\$52.11
FLAGSTONED	0071	L & T CR	Medium	42	Ft	0.2	Crack Sealing - AC	AC	1080	24	42	Ft	\$0.60	\$25.30
FLINTTRL	0295	L & T CR	High	21	Ft	0.1	Patching - AC Shallow	AC	733	24	69	SqFt	\$2.78	\$191.64
FLINTTRL	0295	L & T CR	Medium	422	Ft	2.4	Crack Sealing - AC	AC	733	24	422	Ft	\$0.60	\$253.07
FLORENCEST	0229	RUTTING	High	34	SqFt	0.4	Patching - AC Shallow	AC	333	24	34	SqFt	\$2.78	\$94.72
FLORESTAVI	0288	L & T CR	High	2	Ft	0.0	Patching - AC Shallow	AC	849	22	6	SqFt	\$2.78	\$17.74
FLORESTAVI	0288	RUTTING	Medium	9	SqFt	0.1	Patching - AC Shallow	AC	849	22	9	SqFt	\$2.78	\$24.01
FLORESTAVI	0288	L & T CR	Medium	180	Ft	1.0	Crack Sealing - AC	AC	849	22	180	Ft	\$0.60	\$107.84
FLORESTAVI	0288	ALLIGATOR CR	Medium	79	SqFt	0.4	Patching - AC Deep	AC	849	22	118	SqFt	\$5.56	\$658.46
FORESTLN	0083	RUTTING	Medium	18	SqFt	0.1	Patching - AC Shallow	AC	1329	24	18	SqFt	\$2.78	\$51.26
FOUNTAINGR	0452	L & T CR	High	2	Ft	0.0	Patching - AC Shallow	AC	1595	26	8	SqFt	\$2.78	\$21.56
FOUNTAINGR	0452	L & T CR	Medium	2619	Ft	6.3	Crack Sealing - AC	AC	1595	26	2619	Ft	\$0.60	\$1,571.30
FOUNTAINGR	0452	ALLIGATOR CR	Medium	5	SqFt	0.0	Patching - AC Deep	AC	1595	26	18	SqFt	\$5.56	\$104.44
FOUNTAINGR	0452	POTHOLE	Low	3	Count	0.0	Patching - AC Deep	AC	1595	26	9	SqFt	\$5.56	\$49.91
GAILCT	0481	L & T CR	Medium	142	Ft	4.0	Crack Sealing - AC	AC	160	22	142	Ft	\$0.60	\$85.46
GAILCT	0481	L & T CR	High	1	Ft	0.0	Patching - AC Shallow	AC	160	22	4	SqFt	\$2.78	\$13.02
GAILCT	0481	RUTTING	Medium	28	SqFt	0.8	Patching - AC Shallow	AC	160	22	28	SqFt	\$2.78	\$77.76
GANDERLN	0055	L & T CR	Medium	191	Ft	0.9	Crack Sealing - AC	AC	778	26	191	Ft	\$0.60	\$114.52
GARDINAVIS	0142	RUTTING	High	8	SqFt	0.0	Patching - AC Shallow	AC	1073	22	9	SqFt	\$2.78	\$23.35
GATESST	0220	L & T CR	High	22	Ft	0.1	Patching - AC Shallow	AC	1589	24	71	SqFt	\$2.78	\$197.25
GATESST	0220	L & T CR	Medium	238	Ft	0.6	Crack Sealing - AC	AC	1589	24	239	Ft	\$0.60	\$143.04
GILBERTAVE	0382	RUTTING	High	9	SqFt	0.0	Patching - AC Shallow	AC	1143	22	9	SqFt	\$2.78	\$23.52
GLASGOWLN	0580	L & T CR	Medium	59	Ft	0.7	Crack Sealing - AC	AC	351	24	59	Ft	\$0.60	\$35.58
GLENAVE	0283	L & T CR	Medium	131	Ft	0.5	Crack Sealing - AC	AC	1059	24	132	Ft	\$0.60	\$78.88
GLENAVE	0283	RUTTING	Medium	75	SqFt	0.3	Patching - AC Shallow	AC	1059	24	75	SqFt	\$2.78	\$209.18
GLENNRDG	0577	L & T CR	Medium	285	Ft	3.7	Crack Sealing - AC	AC	293	26	285	Ft	\$0.60	\$170.85
GOLDSBOROL	0599	L & T CR	Medium	255	Ft	1.2	Crack Sealing - AC	AC	908	24	255	Ft	\$0.60	\$153.06
GOLFCOURSE	0119	L & T CR	Medium	1202	Ft	0.6	Crack Sealing - AC	AC	5239	36	1202	Ft	\$0.60	\$721.14
GOLFCOURSE	0119	ALLIGATOR CR	Medium	65	SqFt	0.0	Patching - AC Deep	AC	5239	36	102	SqFt	\$5.56	\$567.15

## Details of the 2022 Localized Distress Maintenance Plan

BranchID	SectionID	Description	Severity	Distress Qty	Distress Unit	Percent Distress	Work Description	Surface Type	Section Length (Ft)	Section Width (Ft)	Work Qty	Work Unit	Unit Cost	Work Cost
GOLFCOURSE	0119	L & T CR	High	112	Ft	0.1	Patching - AC Shallow	AC	5239	36	367	SqFt	\$2.78	\$1,020.70
GOLFCOURSE	0159	L & T CR	Medium	266	Ft	0.3	Crack Sealing - AC	AC	2353	36	266	Ft	\$0.60	\$159.52
GOLFCOURSE	0159	L & T CR	High	2	Ft	0.0	Patching - AC Shallow	AC	2353	36	5	SqFt	\$2.78	\$15.91
GOLFCOURSE	0197	ALLIGATOR CR	Medium	209	SqFt	0.2	Patching - AC Deep	AC	2780	36	271	SqFt	\$5.56	\$1,508.10
GOLFCOURSE	0197	ALLIGATOR CR	High	1	SqFt	0.0	Patching - AC Deep	AC	2780	36	8	SqFt	\$5.56	\$44.57
GOLFCOURSE	0197	L & T CR	High	9	Ft	0.0	Patching - AC Shallow	AC	2780	36	31	SqFt	\$2.78	\$86.37
GOLFCOURSE	0197	L & T CR	Medium	1670	Ft	1.7	Crack Sealing - AC	AC	2780	36	1670	Ft	\$0.60	\$1,002.22
GOLFCOURSE	0197	RUTTING	Medium	27	SqFt	0.0	Patching - AC Shallow	AC	2780	36	27	SqFt	\$2.78	\$74.60
GOLFRD	0279	RUTTING	Medium	10	SqFt	0.0	Patching - AC Shallow	AC	1291	26	10	SqFt	\$2.78	\$27.85
GOLFRD	0279	POTHOLE	Low	3	Count	0.0	Patching - AC Deep	AC	1291	26	9	SqFt	\$5.56	\$50.19
GOLFRD	0279	L & T CR	Medium	97	Ft	0.3	Crack Sealing - AC	AC	1291	26	97	Ft	\$0.60	\$58.15
GOLFRD	0600	RUTTING	Medium	20	SqFt	0.1	Patching - AC Shallow	AC	967	26	20	SqFt	\$2.78	\$56.21
GOLFRD	0600	L & T CR	Medium	31	Ft	0.1	Crack Sealing - AC	AC	967	26	32	Ft	\$0.60	\$18.87
GOLFRD	0600	POTHOLE	Low	3	Count	0.0	Patching - AC Deep	AC	967	26	9	SqFt	\$5.56	\$50.64
GOLFRD	0600	L & T CR	High	22	Ft	0.1	Patching - AC Shallow	AC	967	26	72	SqFt	\$2.78	\$201.86
GRANDVIEWD	0303	L & T CR	Medium	2	Ft	0.0	Crack Sealing - AC	AC	2094	24	2	Ft	\$0.60	\$1.07
GRANDVIEWD	0303	L & T CR	High	7	Ft	0.0	Patching - AC Shallow	AC	2094	24	24	SqFt	\$2.78	\$65.66
GREENBRIER	0257	L & T CR	Medium	681	Ft	1.3	Crack Sealing - AC	AC	1950	26	681	Ft	\$0.60	\$408.68
GREENBRIER	0257	L & T CR	High	6	Ft	0.0	Patching - AC Shallow	AC	1950	26	20	SqFt	\$2.78	\$57.05
GREENBRIER	0437	L & T CR	Medium	23	Ft	0.2	Crack Sealing - AC	AC	528	26	23	Ft	\$0.60	\$13.88
GREENBRIER	0563	L & T CR	Medium	138	Ft	1.0	Crack Sealing - AC	AC	531	26	138	Ft	\$0.60	\$82.85
GREENBRIER	0563	RUTTING	High	11	SqFt	0.1	Patching - AC Deep	AC	531	26	11	SqFt	\$5.56	\$61.80
GREENFIELD	0014	RUTTING	High	9	SqFt	0.0	Patching - AC Deep	AC	1010	22	9	SqFt	\$5.56	\$49.69
GREENOAKSD	0477	RUTTING	High	23	SqFt	0.1	Patching - AC Shallow	AC	1281	30	24	SqFt	\$2.78	\$64.79
GREENVIEWD	0059	L & T CR	Medium	7	Ft	0.0	Crack Sealing - AC	AC	2419	24	7	Ft	\$0.60	\$4.16
GROUSEWAY	0603	RUTTING	High	94	SqFt	0.6	Patching - AC Shallow	AC	567	26	95	SqFt	\$2.78	\$262.39
GROVEST	0299	RUTTING	High	18	SqFt	0.1	Patching - AC Shallow	AC	1699	24	18	SqFt	\$2.78	\$51.14
HAMPTONCT	0720	RUTTING	Medium	11	SqFt	0.1	Patching - AC Shallow	AC	505	24	11	SqFt	\$2.78	\$29.68
HAMPTONCT	0720	L & T CR	Medium	1	Ft	0.0	Crack Sealing - AC	AC	505	24	1	Ft	\$0.60	\$0.79
HAROLDST	0406	L & T CR	High	11	Ft	0.0	Patching - AC Shallow	AC	1685	24	38	SqFt	\$2.78	\$104.27
HAROLDST	0406	L & T CR	Medium	141	Ft	0.4	Crack Sealing - AC	AC	1685	24	141	Ft	\$0.60	\$84.46
HAROLDST	0406	RUTTING	Medium	18	SqFt	0.0	Patching - AC Shallow	AC	1685	24	17	SqFt	\$2.78	\$48.94
HAROLDST	0406	ALLIGATOR CR	Medium	36	SqFt	0.1	Patching - AC Deep	AC	1685	24	64	SqFt	\$5.56	\$354.59
HEATHERDR	0212	ALLIGATOR CR	Medium	0	SqFt	0.0	Patching - AC Deep	AC	1937	22	4	SqFt	\$5.56	\$25.91
HEATHERDR	0212	L & T CR	Medium	113	Ft	0.3	Crack Sealing - AC	AC	1937	22	113	Ft	\$0.60	\$67.76
HEATHERDR	0212	RUTTING	Medium	17	SqFt	0.0	Patching - AC Shallow	AC	1937	22	16	SqFt	\$2.78	\$46.15

## Details of the 2022 Localized Distress Maintenance Plan

BranchID	SectionID	Description	Severity	Distress Qty	Distress Unit	Percent Distress	Work Description	Surface Type	Section Length (Ft)	Section Width (Ft)	Work Qty	Work Unit	Unit Cost	Work Cost
HEATHERDR	0412	L & T CR	High	1	Ft	0.0	Patching - AC Shallow	AC	822	22	4	SqFt	\$2.78	\$10.80
HEISLERCT	0208	L & T CR	Medium	51	Ft	0.8	Crack Sealing - AC	AC	240	26	52	Ft	\$0.60	\$30.82
HELENST	0269	RUTTING	Medium	11	SqFt	0.0	Patching - AC Shallow	AC	1233	28	11	SqFt	\$2.78	\$29.59
HELENST	0269	L & T CR	Medium	1889	Ft	5.5	Crack Sealing - AC	AC	1233	28	1889	Ft	\$0.60	\$1,133.65
HELENST	0269	L & T CR	High	1	Ft	0.0	Patching - AC Shallow	AC	1233	28	2	SqFt	\$2.78	\$7.00
HERITAGEDR	0475	ALLIGATOR CR	Medium	199	SqFt	0.6	Patching - AC Deep	AC	913	36	259	SqFt	\$5.56	\$1,442.17
HERITAGEDR	0475	L & T CR	High	24	Ft	0.1	Patching - AC Shallow	AC	913	36	79	SqFt	\$2.78	\$219.25
HERITAGEDR	0475	ALLIGATOR CR	High	118	SqFt	0.4	Patching - AC Deep	AC	913	36	166	SqFt	\$5.56	\$924.40
HERITAGEDR	0475	RUTTING	High	14	SqFt	0.0	Patching - AC Deep	AC	913	36	14	SqFt	\$5.56	\$80.48
HERITAGEDR	0475	L & T CR	Medium	560	Ft	1.7	Crack Sealing - AC	AC	913	36	560	Ft	\$0.60	\$335.80
HERITAGEDR	0475	RUTTING	Medium	41	SqFt	0.1	Patching - AC Shallow	AC	913	36	41	SqFt	\$2.78	\$115.04
HERITAGEDR	0475	POTHOLE	Low	4	Count	0.0	Patching - AC Deep	AC	913	36	13	SqFt	\$5.56	\$72.51
HICKORYDR	0555	RUTTING	High	9	SqFt	0.0	Patching - AC Shallow	AC	1307	26	10	SqFt	\$2.78	\$26.48
HIGHLANDAV	0289	L & T CR	High	63	Ft	0.2	Patching - AC Shallow	AC	1231	26	206	SqFt	\$2.78	\$570.73
HIGHLANDAV	0289	L & T CR	Medium	206	Ft	0.6	Crack Sealing - AC	AC	1231	26	206	Ft	\$0.60	\$123.56
HIGHLANDAV	0289	ALLIGATOR CR	Medium	52	SqFt	0.2	Patching - AC Deep	AC	1231	26	85	SqFt	\$5.56	\$472.48
HIGHLANDAV	0289	POTHOLE	Low	6	Count	0.0	Patching - AC Deep	AC	1231	26	18	SqFt	\$5.56	\$100.55
HIGHLANDAV	0289	RUTTING	Medium	40	SqFt	0.1	Patching - AC Shallow	AC	1231	26	40	SqFt	\$2.78	\$111.61
HILKERTCT	0574	ALLIGATOR CR	Medium	25	SqFt	0.1	Patching - AC Deep	AC	940	24	50	SqFt	\$5.56	\$273.41
HILKERTCT	0574	RUTTING	Medium	28	SqFt	0.1	Patching - AC Shallow	AC	940	24	28	SqFt	\$2.78	\$77.34
HILKERTCT	0574	L & T CR	Medium	302	Ft	1.3	Crack Sealing - AC	AC	940	24	302	Ft	\$0.60	\$181.06
HILLDR	0036	RUTTING	High	9	SqFt	0.0	Patching - AC Shallow	AC	1069	24	10	SqFt	\$2.78	\$25.87
HILLSIDERD	0297	ALLIGATOR CR	Medium	24	SqFt	0.1	Patching - AC Deep	AC	1336	22	47	SqFt	\$5.56	\$262.78
HILLSIDERD	0297	L & T CR	Medium	1191	Ft	4.1	Crack Sealing - AC	AC	1336	22	1191	Ft	\$0.60	\$714.35
HILLSIDERD	0297	L & T CR	High	24	Ft	0.1	Patching - AC Shallow	AC	1336	22	78	SqFt	\$2.78	\$216.86
HOLLYTREEEL	0202	L & T CR	Medium	129	Ft	0.5	Crack Sealing - AC	AC	952	26	129	Ft	\$0.60	\$77.58
HOLLYTREEEL	0202	RUTTING	Medium	8	SqFt	0.0	Patching - AC Shallow	AC	952	26	9	SqFt	\$2.78	\$23.27
HOLLYTREEEL	0753	L & T CR	Medium	3	Ft	0.2	Crack Sealing - AC	AC	55	26	3	Ft	\$0.60	\$2.03
HONEYSUCKL	0462	RUTTING	Medium	9	SqFt	0.1	Patching - AC Shallow	AC	522	22	9	SqFt	\$2.78	\$24.61
HONEYSUCKL	0462	L & T CR	Medium	81	Ft	0.7	Crack Sealing - AC	AC	522	22	81	Ft	\$0.60	\$48.74
HULLLN	0410	POTHOLE	Low	3	Count	0.0	Patching - AC Deep	AC	300	26	10	SqFt	\$5.56	\$55.53
HULLLN	0410	RUTTING	Medium	22	SqFt	0.3	Patching - AC Shallow	AC	300	26	23	SqFt	\$2.78	\$61.64
HUNTERSTRL	0097	L & T CR	High	27	Ft	0.1	Patching - AC Shallow	AC	1559	24	88	SqFt	\$2.78	\$245.55
HUNTERSTRL	0097	L & T CR	Medium	51	Ft	0.1	Crack Sealing - AC	AC	1559	24	51	Ft	\$0.60	\$30.69
HUNTERSTRL	0097	RUTTING	Medium	9	SqFt	0.0	Patching - AC Shallow	AC	1559	24	9	SqFt	\$2.78	\$25.00
HUNTERSTRL	0097	ALLIGATOR CR	Medium	20	SqFt	0.1	Patching - AC Deep	AC	1559	24	42	SqFt	\$5.56	\$235.33

## Details of the 2022 Localized Distress Maintenance Plan

BranchID	SectionID	Description	Severity	Distress Qty	Distress Unit	Percent Distress	Work Description	Surface Type	Section Length (Ft)	Section Width (Ft)	Work Qty	Work Unit	Unit Cost	Work Cost
HUNTINGTON	0194	POTHOLE	Low	3	Count	0.0	Patching - AC Deep	AC	559	26	10	SqFt	\$5.56	\$51.77
HUNTINGTON	0194	RUTTING	Medium	41	SqFt	0.3	Patching - AC Shallow	AC	559	26	41	SqFt	\$2.78	\$114.92
HUNTLEYRD	0105	RUTTING	High	62	SqFt	0.1	Patching - AC Shallow	AC	3951	24	62	SqFt	\$2.78	\$173.27
HUNTLEYRD	0205	POTHOLE	Low	5	Count	0.0	Patching - AC Deep	AC	2819	24	16	SqFt	\$5.56	\$89.56
HUNTLEYRD	0205	RUTTING	Medium	36	SqFt	0.1	Patching - AC Shallow	AC	2819	24	36	SqFt	\$2.78	\$99.41
HUNTLEYRD	0205	L & T CR	High	22	Ft	0.0	Patching - AC Shallow	AC	2819	24	72	SqFt	\$2.78	\$200.79
HUNTLEYRD	0205	ALLIGATOR CR	Medium	5	SqFt	0.0	Patching - AC Deep	AC	2819	24	18	SqFt	\$5.56	\$100.86
HUNTLEYRD	0205	L & T CR	Medium	761	Ft	1.1	Crack Sealing - AC	AC	2819	24	761	Ft	\$0.60	\$456.39
HUNTLEYRD	0643	RUTTING	High	51	SqFt	1.5	Patching - AC Shallow	AC	138	24	52	SqFt	\$2.78	\$142.35
ILLINOISST	0209	L & T CR	High	61	Ft	0.2	Patching - AC Shallow	AC	1414	24	200	SqFt	\$2.78	\$556.31
ILLINOISST	0209	RUTTING	Medium	9	SqFt	0.0	Patching - AC Shallow	AC	1414	24	9	SqFt	\$2.78	\$25.29
ILLINOISST	0209	L & T CR	Medium	238	Ft	0.7	Crack Sealing - AC	AC	1414	24	238	Ft	\$0.60	\$142.80
ILLINOISST	0209	RUTTING	High	18	SqFt	0.1	Patching - AC Deep	AC	1414	24	18	SqFt	\$5.56	\$101.15
ILLINOISST	0487	RUTTING	High	18	SqFt	0.1	Patching - AC Shallow	AC	659	24	18	SqFt	\$2.78	\$50.84
INDUSTRIAL	0092	RUTTING	High	50	SqFt	0.2	Patching - AC Shallow	AC	1283	24	50	SqFt	\$2.78	\$138.99
IVYLN	0401	RUTTING	High	85	SqFt	0.2	Patching - AC Shallow	AC	1397	28	85	SqFt	\$2.78	\$237.60
JOHNST	0147	RUTTING	High	10	SqFt	0.1	Patching - AC Shallow	AC	828	26	10	SqFt	\$2.78	\$28.39
JUNIPERLN	0348	RUTTING	Medium	10	SqFt	0.1	Patching - AC Shallow	AC	800	24	10	SqFt	\$2.78	\$26.67
KEITHAVE	0009	L & T CR	Medium	256	Ft	0.5	Crack Sealing - AC	AC	1714	28	256	Ft	\$0.60	\$153.73
KEITHAVE	0009	RUTTING	High	28	SqFt	0.1	Patching - AC Deep	AC	1714	28	28	SqFt	\$5.56	\$153.03
KEITHAVE	0009	L & T CR	High	31	Ft	0.1	Patching - AC Shallow	AC	1714	28	102	SqFt	\$2.78	\$283.25
KEITHAVE	0009	RUTTING	Medium	29	SqFt	0.1	Patching - AC Shallow	AC	1714	28	29	SqFt	\$2.78	\$80.80
KELLYLN	0470	L & T CR	Medium	172	Ft	0.3	Crack Sealing - AC	AC	2899	24	172	Ft	\$0.60	\$103.36
KELLYLN	0470	L & T CR	High	1	Ft	0.0	Patching - AC Shallow	AC	2899	24	2	SqFt	\$2.78	\$5.29
KELLYLN	0470	RUTTING	High	9	SqFt	0.0	Patching - AC Deep	AC	2899	24	10	SqFt	\$5.56	\$51.11
KENDALLWOO	0005	L & T CR	High	1	Ft	0.0	Patching - AC Shallow	AC	656	26	3	SqFt	\$2.78	\$8.01
KENDALLWOO	0005	RUTTING	Medium	45	SqFt	0.3	Patching - AC Shallow	AC	656	26	45	SqFt	\$2.78	\$125.52
KENDALLWOO	0005	L & T CR	Medium	194	Ft	1.1	Crack Sealing - AC	AC	656	26	194	Ft	\$0.60	\$116.46
KENNSINGTO	0030	RUTTING	Medium	40	SqFt	0.1	Patching - AC Shallow	AC	2418	26	40	SqFt	\$2.78	\$109.68
KENNSINGTO	0030	L & T CR	Medium	670	Ft	1.1	Crack Sealing - AC	AC	2418	26	670	Ft	\$0.60	\$401.85
KENNSINGTO	0728	L & T CR	Medium	255	Ft	3.2	Crack Sealing - AC	AC	302	26	255	Ft	\$0.60	\$152.91
KIMERCT	0466	L & T CR	High	3	Ft	0.0	Patching - AC Shallow	AC	618	26	11	SqFt	\$2.78	\$29.00
KIMERCT	0466	RUTTING	Medium	48	SqFt	0.3	Patching - AC Shallow	AC	618	26	47	SqFt	\$2.78	\$132.29
KIMERCT	0466	POTHOLE	Low	7	Count	0.0	Patching - AC Deep	AC	618	26	22	SqFt	\$5.56	\$119.18
KIMERCT	0466	L & T CR	Medium	415	Ft	2.6	Crack Sealing - AC	AC	618	26	415	Ft	\$0.60	\$248.79
KIMERCT	0466	RUTTING	High	24	SqFt	0.2	Patching - AC Deep	AC	618	26	24	SqFt	\$5.56	\$132.29

## Details of the 2022 Localized Distress Maintenance Plan

BranchID	SectionID	Description	Severity	Distress Qty	Distress Unit	Percent Distress	Work Description	Surface Type	Section Length (Ft)	Section Width (Ft)	Work Qty	Work Unit	Unit Cost	Work Cost
KINGSPORTC	0506	RUTTING	Medium	68	SqFt	0.3	Patching - AC Shallow	AC	920	26	68	SqFt	\$2.78	\$189.19
KINGSPORTC	0506	L & T CR	High	0	Ft	0.0	Patching - AC Shallow	AC	920	26	1	SqFt	\$2.78	\$1.55
KINGSPORTC	0506	ALLIGATOR CR	Medium	69	SqFt	0.3	Patching - AC Deep	AC	920	26	107	SqFt	\$5.56	\$590.17
KINGSPORTC	0506	L & T CR	Medium	142	Ft	0.6	Crack Sealing - AC	AC	920	26	142	Ft	\$0.60	\$84.99
KINGST	0540	L & T CR	High	30	Ft	0.4	Patching - AC Shallow	AC	334	24	100	SqFt	\$2.78	\$277.15
KINGST	0540	L & T CR	Medium	35	Ft	0.4	Crack Sealing - AC	AC	334	24	35	Ft	\$0.60	\$20.81
KINGST	0540	ALLIGATOR CR	Medium	106	SqFt	1.3	Patching - AC Deep	AC	334	24	152	SqFt	\$5.56	\$841.49
KINGSTONLN	0385	L & T CR	Medium	85	Ft	0.3	Crack Sealing - AC	AC	1126	26	85	Ft	\$0.60	\$50.74
KINGSTONLN	0767	L & T CR	Medium	9	Ft	1.1	Crack Sealing - AC	AC	30	26	9	Ft	\$0.60	\$5.36
KNAACKBLVD	0155	RUTTING	High	14	SqFt	0.0	Patching - AC Shallow	AC	1909	36	14	SqFt	\$2.78	\$38.00
KNOLLWOODDC	0089	L & T CR	Medium	5	Ft	0.0	Crack Sealing - AC	AC	1010	24	5	Ft	\$0.60	\$2.91
KNOLLWOODDC	0089	RUTTING	Medium	9	SqFt	0.0	Patching - AC Shallow	AC	1010	24	10	SqFt	\$2.78	\$25.96
KNOLLWOODDC	0164	L & T CR	High	3	Ft	0.0	Patching - AC Shallow	AC	1639	24	11	SqFt	\$2.78	\$29.02
KNOLLWOODDC	0164	L & T CR	Medium	9	Ft	0.0	Crack Sealing - AC	AC	1639	24	9	Ft	\$0.60	\$5.39
LAGUNARD	0561	L & T CR	Medium	193	Ft	1.1	Crack Sealing - AC	AC	691	26	193	Ft	\$0.60	\$115.61
LAKEAVE	0623	L & T CR	Medium	693	Ft	1.0	Crack Sealing - AC	AC	2443	30	693	Ft	\$0.60	\$415.84
LAKEAVE	0623	ALLIGATOR CR	Medium	72	SqFt	0.1	Patching - AC Deep	AC	2443	30	110	SqFt	\$5.56	\$612.28
LAKEAVE	0623	L & T CR	High	2	Ft	0.0	Patching - AC Shallow	AC	2443	30	9	SqFt	\$2.78	\$22.46
LAKEAVE	0623	POTHOLE	Low	7	Count	0.0	Patching - AC Deep	AC	2443	30	20	SqFt	\$5.56	\$114.12
LAKEAVE	0623	RUTTING	Medium	67	SqFt	0.1	Patching - AC Shallow	AC	2443	30	67	SqFt	\$2.78	\$185.64
LAKECT	0550	POTHOLE	Low	7	Count	0.1	Patching - AC Deep	AC	374	24	20	SqFt	\$5.56	\$110.90
LAKECT	0550	L & T CR	Medium	55	Ft	0.6	Crack Sealing - AC	AC	374	24	55	Ft	\$0.60	\$33.13
LAKESHORED	0143	POTHOLE	Low	12	Count	0.0	Patching - AC Deep	AC	1636	32	34	SqFt	\$5.56	\$194.04
LAKESHORED	0143	L & T CR	High	25	Ft	0.1	Patching - AC Shallow	AC	1636	32	82	SqFt	\$2.78	\$226.36
LAKESHORED	0143	L & T CR	Medium	1283	Ft	2.5	Crack Sealing - AC	AC	1636	32	1283	Ft	\$0.60	\$769.78
LAKESIDEAV	0507	L & T CR	Medium	67	Ft	0.4	Crack Sealing - AC	AC	806	22	67	Ft	\$0.60	\$40.00
LAKEST	0184	RUTTING	Medium	72	SqFt	0.1	Patching - AC Shallow	AC	2472	24	72	SqFt	\$2.78	\$199.93
LAKEST	0184	L & T CR	High	40	Ft	0.1	Patching - AC Shallow	AC	2472	24	132	SqFt	\$2.78	\$367.31
LAKEST	0184	ALLIGATOR CR	Medium	3	SqFt	0.0	Patching - AC Deep	AC	2472	24	15	SqFt	\$5.56	\$82.16
LAKEST	0184	L & T CR	Medium	189	Ft	0.3	Crack Sealing - AC	AC	2472	24	189	Ft	\$0.60	\$113.38
LAKEST	0313	RUTTING	Medium	16	SqFt	0.1	Patching - AC Shallow	AC	1451	22	16	SqFt	\$2.78	\$44.21
LAKEST	0313	L & T CR	Medium	561	Ft	1.8	Crack Sealing - AC	AC	1451	22	561	Ft	\$0.60	\$336.51
LAKEST	0313	POTHOLE	Low	5	Count	0.0	Patching - AC Deep	AC	1451	22	15	SqFt	\$5.56	\$85.72
LAKEST	0313	L & T CR	High	1	Ft	0.0	Patching - AC Shallow	AC	1451	22	2	SqFt	\$2.78	\$6.56
LAKEST	0313	RUTTING	High	24	SqFt	0.1	Patching - AC Deep	AC	1451	22	25	SqFt	\$5.56	\$136.00
LAKEST	0313	ALLIGATOR CR	Medium	59	SqFt	0.2	Patching - AC Deep	AC	1451	22	94	SqFt	\$5.56	\$522.30

## Details of the 2022 Localized Distress Maintenance Plan

BranchID	SectionID	Description	Severity	Distress Qty	Distress Unit	Percent Distress	Work Description	Surface Type	Section Length (Ft)	Section Width (Ft)	Work Qty	Work Unit	Unit Cost	Work Cost
LAKWOODAV	0435	RUTTING	Medium	16	SqFt	0.1	Patching - AC Shallow	AC	1000	22	16	SqFt	\$2.78	\$45.74
LANCASTERD	0237	L & T CR	Medium	7	Ft	0.0	Crack Sealing - AC	AC	1163	26	7	Ft	\$0.60	\$4.19
LEEDR	0493	RUTTING	High	11	SqFt	0.0	Patching - AC Shallow	AC	1493	30	11	SqFt	\$2.78	\$31.14
LEONARDPKW	0190	L & T CR	Medium	33	Ft	0.1	Crack Sealing - AC	AC	1137	26	33	Ft	\$0.60	\$19.96
LIBERTYRD	0244	RUTTING	High	40	SqFt	0.1	Patching - AC Shallow	AC	2200	36	40	SqFt	\$2.78	\$109.84
LILACDR	0018	RUTTING	Medium	18	SqFt	0.1	Patching - AC Shallow	AC	1536	24	18	SqFt	\$2.78	\$51.24
LILACDR	0018	L & T CR	Medium	20	Ft	0.1	Crack Sealing - AC	AC	1536	24	20	Ft	\$0.60	\$12.15
LILACDR	0018	L & T CR	High	2	Ft	0.0	Patching - AC Shallow	AC	1536	24	8	SqFt	\$2.78	\$21.20
LILLAVE	0464	L & T CR	Medium	15	Ft	0.1	Crack Sealing - AC	AC	730	22	15	Ft	\$0.60	\$8.80
LILLAVE	0464	ALLIGATOR CR	High	1	SqFt	0.0	Patching - AC Deep	AC	730	22	10	SqFt	\$5.56	\$53.94
LILLAVE	0464	RUTTING	Medium	9	SqFt	0.1	Patching - AC Shallow	AC	730	22	9	SqFt	\$2.78	\$24.28
LINCOLNPKW	0571	RUTTING	Medium	73	SqFt	0.2	Patching - AC Shallow	AC	1273	24	73	SqFt	\$2.78	\$202.79
LINCOLNPKW	0571	L & T CR	High	146	Ft	0.5	Patching - AC Shallow	AC	1273	24	480	SqFt	\$2.78	\$1,335.90
LINCOLNPKW	0571	L & T CR	Medium	1099	Ft	3.6	Crack Sealing - AC	AC	1273	24	1099	Ft	\$0.60	\$659.35
LINCOLNPKW	0571	POTHOLE	Low	3	Count	0.0	Patching - AC Deep	AC	1273	24	9	SqFt	\$5.56	\$45.66
LINCOLNPKW	0583	L & T CR	Medium	16	Ft	0.1	Crack Sealing - AC	AC	1312	26	16	Ft	\$0.60	\$9.54
LINCOLNSHI	0094	L & T CR	Medium	58	Ft	0.2	Crack Sealing - AC	AC	1210	22	58	Ft	\$0.60	\$35.08
LINCOLNSHI	0094	ALLIGATOR CR	Medium	211	SqFt	0.8	Patching - AC Deep	AC	1210	22	273	SqFt	\$5.56	\$1,518.25
LOCHWOODDR	0031	L & T CR	High	0	Ft	0.0	Patching - AC Shallow	AC	622	24	1	SqFt	\$2.78	\$3.78
LOCHWOODDR	0031	L & T CR	Medium	193	Ft	1.3	Crack Sealing - AC	AC	622	24	193	Ft	\$0.60	\$115.80
LOCHWOODDR	0031	RUTTING	Medium	18	SqFt	0.1	Patching - AC Shallow	AC	622	24	18	SqFt	\$2.78	\$51.19
LOCHWOODDR	0031	POTHOLE	Low	3	Count	0.0	Patching - AC Deep	AC	622	24	9	SqFt	\$5.56	\$46.12
LOCHWOODDR	0565	RUTTING	High	10	SqFt	0.0	Patching - AC Shallow	AC	1142	26	10	SqFt	\$2.78	\$27.77
LOMBARDDR	0432	L & T CR	Medium	2	Ft	0.0	Crack Sealing - AC	AC	336	26	2	Ft	\$0.60	\$1.41
LOMBARDDR	0432	L & T CR	High	6	Ft	0.1	Patching - AC Shallow	AC	336	26	19	SqFt	\$2.78	\$53.37
LOUAVE	0271	L & T CR	Medium	50	Ft	0.2	Crack Sealing - AC	AC	1000	22	50	Ft	\$0.60	\$29.76
LUCASRD	0637	ALLIGATOR CR	Medium	8	SqFt	0.1	Patching - AC Deep	AC	371	22	23	SqFt	\$5.56	\$128.55
LUCASRD	0637	L & T CR	Medium	129	Ft	1.6	Crack Sealing - AC	AC	371	22	129	Ft	\$0.60	\$77.53
LUCASRD	0637	L & T CR	High	16	Ft	0.2	Patching - AC Shallow	AC	371	22	52	SqFt	\$2.78	\$145.07
LUCASRD	0638	L & T CR	High	54	Ft	0.2	Patching - AC Shallow	AC	1317	22	177	SqFt	\$2.78	\$491.18
LUCASRD	0638	L & T CR	Medium	670	Ft	2.3	Crack Sealing - AC	AC	1317	22	670	Ft	\$0.60	\$402.09
LUCASRD	0638	RUTTING	Medium	16	SqFt	0.1	Patching - AC Shallow	AC	1317	22	16	SqFt	\$2.78	\$45.84
LUCASRD	0639	L & T CR	Medium	147	Ft	0.5	Crack Sealing - AC	AC	1315	22	147	Ft	\$0.60	\$88.23
LUCASRD	0639	L & T CR	High	87	Ft	0.3	Patching - AC Shallow	AC	1315	22	286	SqFt	\$2.78	\$795.77
MANCHESTER	0210	L & T CR	Medium	4	Ft	0.0	Crack Sealing - AC	AC	1126	24	4	Ft	\$0.60	\$2.28
MANCHESTER	0210	L & T CR	High	2	Ft	0.0	Patching - AC Shallow	AC	1126	24	6	SqFt	\$2.78	\$16.54

## Details of the 2022 Localized Distress Maintenance Plan

BranchID	SectionID	Description	Severity	Distress Qty	Distress Unit	Percent Distress	Work Description	Surface Type	Section Length (Ft)	Section Width (Ft)	Work Qty	Work Unit	Unit Cost	Work Cost
MANORRD	0474	L & T CR	Medium	258	Ft	3.0	Crack Sealing - AC	AC	358	24	258	Ft	\$0.60	\$154.98
MANORRD	0474	ALLIGATOR CR	Medium	27	SqFt	0.3	Patching - AC Deep	AC	358	24	52	SqFt	\$5.56	\$287.21
MANORRD	0474	RUTTING	Medium	9	SqFt	0.1	Patching - AC Shallow	AC	358	24	10	SqFt	\$2.78	\$26.02
MANORRD	0474	L & T CR	High	4	Ft	0.0	Patching - AC Shallow	AC	358	24	12	SqFt	\$2.78	\$32.56
MANORRD	0474	POTHOLE	Low	3	Count	0.0	Patching - AC Deep	AC	358	24	9	SqFt	\$5.56	\$46.88
MAPLEST	0648	L & T CR	High	10	Ft	0.0	Patching - AC Shallow	AC	1062	24	33	SqFt	\$2.78	\$93.47
MAPLEST	0648	L & T CR	Medium	21	Ft	0.1	Crack Sealing - AC	AC	1062	24	21	Ft	\$0.60	\$12.60
MARHILCT	0203	L & T CR	Medium	59	Ft	0.4	Crack Sealing - AC	AC	360	45	59	Ft	\$0.60	\$35.17
MARIANPKWY	0040	L & T CR	Medium	112	Ft	0.3	Crack Sealing - AC	AC	1270	28	112	Ft	\$0.60	\$67.03
MARIANPKWY	0040	RUTTING	Medium	11	SqFt	0.0	Patching - AC Shallow	AC	1270	28	11	SqFt	\$2.78	\$29.98
MARYLN	0067	RUTTING	High	18	SqFt	0.0	Patching - AC Deep	AC	2045	24	18	SqFt	\$5.56	\$100.96
MARYLN	0067	L & T CR	High	25	Ft	0.1	Patching - AC Shallow	AC	2045	24	81	SqFt	\$2.78	\$225.56
MARYLN	0067	RUTTING	Medium	9	SqFt	0.0	Patching - AC Shallow	AC	2045	24	9	SqFt	\$2.78	\$25.24
MARYLN	0067	L & T CR	Medium	89	Ft	0.2	Crack Sealing - AC	AC	2045	24	89	Ft	\$0.60	\$53.38
MARYLN	0123	L & T CR	Medium	123	Ft	2.6	Crack Sealing - AC	AC	196	24	123	Ft	\$0.60	\$74.03
MCCULLOMST	0331	L & T CR	Medium	33	Ft	0.2	Crack Sealing - AC	AC	669	24	32	Ft	\$0.60	\$19.51
MCHENRYAVE	0088	L & T CR	Medium	5988	Ft	1.3	Crack Sealing - AC	AC	9703	48	5988	Ft	\$0.60	\$3,592.57
MCHENRYAVE	0088	POTHOLE	Low	31	Count	0.0	Patching - AC Deep	AC	9703	48	93	SqFt	\$5.56	\$512.92
MCHENRYAVE	0088	RUTTING	High	86	SqFt	0.0	Patching - AC Deep	AC	9703	48	86	SqFt	\$5.56	\$476.77
MCHENRYAVE	0088	RUTTING	Medium	230	SqFt	0.1	Patching - AC Shallow	AC	9703	48	230	SqFt	\$2.78	\$639.32
MCHENRYAVE	0088	L & T CR	High	421	Ft	0.1	Patching - AC Shallow	AC	9703	48	1383	SqFt	\$2.78	\$3,844.02
MCHENRYAVE	0088	ALLIGATOR CR	Medium	351	SqFt	0.1	Patching - AC Deep	AC	9703	48	431	SqFt	\$5.56	\$2,393.58
MCHENRYAVE	0140	RUTTING	Medium	25	SqFt	0.0	Patching - AC Shallow	AC	4225	34	26	SqFt	\$2.78	\$70.36
MCHENRYAVE	0140	RUTTING	High	101	SqFt	0.1	Patching - AC Deep	AC	4225	34	101	SqFt	\$5.56	\$563.13
MCHENRYAVE	0140	L & T CR	High	77	Ft	0.1	Patching - AC Shallow	AC	4225	34	253	SqFt	\$2.78	\$703.31
MCHENRYAVE	0140	ALLIGATOR CR	Medium	15	SqFt	0.0	Patching - AC Deep	AC	4225	34	36	SqFt	\$5.56	\$195.93
MCHENRYAVE	0140	POTHOLE	Low	11	Count	0.0	Patching - AC Deep	AC	4225	34	34	SqFt	\$5.56	\$190.18
MCHENRYAVE	0140	L & T CR	Medium	315	Ft	0.2	Crack Sealing - AC	AC	4225	34	315	Ft	\$0.60	\$189.13
MELROSELN	0060	L & T CR	High	0	Ft	0.0	Patching - AC Shallow	AC	1090	22	1	SqFt	\$2.78	\$1.83
MELROSELN	0060	L & T CR	Medium	8	Ft	0.0	Crack Sealing - AC	AC	1090	22	8	Ft	\$0.60	\$4.99
MERIDIANST	0471	L & T CR	Medium	6	Ft	0.0	Crack Sealing - AC	AC	1050	22	6	Ft	\$0.60	\$3.59
MIDLANEDR	0139	ALLIGATOR CR	Medium	72	SqFt	0.1	Patching - AC Deep	AC	2871	24	110	SqFt	\$5.56	\$609.50
MIDLANEDR	0139	L & T CR	Medium	1914	Ft	2.8	Crack Sealing - AC	AC	2871	24	1914	Ft	\$0.60	\$1,148.21
MIDLANEDR	0139	L & T CR	High	5	Ft	0.0	Patching - AC Shallow	AC	2871	24	16	SqFt	\$2.78	\$44.26
MILLERRD	0150	RUTTING	Medium	179	SqFt	0.1	Patching - AC Shallow	AC	3865	40	179	SqFt	\$2.78	\$496.94
MILLERRD	0150	ALLIGATOR CR	Medium	80	SqFt	0.1	Patching - AC Deep	AC	3865	40	119	SqFt	\$5.56	\$667.09

## Details of the 2022 Localized Distress Maintenance Plan

BranchID	SectionID	Description	Severity	Distress Qty	Distress Unit	Percent Distress	Work Description	Surface Type	Section Length (Ft)	Section Width (Ft)	Work Qty	Work Unit	Unit Cost	Work Cost
MILLERRD	0150	L & T CR	High	35	Ft	0.0	Patching - AC Shallow	AC	3865	40	115	SqFt	\$2.78	\$321.10
MILLERRD	0150	L & T CR	Medium	1631	Ft	1.1	Crack Sealing - AC	AC	3865	40	1631	Ft	\$0.60	\$978.83
MILLERRD	0150	POTHOLE	Low	13	Count	0.0	Patching - AC Deep	AC	3865	40	40	SqFt	\$5.56	\$223.85
MILLERRD	0267	ALLIGATOR CR	Medium	1	SqFt	0.0	Patching - AC Deep	AC	3194	40	9	SqFt	\$5.56	\$47.57
MILLERRD	0267	POTHOLE	Low	4	Count	0.0	Patching - AC Deep	AC	3194	40	13	SqFt	\$5.56	\$74.47
MILLERRD	0267	L & T CR	Medium	2296	Ft	1.8	Crack Sealing - AC	AC	3194	40	2296	Ft	\$0.60	\$1,377.38
MILLERRD	0267	RUTTING	Medium	30	SqFt	0.0	Patching - AC Shallow	AC	3194	40	30	SqFt	\$2.78	\$82.66
MILLERRD	0267	L & T CR	High	70	Ft	0.1	Patching - AC Shallow	AC	3194	40	229	SqFt	\$2.78	\$637.67
MINNIEST	0261	RUTTING	Medium	10	SqFt	0.1	Patching - AC Shallow	AC	726	24	10	SqFt	\$2.78	\$28.02
MINNIEST	0261	L & T CR	High	3	Ft	0.0	Patching - AC Shallow	AC	726	24	9	SqFt	\$2.78	\$23.19
MINNIEST	0261	L & T CR	Medium	243	Ft	1.4	Crack Sealing - AC	AC	726	24	243	Ft	\$0.60	\$145.86
MIRAST	0448	RUTTING	Medium	9	SqFt	0.0	Patching - AC Shallow	AC	1345	24	10	SqFt	\$2.78	\$25.93
MISTWOODLN	0048	RUTTING	High	9	SqFt	0.0	Patching - AC Shallow	AC	879	28	10	SqFt	\$2.78	\$25.87
MITCHELLCT	0440	L & T CR	Medium	201	Ft	1.0	Crack Sealing - AC	AC	565	34	200	Ft	\$0.60	\$120.35
MITCHELLCT	0606	L & T CR	Medium	304	Ft	4.1	Crack Sealing - AC	AC	219	34	304	Ft	\$0.60	\$182.23
MITCHELLCT	0606	ALLIGATOR CR	Medium	10	SqFt	0.1	Patching - AC Deep	AC	219	34	26	SqFt	\$5.56	\$144.77
MOORLANDLN	0120	RUTTING	High	53	SqFt	0.2	Patching - AC Shallow	AC	1155	24	53	SqFt	\$2.78	\$146.57
MORGANST	0597	RUTTING	High	49	SqFt	0.3	Patching - AC Deep	AC	658	24	48	SqFt	\$5.56	\$270.88
MORGANST	0597	POTHOLE	Low	26	Count	0.2	Patching - AC Deep	AC	658	24	79	SqFt	\$5.56	\$439.26
MORGANST	0597	RUTTING	Medium	49	SqFt	0.3	Patching - AC Shallow	AC	658	24	48	SqFt	\$2.78	\$135.44
MORGANST	0597	L & T CR	Medium	224	Ft	1.4	Crack Sealing - AC	AC	658	24	224	Ft	\$0.60	\$134.59
MORGANST	0597	L & T CR	High	34	Ft	0.2	Patching - AC Shallow	AC	658	24	112	SqFt	\$2.78	\$311.98
MUNSHAWLN	0029	L & T CR	Medium	374	Ft	0.9	Crack Sealing - AC	AC	1117	36	374	Ft	\$0.60	\$224.20
MUNSHAWLN	0029	L & T CR	High	7	Ft	0.0	Patching - AC Shallow	AC	1117	36	22	SqFt	\$2.78	\$61.15
N/A	0620	L & T CR	Medium	289	Ft	3.4	Crack Sealing - AC	AC	235	36	289	Ft	\$0.60	\$173.16
N/A	0620	L & T CR	High	18	Ft	0.2	Patching - AC Shallow	AC	235	36	59	SqFt	\$2.78	\$165.64
N/A	0628	L & T CR	Medium	208	Ft	2.5	Crack Sealing - AC	AC	319	26	208	Ft	\$0.60	\$124.56
N/A	0628	RUTTING	High	13	SqFt	0.2	Patching - AC Deep	AC	319	26	13	SqFt	\$5.56	\$71.01
NARRAGANSE	0713	ALLIGATOR CR	Medium	98	SqFt	0.8	Patching - AC Deep	AC	544	24	141	SqFt	\$5.56	\$785.58
NARRAGANSE	0713	L & T CR	High	71	Ft	0.5	Patching - AC Shallow	AC	544	24	233	SqFt	\$2.78	\$646.43
NARRAGANSE	0713	L & T CR	Medium	110	Ft	0.8	Crack Sealing - AC	AC	544	24	110	Ft	\$0.60	\$66.02
NARRAGANSE	0713	RUTTING	High	53	SqFt	0.4	Patching - AC Deep	AC	544	24	53	SqFt	\$5.56	\$292.30
NASHRD	0054	ALLIGATOR CR	Medium	100	SqFt	0.1	Patching - AC Deep	AC	2959	34	144	SqFt	\$5.56	\$804.54
NASHRD	0054	L & T CR	Medium	175	Ft	0.2	Crack Sealing - AC	AC	2959	34	175	Ft	\$0.60	\$104.83
NASHRD	0054	L & T CR	High	2	Ft	0.0	Patching - AC Shallow	AC	2959	34	6	SqFt	\$2.78	\$16.76
NASHRD	0629	RUTTING	Medium	15	SqFt	0.2	Patching - AC Shallow	AC	280	34	15	SqFt	\$2.78	\$40.76

## Details of the 2022 Localized Distress Maintenance Plan

BranchID	SectionID	Description	Severity	Distress Qty	Distress Unit	Percent Distress	Work Description	Surface Type	Section Length (Ft)	Section Width (Ft)	Work Qty	Work Unit	Unit Cost	Work Cost
NASHRD	0629	L & T CR	Medium	20	Ft	0.2	Crack Sealing - AC	AC	280	34	20	Ft	\$0.60	\$11.92
NASHRD	0629	L & T CR	High	34	Ft	0.4	Patching - AC Shallow	AC	280	34	112	SqFt	\$2.78	\$312.46
NASHRD	0629	RUTTING	High	15	SqFt	0.2	Patching - AC Deep	AC	280	34	15	SqFt	\$5.56	\$81.53
NASHUACT	0719	L & T CR	Medium	129	Ft	2.5	Crack Sealing - AC	AC	216	24	129	Ft	\$0.60	\$77.33
NASHUACT	0719	L & T CR	High	5	Ft	0.1	Patching - AC Shallow	AC	216	24	15	SqFt	\$2.78	\$43.30
NCAROLINES	0280	L & T CR	Medium	169	Ft	0.5	Crack Sealing - AC	AC	1307	26	169	Ft	\$0.60	\$101.33
NCAROLINES	0280	RUTTING	High	56	SqFt	0.2	Patching - AC Deep	AC	1307	26	56	SqFt	\$5.56	\$309.32
NCAROLINES	0280	L & T CR	High	109	Ft	0.3	Patching - AC Shallow	AC	1307	26	360	SqFt	\$2.78	\$998.15
NCAROLINES	0280	RUTTING	Medium	134	SqFt	0.4	Patching - AC Shallow	AC	1307	26	135	SqFt	\$2.78	\$372.73
NDOLEAVE	0329	L & T CR	Medium	114	Ft	0.2	Crack Sealing - AC	AC	2064	30	114	Ft	\$0.60	\$68.13
NDOLEAVE	0329	ALLIGATOR CR	Medium	103	SqFt	0.2	Patching - AC Deep	AC	2064	30	149	SqFt	\$5.56	\$824.21
NDOLEAVE	0329	RUTTING	Medium	57	SqFt	0.1	Patching - AC Shallow	AC	2064	30	57	SqFt	\$2.78	\$157.73
NDOLEAVE	0329	RUTTING	High	34	SqFt	0.1	Patching - AC Deep	AC	2064	30	34	SqFt	\$5.56	\$189.16
NDOLEAVE	0329	L & T CR	High	16	Ft	0.0	Patching - AC Shallow	AC	2064	30	53	SqFt	\$2.78	\$145.68
NEWBURYDR	0605	L & T CR	Medium	79	Ft	0.7	Crack Sealing - AC	AC	510	24	79	Ft	\$0.60	\$47.38
NEWCASTLEC	0066	RUTTING	Medium	18	SqFt	0.1	Patching - AC Shallow	AC	1055	24	18	SqFt	\$2.78	\$50.10
NMAINST	0128	RUTTING	High	54	SqFt	0.1	Patching - AC Shallow	AC	1717	24	55	SqFt	\$2.78	\$151.42
NMAINST	0363	L & T CR	High	15	Ft	0.1	Patching - AC Shallow	AC	663	24	50	SqFt	\$2.78	\$137.26
NMAINST	0363	L & T CR	Medium	225	Ft	1.4	Crack Sealing - AC	AC	663	24	225	Ft	\$0.60	\$135.19
NMAINST	0460	RUTTING	High	14	SqFt	0.0	Patching - AC Shallow	AC	914	36	14	SqFt	\$2.78	\$38.45
NOAKST	0056	L & T CR	Medium	8	Ft	0.0	Crack Sealing - AC	AC	1310	30	8	Ft	\$0.60	\$4.77
NOAKST	0451	RUTTING	High	34	SqFt	0.1	Patching - AC Shallow	AC	1658	30	33	SqFt	\$2.78	\$93.58
NOAKST	0626	POTHOLE	Low	10	Count	0.0	Patching - AC Deep	AC	1471	30	30	SqFt	\$5.56	\$168.05
NOAKST	0626	RUTTING	Medium	109	SqFt	0.3	Patching - AC Shallow	AC	1471	30	109	SqFt	\$2.78	\$302.11
NOAKST	0626	L & T CR	High	326	Ft	0.7	Patching - AC Shallow	AC	1471	30	1071	SqFt	\$2.78	\$2,977.23
NOAKST	0626	ALLIGATOR CR	Medium	406	SqFt	0.9	Patching - AC Deep	AC	1471	30	491	SqFt	\$5.56	\$2,731.84
NOAKST	0626	L & T CR	Medium	1354	Ft	3.1	Crack Sealing - AC	AC	1471	30	1354	Ft	\$0.60	\$812.51
NOAKST	0627	RUTTING	High	81	SqFt	0.2	Patching - AC Deep	AC	1436	30	81	SqFt	\$5.56	\$449.70
NOAKST	0627	L & T CR	High	123	Ft	0.3	Patching - AC Shallow	AC	1436	30	405	SqFt	\$2.78	\$1,125.22
NOAKST	0627	RUTTING	Medium	35	SqFt	0.1	Patching - AC Shallow	AC	1436	30	34	SqFt	\$2.78	\$96.32
NOAKST	0627	ALLIGATOR CR	Medium	91	SqFt	0.2	Patching - AC Deep	AC	1436	30	133	SqFt	\$5.56	\$743.61
NOAKST	0627	L & T CR	Medium	385	Ft	0.9	Crack Sealing - AC	AC	1436	30	386	Ft	\$0.60	\$231.26
NORTHAVE	0077	L & T CR	High	7	Ft	0.0	Patching - AC Shallow	AC	1218	26	24	SqFt	\$2.78	\$64.99
NORTHAVE	0077	ALLIGATOR CR	High	1	SqFt	0.0	Patching - AC Deep	AC	1218	26	10	SqFt	\$5.56	\$51.39
NORTHAVE	0077	L & T CR	Medium	243	Ft	0.8	Crack Sealing - AC	AC	1218	26	243	Ft	\$0.60	\$145.76
NORTHAVE	0077	POTHOLE	Low	9	Count	0.0	Patching - AC Deep	AC	1218	26	27	SqFt	\$5.56	\$149.20

## Details of the 2022 Localized Distress Maintenance Plan

BranchID	SectionID	Description	Severity	Distress Qty	Distress Unit	Percent Distress	Work Description	Surface Type	Section Length (Ft)	Section Width (Ft)	Work Qty	Work Unit	Unit Cost	Work Cost
NORTHHAVE	0077	RUTTING	Medium	38	SqFt	0.1	Patching - AC Shallow	AC	1218	26	39	SqFt	\$2.78	\$106.51
NORTHHAVE	0077	ALLIGATOR CR	Medium	42	SqFt	0.1	Patching - AC Deep	AC	1218	26	72	SqFt	\$5.56	\$399.56
NORTHSHERE	0032	POTHOLE	Low	5	Count	0.0	Patching - AC Deep	AC	4145	24	16	SqFt	\$5.56	\$89.50
NORTHSHERE	0032	L & T CR	Medium	417	Ft	0.4	Crack Sealing - AC	AC	4145	24	417	Ft	\$0.60	\$250.28
NORTHSHERE	0032	L & T CR	High	6	Ft	0.0	Patching - AC Shallow	AC	4145	24	20	SqFt	\$2.78	\$57.50
NORTHSHERE	0032	ALLIGATOR CR	Medium	159	SqFt	0.2	Patching - AC Deep	AC	4145	24	214	SqFt	\$5.56	\$1,191.32
NORTHSHERE	0032	RUTTING	Medium	27	SqFt	0.0	Patching - AC Shallow	AC	4145	24	27	SqFt	\$2.78	\$74.51
NORTHSHERE	0249	L & T CR	High	52	Ft	0.1	Patching - AC Shallow	AC	2574	26	170	SqFt	\$2.78	\$473.45
NORTHSHERE	0249	L & T CR	Medium	89	Ft	0.1	Crack Sealing - AC	AC	2574	26	89	Ft	\$0.60	\$53.45
NORTHSHERE	0591	POTHOLE	Low	3	Count	0.0	Patching - AC Deep	AC	390	22	9	SqFt	\$5.56	\$49.68
NORWICHCT	0716	RUTTING	High	10	SqFt	0.3	Patching - AC Deep	AC	160	24	10	SqFt	\$5.56	\$56.71
NORWICHCT	0717	L & T CR	High	105	Ft	0.6	Patching - AC Shallow	AC	730	24	343	SqFt	\$2.78	\$954.14
NORWICHCT	0717	RUTTING	High	80	SqFt	0.5	Patching - AC Deep	AC	730	24	80	SqFt	\$5.56	\$445.01
NORWICHCT	0717	ALLIGATOR CR	High	202	SqFt	1.2	Patching - AC Deep	AC	730	24	264	SqFt	\$5.56	\$1,465.45
NORWICHCT	0717	L & T CR	Medium	47	Ft	0.3	Crack Sealing - AC	AC	730	24	47	Ft	\$0.60	\$28.25
NORWICHCT	0717	RUTTING	Medium	10	SqFt	0.1	Patching - AC Shallow	AC	730	24	10	SqFt	\$2.78	\$27.31
NOTTINGHAM	0238	L & T CR	High	1	Ft	0.0	Patching - AC Shallow	AC	3283	36	2	SqFt	\$2.78	\$5.95
NOTTINGHAM	0238	ALLIGATOR CR	Medium	4	SqFt	0.0	Patching - AC Deep	AC	3283	36	15	SqFt	\$5.56	\$85.05
NOTTINGHAM	0238	L & T CR	Medium	67	Ft	0.1	Crack Sealing - AC	AC	3283	36	67	Ft	\$0.60	\$40.37
NOTTINGHAM	0426	L & T CR	Medium	195	Ft	4.0	Crack Sealing - AC	AC	187	26	195	Ft	\$0.60	\$116.85
NOTTINGHAM	0426	L & T CR	High	2	Ft	0.1	Patching - AC Shallow	AC	187	26	8	SqFt	\$2.78	\$21.96
NOTTINGHAM	0426	RUTTING	Medium	8	SqFt	0.2	Patching - AC Shallow	AC	187	26	8	SqFt	\$2.78	\$20.83
NOTTINGHAM	0515	L & T CR	Medium	8	Ft	0.0	Crack Sealing - AC	AC	1240	38	8	Ft	\$0.60	\$4.87
NUNDATRL	0486	RUTTING	High	28	SqFt	0.1	Patching - AC Shallow	AC	1346	24	28	SqFt	\$2.78	\$77.86
NWALKUPAVE	0149	RUTTING	High	162	SqFt	0.2	Patching - AC Deep	AC	1940	36	161	SqFt	\$5.56	\$898.45
NWALKUPAVE	0149	L & T CR	High	262	Ft	0.4	Patching - AC Shallow	AC	1940	36	858	SqFt	\$2.78	\$2,385.48
NWALKUPAVE	0149	ALLIGATOR CR	High	128	SqFt	0.2	Patching - AC Deep	AC	1940	36	178	SqFt	\$5.56	\$989.24
NWALKUPAVE	0149	POTHOLE	Low	12	Count	0.0	Patching - AC Deep	AC	1940	36	37	SqFt	\$5.56	\$202.25
NWALKUPAVE	0149	L & T CR	Medium	801	Ft	1.2	Crack Sealing - AC	AC	1940	36	801	Ft	\$0.60	\$480.75
NWALKUPAVE	0149	ALLIGATOR CR	Medium	256	SqFt	0.4	Patching - AC Deep	AC	1940	36	324	SqFt	\$5.56	\$1,801.17
NWALKUPAVE	0149	RUTTING	Medium	117	SqFt	0.2	Patching - AC Shallow	AC	1940	36	117	SqFt	\$2.78	\$326.19
NWALKUPAVE	0374	L & T CR	Medium	202	Ft	0.5	Crack Sealing - AC	AC	653	60	201	Ft	\$0.60	\$120.96
NWALKUPAVE	0374	L & T CR	High	3	Ft	0.0	Patching - AC Shallow	AC	653	60	9	SqFt	\$2.78	\$24.56
NWILLIAMSS	0291	RUTTING	High	16	SqFt	0.0	Patching - AC Shallow	AC	1001	40	16	SqFt	\$2.78	\$43.80
OAKCT	0508	POTHOLE	Low	3	Count	0.0	Patching - AC Deep	AC	881	24	9	SqFt	\$5.56	\$46.64
OAKCT	0508	RUTTING	Medium	112	SqFt	0.5	Patching - AC Shallow	AC	881	24	112	SqFt	\$2.78	\$310.80

## Details of the 2022 Localized Distress Maintenance Plan

BranchID	SectionID	Description	Severity	Distress Qty	Distress Unit	Percent Distress	Work Description	Surface Type	Section Length (Ft)	Section Width (Ft)	Work Qty	Work Unit	Unit Cost	Work Cost
OAKCT	0508	L & T CR	Medium	28	Ft	0.1	Crack Sealing - AC	AC	881	24	28	Ft	\$0.60	\$17.01
OAKCT	0508	RUTTING	High	9	SqFt	0.0	Patching - AC Deep	AC	881	24	10	SqFt	\$5.56	\$51.77
OAKCT	0508	L & T CR	High	1	Ft	0.0	Patching - AC Shallow	AC	881	24	4	SqFt	\$2.78	\$13.01
OAKHOLLOWC	0615	L & T CR	High	2	Ft	0.0	Patching - AC Shallow	AC	210	36	6	SqFt	\$2.78	\$16.89
OAKHOLLOWC	0615	L & T CR	Medium	7	Ft	0.1	Crack Sealing - AC	AC	210	36	7	Ft	\$0.60	\$4.17
OAKHOLLOWR	0243	L & T CR	High	6	Ft	0.0	Patching - AC Shallow	AC	1925	36	18	SqFt	\$2.78	\$51.07
OAKHOLLOWR	0243	L & T CR	Medium	295	Ft	0.4	Crack Sealing - AC	AC	1925	36	295	Ft	\$0.60	\$176.83
OAKHOLLOWR	0768	L & T CR	Medium	205	Ft	2.9	Crack Sealing - AC	AC	271	26	205	Ft	\$0.60	\$123.00
OAKHOLLOWR	0768	RUTTING	Medium	9	SqFt	0.1	Patching - AC Shallow	AC	271	26	9	SqFt	\$2.78	\$24.15
OAKHOLLOWR	0768	L & T CR	High	6	Ft	0.1	Patching - AC Shallow	AC	271	26	22	SqFt	\$2.78	\$59.02
OAKVALLEYC	0373	L & T CR	Medium	5	Ft	0.1	Crack Sealing - AC	AC	380	24	5	Ft	\$0.60	\$2.88
OAKVALLEYD	0057	L & T CR	Medium	38	Ft	0.1	Crack Sealing - AC	AC	1353	24	38	Ft	\$0.60	\$22.99
OAKVALLEYD	0057	L & T CR	High	1	Ft	0.0	Patching - AC Shallow	AC	1353	24	2	SqFt	\$2.78	\$5.06
OFFICIALRD	0582	L & T CR	Medium	19	Ft	0.1	Crack Sealing - AC	AC	1136	22	19	Ft	\$0.60	\$11.14
OFFICIALRD	0582	L & T CR	High	0	Ft	0.0	Patching - AC Shallow	AC	1136	22	1	SqFt	\$2.78	\$3.28
OLDWESTBUR	0178	L & T CR	Medium	0	Ft	0.0	Crack Sealing - AC	AC	1718	24	0	Ft	\$0.60	\$0.07
OLDWESTBUR	0379	L & T CR	Medium	26	Ft	0.2	Crack Sealing - AC	AC	485	24	26	Ft	\$0.60	\$15.61
ORCHARDROW	0592	L & T CR	Medium	104	Ft	1.1	Crack Sealing - AC	AC	358	26	104	Ft	\$0.60	\$62.11
ORCHARDROW	0592	ALLIGATOR CR	Medium	4	SqFt	0.0	Patching - AC Deep	AC	358	26	16	SqFt	\$5.56	\$88.96
ORCHARDROW	0592	RUTTING	Medium	22	SqFt	0.2	Patching - AC Shallow	AC	358	26	22	SqFt	\$2.78	\$59.84
ORCHARDROW	0592	L & T CR	High	12	Ft	0.1	Patching - AC Shallow	AC	358	26	40	SqFt	\$2.78	\$111.73
OXFORDLN	0286	RUTTING	Medium	17	SqFt	0.1	Patching - AC Shallow	AC	1191	22	17	SqFt	\$2.78	\$48.13
OXFORDLN	0286	L & T CR	Medium	98	Ft	0.4	Crack Sealing - AC	AC	1191	22	97	Ft	\$0.60	\$58.51
PARKBLVD	0101	L & T CR	Medium	622	Ft	2.6	Crack Sealing - AC	AC	1015	24	622	Ft	\$0.60	\$373.29
PARKBLVD	0101	POTHOLE	Low	6	Count	0.0	Patching - AC Deep	AC	1015	24	17	SqFt	\$5.56	\$94.08
PARKBLVD	0101	RUTTING	Medium	9	SqFt	0.0	Patching - AC Shallow	AC	1015	24	10	SqFt	\$2.78	\$26.11
PARKBLVD	0101	L & T CR	High	27	Ft	0.1	Patching - AC Shallow	AC	1015	24	87	SqFt	\$2.78	\$243.07
PARKBLVD	0101	ALLIGATOR CR	Medium	188	SqFt	0.8	Patching - AC Deep	AC	1015	24	248	SqFt	\$5.56	\$1,374.65
PARKLN	0529	L & T CR	Medium	200	Ft	2.3	Crack Sealing - AC	AC	368	24	200	Ft	\$0.60	\$120.20
PARKLN	0529	RUTTING	High	22	SqFt	0.3	Patching - AC Deep	AC	368	24	22	SqFt	\$5.56	\$121.15
PARKLN	0529	RUTTING	Medium	33	SqFt	0.4	Patching - AC Shallow	AC	368	24	32	SqFt	\$2.78	\$90.87
PARKLN	0529	L & T CR	High	47	Ft	0.5	Patching - AC Shallow	AC	368	24	153	SqFt	\$2.78	\$424.35
PARKRIDGECEC	0618	L & T CR	Medium	295	Ft	3.2	Crack Sealing - AC	AC	359	26	295	Ft	\$0.60	\$177.22
PARKRIDGECEC	0618	L & T CR	High	1	Ft	0.0	Patching - AC Shallow	AC	359	26	2	SqFt	\$2.78	\$4.73
PARKRIDGECEC	0618	RUTTING	Medium	11	SqFt	0.1	Patching - AC Shallow	AC	359	26	11	SqFt	\$2.78	\$30.02
PARKSIDECT	0365	L & T CR	Medium	266	Ft	1.8	Crack Sealing - AC	AC	610	24	266	Ft	\$0.60	\$159.40

## Details of the 2022 Localized Distress Maintenance Plan

BranchID	SectionID	Description	Severity	Distress Qty	Distress Unit	Percent Distress	Work Description	Surface Type	Section Length (Ft)	Section Width (Ft)	Work Qty	Work Unit	Unit Cost	Work Cost
PARKSIDECT	0365	L & T CR	High	1	Ft	0.0	Patching - AC Shallow	AC	610	24	4	SqFt	\$2.78	\$10.50
PARKSIDETE	0601	L & T CR	Medium	198	Ft	1.8	Crack Sealing - AC	AC	460	24	198	Ft	\$0.60	\$119.09
PARKSIDETE	0601	RUTTING	Medium	12	SqFt	0.1	Patching - AC Shallow	AC	460	24	12	SqFt	\$2.78	\$33.40
PARKVIEWCT	0494	L & T CR	Medium	13	Ft	0.0	Crack Sealing - AC	AC	1467	24	12	Ft	\$0.60	\$7.49
PARKVIEWCT	0494	L & T CR	High	6	Ft	0.0	Patching - AC Shallow	AC	1467	24	19	SqFt	\$2.78	\$54.78
PEBBLELN	0158	RUTTING	Medium	11	SqFt	0.1	Patching - AC Shallow	AC	610	26	11	SqFt	\$2.78	\$30.20
PEBBLELN	0158	L & T CR	Medium	4	Ft	0.0	Crack Sealing - AC	AC	610	26	4	Ft	\$0.60	\$2.15
PENNYLN	0112	L & T CR	High	73	Ft	0.2	Patching - AC Shallow	AC	1738	26	238	SqFt	\$2.78	\$661.90
PENNYLN	0112	L & T CR	Medium	31	Ft	0.1	Crack Sealing - AC	AC	1738	26	31	Ft	\$0.60	\$18.79
PENNYLN	0112	RUTTING	High	10	SqFt	0.0	Patching - AC Deep	AC	1738	26	10	SqFt	\$5.56	\$54.69
PENNYLN	0112	RUTTING	Medium	29	SqFt	0.1	Patching - AC Shallow	AC	1738	26	29	SqFt	\$2.78	\$82.03
PENNYLN	0744	RUTTING	Medium	13	SqFt	0.2	Patching - AC Shallow	AC	250	26	13	SqFt	\$2.78	\$37.13
PENNYLN	0744	L & T CR	High	9	Ft	0.1	Patching - AC Shallow	AC	250	26	29	SqFt	\$2.78	\$80.49
PENNYLN	0744	L & T CR	Medium	1	Ft	0.0	Crack Sealing - AC	AC	250	26	1	Ft	\$0.60	\$0.82
PENNYLN	0745	L & T CR	Medium	8	Ft	0.1	Crack Sealing - AC	AC	236	26	9	Ft	\$0.60	\$5.08
PENNYLN	0745	RUTTING	Medium	13	SqFt	0.2	Patching - AC Shallow	AC	236	26	13	SqFt	\$2.78	\$35.01
PENNYLN	0745	L & T CR	High	8	Ft	0.1	Patching - AC Shallow	AC	236	26	27	SqFt	\$2.78	\$74.85
PETERSONPK	0527	ALLIGATOR CR	Medium	0	SqFt	0.0	Patching - AC Deep	AC	1271	24	4	SqFt	\$5.56	\$26.09
PETERSONPK	0527	RUTTING	Medium	8	SqFt	0.0	Patching - AC Shallow	AC	1271	24	8	SqFt	\$2.78	\$21.72
PETERSONPK	0527	POTHOLE	Low	5	Count	0.0	Patching - AC Deep	AC	1271	24	16	SqFt	\$5.56	\$91.15
PETERSONPK	0527	L & T CR	High	9	Ft	0.0	Patching - AC Shallow	AC	1271	24	30	SqFt	\$2.78	\$82.74
PETERSONPK	0527	L & T CR	Medium	166	Ft	0.5	Crack Sealing - AC	AC	1271	24	166	Ft	\$0.60	\$99.63
PHEASANTLN	0019	RUTTING	Medium	11	SqFt	0.1	Patching - AC Shallow	AC	326	26	11	SqFt	\$2.78	\$31.15
PHEASANTLN	0019	L & T CR	Medium	47	Ft	0.6	Crack Sealing - AC	AC	326	26	47	Ft	\$0.60	\$27.94
PIERSONST	0034	RUTTING	High	133	SqFt	0.2	Patching - AC Deep	AC	2366	24	133	SqFt	\$5.56	\$741.46
PIERSONST	0034	L & T CR	High	115	Ft	0.2	Patching - AC Shallow	AC	2366	24	376	SqFt	\$2.78	\$1,045.66
PIERSONST	0034	ALLIGATOR CR	Medium	28	SqFt	0.1	Patching - AC Deep	AC	2366	24	53	SqFt	\$5.56	\$294.11
PIERSONST	0034	POTHOLE	Low	5	Count	0.0	Patching - AC Deep	AC	2366	24	16	SqFt	\$5.56	\$90.72
PIERSONST	0034	RUTTING	Medium	307	SqFt	0.5	Patching - AC Shallow	AC	2366	24	307	SqFt	\$2.78	\$852.66
PIERSONST	0034	L & T CR	Medium	550	Ft	1.0	Crack Sealing - AC	AC	2366	24	551	Ft	\$0.60	\$330.28
PINECT	0223	RUTTING	High	17	SqFt	0.1	Patching - AC Deep	AC	1130	22	17	SqFt	\$5.56	\$94.69
PINECT	0223	RUTTING	Medium	17	SqFt	0.1	Patching - AC Shallow	AC	1130	22	17	SqFt	\$2.78	\$47.35
PINECT	0223	POTHOLE	Low	8	Count	0.0	Patching - AC Deep	AC	1130	22	23	SqFt	\$5.56	\$127.97
PINECT	0223	ALLIGATOR CR	Medium	190	SqFt	0.8	Patching - AC Deep	AC	1130	22	250	SqFt	\$5.56	\$1,385.50
PINECT	0223	L & T CR	High	11	Ft	0.0	Patching - AC Shallow	AC	1130	22	37	SqFt	\$2.78	\$101.69
PINECT	0223	L & T CR	Medium	584	Ft	2.4	Crack Sealing - AC	AC	1130	22	584	Ft	\$0.60	\$350.34

## Details of the 2022 Localized Distress Maintenance Plan

BranchID	SectionID	Description	Severity	Distress Qty	Distress Unit	Percent Distress	Work Description	Surface Type	Section Length (Ft)	Section Width (Ft)	Work Qty	Work Unit	Unit Cost	Work Cost
PINECT	0223	ALLIGATOR CR	High	5	SqFt	0.0	Patching - AC Deep	AC	1130	22	18	SqFt	\$5.56	\$99.67
PINEST	0510	RUTTING	High	9	SqFt	0.1	Patching - AC Shallow	AC	509	24	10	SqFt	\$2.78	\$26.16
PINEWOODDR	0136	RUTTING	Medium	9	SqFt	0.1	Patching - AC Shallow	AC	498	22	9	SqFt	\$2.78	\$24.48
PINEWOODDR	0136	L & T CR	Medium	21	Ft	0.2	Crack Sealing - AC	AC	498	22	21	Ft	\$0.60	\$12.60
PINGREERD	0072	L & T CR	Medium	535	Ft	0.6	Crack Sealing - AC	AC	2406	36	535	Ft	\$0.60	\$321.24
PINGREERD	0072	RUTTING	High	78	SqFt	0.1	Patching - AC Deep	AC	2406	36	79	SqFt	\$5.56	\$435.20
PINGREERD	0072	RUTTING	Medium	13	SqFt	0.0	Patching - AC Shallow	AC	2406	36	13	SqFt	\$2.78	\$37.12
PINGREERD	0072	L & T CR	High	85	Ft	0.1	Patching - AC Shallow	AC	2406	36	278	SqFt	\$2.78	\$771.69
PINGREERD	0072	ALLIGATOR CR	High	236	SqFt	0.3	Patching - AC Deep	AC	2406	36	301	SqFt	\$5.56	\$1,676.56
PINGREERD	0072	ALLIGATOR CR	Medium	63	SqFt	0.1	Patching - AC Deep	AC	2406	36	99	SqFt	\$5.56	\$553.18
PINGREERD	0080	L & T CR	Medium	226	Ft	0.1	Crack Sealing - AC	AC	4730	36	226	Ft	\$0.60	\$135.42
PINGREERD	0080	L & T CR	High	25	Ft	0.0	Patching - AC Shallow	AC	4730	36	82	SqFt	\$2.78	\$226.99
PINGREERD	0080	POTHOLE	Low	32	Count	0.0	Patching - AC Deep	AC	4730	36	96	SqFt	\$5.56	\$533.12
PINGREERD	0080	RUTTING	Medium	21	SqFt	0.0	Patching - AC Shallow	AC	4730	36	22	SqFt	\$2.78	\$59.18
PINGREERD	0341	RUTTING	High	31	SqFt	0.0	Patching - AC Shallow	AC	1719	56	31	SqFt	\$2.78	\$85.48
PINGREERD	0530	RUTTING	Medium	42	SqFt	0.1	Patching - AC Shallow	AC	1550	28	42	SqFt	\$2.78	\$115.99
PINGREERD	0530	L & T CR	High	379	Ft	0.9	Patching - AC Shallow	AC	1550	28	1242	SqFt	\$2.78	\$3,452.76
PINGREERD	0530	ALLIGATOR CR	High	69	SqFt	0.2	Patching - AC Deep	AC	1550	28	107	SqFt	\$5.56	\$593.56
PINGREERD	0530	L & T CR	Medium	1846	Ft	4.3	Crack Sealing - AC	AC	1550	28	1845	Ft	\$0.60	\$1,107.33
PINGREERD	0530	POTHOLE	Low	5	Count	0.0	Patching - AC Deep	AC	1550	28	14	SqFt	\$5.56	\$78.34
PINGREERD	0530	RUTTING	High	47	SqFt	0.1	Patching - AC Deep	AC	1550	28	47	SqFt	\$5.56	\$261.04
PINGREERD	0530	ALLIGATOR CR	Medium	83	SqFt	0.2	Patching - AC Deep	AC	1550	28	124	SqFt	\$5.56	\$688.90
PINGREERD	0630	RUTTING	High	7	SqFt	0.0	Patching - AC Shallow	AC	492	36	6	SqFt	\$2.78	\$19.00
PIPERCT	0073	L & T CR	Medium	51	Ft	1.0	Crack Sealing - AC	AC	205	26	51	Ft	\$0.60	\$30.80
PIPERCT	0073	RUTTING	Medium	11	SqFt	0.2	Patching - AC Shallow	AC	205	26	11	SqFt	\$2.78	\$30.50
PLYMOUTHLN	0558	L & T CR	Medium	128	Ft	0.6	Crack Sealing - AC	AC	1045	22	128	Ft	\$0.60	\$76.95
POMEROYAVE	0270	L & T CR	Medium	440	Ft	0.7	Crack Sealing - AC	AC	2685	24	440	Ft	\$0.60	\$263.88
POMEROYAVE	0270	RUTTING	Medium	9	SqFt	0.0	Patching - AC Shallow	AC	2685	24	9	SqFt	\$2.78	\$25.11
POMEROYAVE	0270	L & T CR	High	14	Ft	0.0	Patching - AC Shallow	AC	2685	24	47	SqFt	\$2.78	\$130.86
POMEROYAVE	0270	POTHOLE	Low	5	Count	0.0	Patching - AC Deep	AC	2685	24	16	SqFt	\$5.56	\$90.48
POMEROYAVE	0568	POTHOLE	Low	3	Count	0.0	Patching - AC Deep	AC	830	24	9	SqFt	\$5.56	\$46.17
POMEROYAVE	0568	RUTTING	Medium	9	SqFt	0.1	Patching - AC Shallow	AC	830	24	10	SqFt	\$2.78	\$25.62
POMEROYAVE	0568	L & T CR	Medium	1	Ft	0.0	Crack Sealing - AC	AC	830	24	1	Ft	\$0.60	\$0.75
POPLARST	0107	RUTTING	Medium	9	SqFt	0.0	Patching - AC Shallow	AC	1321	24	10	SqFt	\$2.78	\$25.88
POPLARST	0107	L & T CR	Medium	168	Ft	0.5	Crack Sealing - AC	AC	1321	24	168	Ft	\$0.60	\$100.76
POPLARST	0107	L & T CR	High	5	Ft	0.0	Patching - AC Shallow	AC	1321	24	16	SqFt	\$2.78	\$43.60

## Details of the 2022 Localized Distress Maintenance Plan

BranchID	SectionID	Description	Severity	Distress Qty	Distress Unit	Percent Distress	Work Description	Surface Type	Section Length (Ft)	Section Width (Ft)	Work Qty	Work Unit	Unit Cost	Work Cost
PRAIRIEST	0336	RUTTING	High	18	SqFt	0.0	Patching - AC Shallow	AC	1720	24	18	SqFt	\$2.78	\$51.16
PRIMROSELN	0388	RUTTING	High	10	SqFt	0.1	Patching - AC Shallow	AC	872	26	11	SqFt	\$2.78	\$28.43
PROVIDENCE	0216	L & T CR	Medium	3438	Ft	3.8	Crack Sealing - AC	AC	2635	34	3438	Ft	\$0.60	\$2,062.89
PROVIDENCE	0216	ALLIGATOR CR	High	4	SqFt	0.0	Patching - AC Deep	AC	2635	34	15	SqFt	\$5.56	\$85.23
PROVIDENCE	0216	ALLIGATOR CR	Medium	361	SqFt	0.4	Patching - AC Deep	AC	2635	34	441	SqFt	\$5.56	\$2,456.19
PROVIDENCE	0216	RUTTING	Medium	13	SqFt	0.0	Patching - AC Shallow	AC	2635	34	13	SqFt	\$2.78	\$36.28
PROVIDENCE	0216	L & T CR	High	303	Ft	0.3	Patching - AC Shallow	AC	2635	34	996	SqFt	\$2.78	\$2,767.32
QUEENSPORT	0434	L & T CR	Medium	455	Ft	2.1	Crack Sealing - AC	AC	899	24	455	Ft	\$0.60	\$273.21
RAILROADST	0259	RUTTING	High	9	SqFt	0.0	Patching - AC Shallow	AC	1593	24	10	SqFt	\$2.78	\$25.54
RAYMONDDR	0557	L & T CR	Medium	94	Ft	0.3	Crack Sealing - AC	AC	1045	36	94	Ft	\$0.60	\$56.66
REBECCAST	0578	RUTTING	Medium	8	SqFt	0.1	Patching - AC Shallow	AC	700	24	9	SqFt	\$2.78	\$22.48
REBECCAST	0578	L & T CR	Medium	36	Ft	0.2	Crack Sealing - AC	AC	700	24	35	Ft	\$0.60	\$21.35
REDWOODST	0679	ALLIGATOR CR	Medium	16	SqFt	0.1	Patching - AC Deep	AC	519	24	36	SqFt	\$5.56	\$198.92
REDWOODST	0679	L & T CR	Medium	652	Ft	5.2	Crack Sealing - AC	AC	519	24	652	Ft	\$0.60	\$391.38
REGALDR	0235	L & T CR	Medium	203	Ft	0.5	Crack Sealing - AC	AC	1184	36	202	Ft	\$0.60	\$121.51
REILANDDR	0538	L & T CR	High	104	Ft	0.4	Patching - AC Shallow	AC	1046	28	342	SqFt	\$2.78	\$950.09
REILANDDR	0538	RUTTING	Medium	116	SqFt	0.4	Patching - AC Shallow	AC	1046	28	116	SqFt	\$2.78	\$322.90
REILANDDR	0538	L & T CR	Medium	661	Ft	2.3	Crack Sealing - AC	AC	1046	28	661	Ft	\$0.60	\$396.38
REILANDDR	0538	ALLIGATOR CR	Medium	280	SqFt	1.0	Patching - AC Deep	AC	1046	28	351	SqFt	\$5.56	\$1,952.29
RESERVEDR	0521	RUTTING	High	40	SqFt	0.1	Patching - AC Shallow	AC	1616	26	40	SqFt	\$2.78	\$110.81
RICKERTRD	0285	L & T CR	High	67	Ft	0.4	Patching - AC Shallow	AC	656	24	221	SqFt	\$2.78	\$613.37
RICKERTRD	0285	ALLIGATOR CR	Medium	136	SqFt	0.9	Patching - AC Deep	AC	656	24	187	SqFt	\$5.56	\$1,039.85
RICKERTRD	0285	L & T CR	Medium	546	Ft	3.5	Crack Sealing - AC	AC	656	24	546	Ft	\$0.60	\$327.47
RICKERTRD	0285	RUTTING	Medium	8	SqFt	0.1	Patching - AC Shallow	AC	656	24	9	SqFt	\$2.78	\$23.12
RIDGEAVE	0330	RUTTING	High	10	SqFt	0.0	Patching - AC Shallow	AC	1349	26	10	SqFt	\$2.78	\$27.34
RINGLINGRD	0022	L & T CR	Medium	798	Ft	2.8	Crack Sealing - AC	AC	1102	26	798	Ft	\$0.60	\$478.62
RINGLINGRD	0022	RUTTING	Medium	50	SqFt	0.2	Patching - AC Shallow	AC	1102	26	50	SqFt	\$2.78	\$139.02
RINGLINGRD	0022	ALLIGATOR CR	High	32	SqFt	0.1	Patching - AC Deep	AC	1102	26	59	SqFt	\$5.56	\$328.01
RINGLINGRD	0022	ALLIGATOR CR	Medium	134	SqFt	0.5	Patching - AC Deep	AC	1102	26	184	SqFt	\$5.56	\$1,023.67
RINGLINGRD	0022	L & T CR	High	87	Ft	0.3	Patching - AC Shallow	AC	1102	26	285	SqFt	\$2.78	\$793.31
RINGLINGRD	0022	POTHOLE	Low	6	Count	0.0	Patching - AC Deep	AC	1102	26	18	SqFt	\$5.56	\$100.19
RIVERSIDED	0323	L & T CR	Medium	7	Ft	0.0	Crack Sealing - AC	AC	927	22	7	Ft	\$0.60	\$4.00
RIVERSIDED	0762	L & T CR	Medium	11	Ft	0.0	Crack Sealing - AC	AC	1264	22	11	Ft	\$0.60	\$6.61
ROCKLANDRD	0572	L & T CR	High	5	Ft	0.0	Patching - AC Shallow	AC	1585	26	17	SqFt	\$2.78	\$48.09
ROCKLANDRD	0572	L & T CR	Medium	34	Ft	0.1	Crack Sealing - AC	AC	1585	26	34	Ft	\$0.60	\$20.61
ROLLINGHIL	0408	RUTTING	High	29	SqFt	0.0	Patching - AC Shallow	AC	3316	26	29	SqFt	\$2.78	\$81.60

## Details of the 2022 Localized Distress Maintenance Plan

BranchID	SectionID	Description	Severity	Distress Qty	Distress Unit	Percent Distress	Work Description	Surface Type	Section Length (Ft)	Section Width (Ft)	Work Qty	Work Unit	Unit Cost	Work Cost
ROSEDALEAV	0052	RUTTING	Medium	16	SqFt	0.1	Patching - AC Shallow	AC	1154	22	15	SqFt	\$2.78	\$43.35
ROSEDALEAV	0052	L & T CR	High	9	Ft	0.0	Patching - AC Shallow	AC	1154	22	29	SqFt	\$2.78	\$79.96
ROSEDALEAV	0052	POTHOLE	Low	3	Count	0.0	Patching - AC Deep	AC	1154	22	8	SqFt	\$5.56	\$42.02
ROSEDALEAV	0052	ALLIGATOR CR	Medium	28	SqFt	0.1	Patching - AC Deep	AC	1154	22	53	SqFt	\$5.56	\$296.05
ROSEDALEAV	0052	L & T CR	Medium	149	Ft	0.6	Crack Sealing - AC	AC	1154	22	149	Ft	\$0.60	\$89.65
ROSENTHALD	0593	RUTTING	High	61	SqFt	0.4	Patching - AC Shallow	AC	460	36	61	SqFt	\$2.78	\$170.36
ROSEWOODLN	0251	L & T CR	Medium	263	Ft	1.4	Crack Sealing - AC	AC	713	26	263	Ft	\$0.60	\$157.96
ROSEWOODLN	0251	ALLIGATOR CR	Medium	26	SqFt	0.1	Patching - AC Deep	AC	713	26	51	SqFt	\$5.56	\$283.71
RUDATCT	0342	RUTTING	High	120	SqFt	0.9	Patching - AC Shallow	AC	452	30	119	SqFt	\$2.78	\$332.44
SADDLECREE	0344	L & T CR	Medium	22	Ft	0.1	Crack Sealing - AC	AC	994	24	22	Ft	\$0.60	\$13.36
SADDLERDG	0453	L & T CR	Medium	320	Ft	1.1	Crack Sealing - AC	AC	1242	24	320	Ft	\$0.60	\$191.76
SAGGERSLN	0681	L & T CR	High	2	Ft	0.0	Patching - AC Shallow	AC	321	24	6	SqFt	\$2.78	\$17.85
SAGGERSLN	0681	L & T CR	Medium	163	Ft	2.1	Crack Sealing - AC	AC	321	24	163	Ft	\$0.60	\$98.09
SAGGERSLN	0683	L & T CR	High	1	Ft	0.0	Patching - AC Shallow	AC	313	24	2	SqFt	\$2.78	\$4.90
SAGGERSLN	0683	L & T CR	Medium	168	Ft	2.2	Crack Sealing - AC	AC	313	24	168	Ft	\$0.60	\$100.72
SANDALWOOD	0230	RUTTING	High	27	SqFt	0.1	Patching - AC Shallow	AC	1604	24	27	SqFt	\$2.78	\$76.17
SANDALWOOD	0398	RUTTING	Medium	206	SqFt	0.5	Patching - AC Shallow	AC	1814	24	206	SqFt	\$2.78	\$571.84
SANDALWOOD	0398	L & T CR	Medium	75	Ft	0.2	Crack Sealing - AC	AC	1814	24	75	Ft	\$0.60	\$45.08
SANDSRD	0645	RUTTING	High	245	SqFt	0.3	Patching - AC Shallow	AC	2265	34	245	SqFt	\$2.78	\$681.34
SARASOTALN	0129	L & T CR	Medium	523	Ft	1.4	Crack Sealing - AC	AC	1589	24	523	Ft	\$0.60	\$313.69
SARASOTALN	0129	RUTTING	Medium	54	SqFt	0.1	Patching - AC Shallow	AC	1589	24	54	SqFt	\$2.78	\$149.35
SARASOTALN	0129	ALLIGATOR CR	Medium	36	SqFt	0.1	Patching - AC Deep	AC	1589	24	65	SqFt	\$5.56	\$359.10
SARASOTALN	0129	L & T CR	High	23	Ft	0.1	Patching - AC Shallow	AC	1589	24	76	SqFt	\$2.78	\$211.60
SAVANNAHSLN	0459	RUTTING	High	8	SqFt	0.0	Patching - AC Shallow	AC	1267	24	8	SqFt	\$2.78	\$22.01
SBRENTWOOD	0126	RUTTING	High	10	SqFt	0.0	Patching - AC Shallow	AC	2112	26	10	SqFt	\$2.78	\$27.16
SCAROLINES	0455	L & T CR	High	2	Ft	0.0	Patching - AC Shallow	AC	1136	24	5	SqFt	\$2.78	\$14.58
SCAROLINES	0455	RUTTING	Medium	28	SqFt	0.1	Patching - AC Shallow	AC	1136	24	28	SqFt	\$2.78	\$77.89
SCAROLINES	0455	ALLIGATOR CR	Medium	16	SqFt	0.1	Patching - AC Deep	AC	1136	24	36	SqFt	\$5.56	\$196.13
SCAROLINES	0455	POTHOLE	Low	11	Count	0.0	Patching - AC Deep	AC	1136	24	33	SqFt	\$5.56	\$187.12
SCAROLINES	0455	L & T CR	Medium	304	Ft	1.1	Crack Sealing - AC	AC	1136	24	304	Ft	\$0.60	\$182.27
SDOLEAVE	0132	RUTTING	High	162	SqFt	0.2	Patching - AC Shallow	AC	2969	30	161	SqFt	\$2.78	\$449.90
SDOLEAVE	0489	RUTTING	High	55	SqFt	0.1	Patching - AC Shallow	AC	1715	30	55	SqFt	\$2.78	\$153.06
SECONDCT	0023	ALLIGATOR CR	Medium	62	SqFt	0.4	Patching - AC Deep	AC	767	22	98	SqFt	\$5.56	\$546.10
SECONDCT	0023	L & T CR	High	1	Ft	0.0	Patching - AC Shallow	AC	767	22	2	SqFt	\$2.78	\$5.78
SECONDCT	0023	L & T CR	Medium	180	Ft	1.1	Crack Sealing - AC	AC	767	22	180	Ft	\$0.60	\$108.07
SECONDCT	0023	RUTTING	Medium	18	SqFt	0.1	Patching - AC Shallow	AC	767	22	18	SqFt	\$2.78	\$51.02

## Details of the 2022 Localized Distress Maintenance Plan

BranchID	SectionID	Description	Severity	Distress Qty	Distress Unit	Percent Distress	Work Description	Surface Type	Section Length (Ft)	Section Width (Ft)	Work Qty	Work Unit	Unit Cost	Work Cost
SEGEWICKC	0721	RUTTING	High	26	SqFt	0.3	Patching - AC Shallow	AC	319	24	26	SqFt	\$2.78	\$71.59
SEYBROOKEC	0651	L & T CR	Medium	4	Ft	0.0	Crack Sealing - AC	AC	1376	24	4	Ft	\$0.60	\$2.38
SEYBROOKEC	0651	RUTTING	Medium	9	SqFt	0.0	Patching - AC Shallow	AC	1376	24	9	SqFt	\$2.78	\$25.35
SEYBROOKEC	0651	POTHOLE	Low	3	Count	0.0	Patching - AC Deep	AC	1376	24	9	SqFt	\$5.56	\$45.67
SHADOWOODL	0321	L & T CR	High	40	Ft	0.2	Patching - AC Shallow	AC	1028	24	131	SqFt	\$2.78	\$365.06
SHADOWOODL	0321	ALLIGATOR CR	Medium	162	SqFt	0.7	Patching - AC Deep	AC	1028	24	216	SqFt	\$5.56	\$1,205.10
SHADOWOODL	0321	L & T CR	Medium	440	Ft	1.8	Crack Sealing - AC	AC	1028	24	440	Ft	\$0.60	\$263.78
SHADOWOODL	0321	ALLIGATOR CR	High	0	SqFt	0.0	Patching - AC Deep	AC	1028	24	5	SqFt	\$5.56	\$31.39
SHADOWOODL	0321	RUTTING	Medium	91	SqFt	0.4	Patching - AC Shallow	AC	1028	24	90	SqFt	\$2.78	\$251.54
SHALESST	0688	L & T CR	High	41	Ft	0.2	Patching - AC Shallow	AC	758	24	133	SqFt	\$2.78	\$372.32
SHALESST	0688	L & T CR	Medium	741	Ft	4.1	Crack Sealing - AC	AC	758	24	741	Ft	\$0.60	\$444.53
SHARONDR	0204	L & T CR	Medium	215	Ft	0.8	Crack Sealing - AC	AC	894	30	215	Ft	\$0.60	\$129.17
SHEFFIELDDD	0375	RUTTING	High	10	SqFt	0.0	Patching - AC Shallow	AC	1486	26	10	SqFt	\$2.78	\$27.23
SHEFFIELDDD	0766	RUTTING	Medium	11	SqFt	0.1	Patching - AC Shallow	AC	496	26	12	SqFt	\$2.78	\$31.60
SHEFFIELDDD	0766	L & T CR	Medium	773	Ft	6.0	Crack Sealing - AC	AC	496	26	773	Ft	\$0.60	\$463.66
SHEFFIELDDD	0766	L & T CR	High	30	Ft	0.2	Patching - AC Shallow	AC	496	26	99	SqFt	\$2.78	\$274.58
SHELTONLN	0320	POTHOLE	Low	3	Count	0.0	Patching - AC Deep	AC	1113	26	9	SqFt	\$5.56	\$50.57
SHELTONLN	0320	L & T CR	High	4	Ft	0.0	Patching - AC Shallow	AC	1113	26	12	SqFt	\$2.78	\$34.01
SHELTONLN	0320	ALLIGATOR CR	High	41	SqFt	0.1	Patching - AC Deep	AC	1113	26	71	SqFt	\$5.56	\$396.10
SHELTONLN	0320	L & T CR	Medium	82	Ft	0.3	Crack Sealing - AC	AC	1113	26	82	Ft	\$0.60	\$49.26
SHELTONLN	0320	ALLIGATOR CR	Medium	8	SqFt	0.0	Patching - AC Deep	AC	1113	26	23	SqFt	\$5.56	\$127.74
SHELTONLN	0320	RUTTING	High	30	SqFt	0.1	Patching - AC Deep	AC	1113	26	30	SqFt	\$5.56	\$168.41
SHERMANST	0163	RUTTING	Medium	62	SqFt	0.2	Patching - AC Shallow	AC	1082	24	62	SqFt	\$2.78	\$172.85
SHERMANST	0163	L & T CR	Medium	288	Ft	1.1	Crack Sealing - AC	AC	1082	24	288	Ft	\$0.60	\$172.86
SHERMANST	0163	POTHOLE	Low	3	Count	0.0	Patching - AC Deep	AC	1082	24	9	SqFt	\$5.56	\$45.39
SHORTST	0002	RUTTING	High	64	SqFt	0.7	Patching - AC Shallow	AC	387	24	65	SqFt	\$2.78	\$179.20
SHORTST	0587	L & T CR	Medium	19	Ft	0.5	Crack Sealing - AC	AC	162	24	19	Ft	\$0.60	\$11.62
SILVERBERR	0535	L & T CR	High	2	Ft	0.0	Patching - AC Shallow	AC	714	26	8	SqFt	\$2.78	\$20.24
SILVERBERR	0535	L & T CR	Medium	1	Ft	0.0	Crack Sealing - AC	AC	714	26	1	Ft	\$0.60	\$0.51
SKYRIDGEDR	0087	L & T CR	Medium	144	Ft	0.4	Crack Sealing - AC	AC	1552	26	144	Ft	\$0.60	\$86.64
SKYRIDGEDR	0087	RUTTING	Medium	9	SqFt	0.0	Patching - AC Shallow	AC	1552	26	9	SqFt	\$2.78	\$23.77
SMAINST	0449	POTHOLE	Low	2	Count	0.0	Patching - AC Deep	AC	2679	58	6	SqFt	\$5.56	\$36.65
SMAINST	0449	ALLIGATOR CR	High	19	SqFt	0.0	Patching - AC Deep	AC	2679	58	40	SqFt	\$5.56	\$221.19
SMAINST	0449	L & T CR	High	908	Ft	0.9	Patching - AC Shallow	AC	2679	58	2978	SqFt	\$2.78	\$8,278.72
SMAINST	0449	L & T CR	Medium	3182	Ft	3.2	Crack Sealing - AC	AC	2679	58	3182	Ft	\$0.60	\$1,909.01
SMAINST	0449	RUTTING	Medium	453	SqFt	0.5	Patching - AC Shallow	AC	2679	58	453	SqFt	\$2.78	\$1,260.52

## Details of the 2022 Localized Distress Maintenance Plan

BranchID	SectionID	Description	Severity	Distress Qty	Distress Unit	Percent Distress	Work Description	Surface Type	Section Length (Ft)	Section Width (Ft)	Work Qty	Work Unit	Unit Cost	Work Cost
SMITANARD	0233	RUTTING	High	117	SqFt	0.3	Patching - AC Shallow	AC	1717	24	117	SqFt	\$2.78	\$324.72
SNOWBERRYL	0446	RUTTING	High	17	SqFt	0.1	Patching - AC Shallow	AC	1292	22	17	SqFt	\$2.78	\$46.40
SOAKST	0263	L & T CR	High	139	Ft	0.4	Patching - AC Shallow	AC	1239	30	455	SqFt	\$2.78	\$1,266.18
SOAKST	0263	L & T CR	Medium	596	Ft	1.6	Crack Sealing - AC	AC	1239	30	596	Ft	\$0.60	\$357.73
SOMERFIELD	0047	POTHOLE	Low	3	Count	0.0	Patching - AC Deep	AC	2355	26	9	SqFt	\$5.56	\$50.21
SOMERFIELD	0047	RUTTING	Medium	20	SqFt	0.0	Patching - AC Shallow	AC	2355	26	20	SqFt	\$2.78	\$55.74
SOMERFIELD	0047	L & T CR	High	2	Ft	0.0	Patching - AC Shallow	AC	2355	26	8	SqFt	\$2.78	\$21.14
SOMERFIELD	0047	L & T CR	Medium	156	Ft	0.3	Crack Sealing - AC	AC	2355	26	156	Ft	\$0.60	\$93.69
SOMERFIELD	0732	L & T CR	Medium	7	Ft	0.1	Crack Sealing - AC	AC	269	26	7	Ft	\$0.60	\$3.89
SOMERFIELD	0732	L & T CR	High	0	Ft	0.0	Patching - AC Shallow	AC	269	26	0	SqFt	\$2.78	\$0.64
SORIOLETRL	0016	ALLIGATOR CR	Medium	50	SqFt	0.1	Patching - AC Deep	AC	3586	24	82	SqFt	\$5.56	\$454.70
SORIOLETRL	0016	POTHOLE	Low	5	Count	0.0	Patching - AC Deep	AC	3586	24	16	SqFt	\$5.56	\$90.63
SORIOLETRL	0016	L & T CR	Medium	1651	Ft	1.9	Crack Sealing - AC	AC	3586	24	1651	Ft	\$0.60	\$990.31
SORIOLETRL	0016	L & T CR	High	137	Ft	0.2	Patching - AC Shallow	AC	3586	24	448	SqFt	\$2.78	\$1,245.11
SORIOLETRL	0016	RUTTING	High	18	SqFt	0.0	Patching - AC Deep	AC	3586	24	18	SqFt	\$5.56	\$100.60
SORIOLETRL	0016	RUTTING	Medium	180	SqFt	0.2	Patching - AC Shallow	AC	3586	24	180	SqFt	\$2.78	\$499.67
SOUTHST	0394	RUTTING	High	9	SqFt	0.1	Patching - AC Deep	AC	560	22	9	SqFt	\$5.56	\$50.73
SOUTHST	0394	POTHOLE	Low	3	Count	0.0	Patching - AC Deep	AC	560	22	9	SqFt	\$5.56	\$45.70
SPRINGRIDG	0727	RUTTING	High	4	SqFt	0.5	Patching - AC Shallow	AC	30	24	4	SqFt	\$2.78	\$10.63
STANDREWSL	0214	L & T CR	High	3	Ft	0.0	Patching - AC Shallow	AC	2765	34	9	SqFt	\$2.78	\$24.00
STANDREWSL	0214	RUTTING	Medium	11	SqFt	0.0	Patching - AC Shallow	AC	2765	34	11	SqFt	\$2.78	\$30.76
STANDREWSL	0214	L & T CR	Medium	95	Ft	0.1	Crack Sealing - AC	AC	2765	34	95	Ft	\$0.60	\$57.04
STOCKTONLN	0117	RUTTING	Medium	20	SqFt	0.0	Patching - AC Shallow	AC	2629	26	19	SqFt	\$2.78	\$54.49
STOCKTONLN	0117	L & T CR	Medium	70	Ft	0.1	Crack Sealing - AC	AC	2629	26	70	Ft	\$0.60	\$41.94
STOCKTONLN	0746	L & T CR	Medium	31	Ft	0.6	Crack Sealing - AC	AC	195	26	31	Ft	\$0.60	\$18.48
STONEBRIDG	0534	L & T CR	Medium	640	Ft	2.8	Crack Sealing - AC	AC	880	26	640	Ft	\$0.60	\$384.01
STONEBRIDG	0534	L & T CR	High	1	Ft	0.0	Patching - AC Shallow	AC	880	26	2	SqFt	\$2.78	\$4.97
STONEBRIDG	0534	RUTTING	Medium	10	SqFt	0.0	Patching - AC Shallow	AC	880	26	10	SqFt	\$2.78	\$28.02
STONEBRIDG	0585	L & T CR	Medium	686	Ft	2.2	Crack Sealing - AC	AC	1324	24	686	Ft	\$0.60	\$411.51
STONEBRIDG	0585	RUTTING	Medium	18	SqFt	0.1	Patching - AC Shallow	AC	1324	24	18	SqFt	\$2.78	\$50.29
STONEBRIDG	0585	L & T CR	High	12	Ft	0.0	Patching - AC Shallow	AC	1324	24	38	SqFt	\$2.78	\$105.29
STONEHEDGE	0518	L & T CR	Medium	442	Ft	4.9	Crack Sealing - AC	AC	374	24	442	Ft	\$0.60	\$265.25
STONEHEDGE	0518	L & T CR	High	0	Ft	0.0	Patching - AC Shallow	AC	374	24	2	SqFt	\$2.78	\$4.54
STONYHILL	0152	L & T CR	Medium	3	Ft	0.0	Crack Sealing - AC	AC	1432	24	4	Ft	\$0.60	\$2.07
STONYHILL	0152	RUTTING	Medium	9	SqFt	0.0	Patching - AC Shallow	AC	1432	24	10	SqFt	\$2.78	\$26.00
SUNNYSIDEA	0395	L & T CR	Medium	243	Ft	1.1	Crack Sealing - AC	AC	1027	22	243	Ft	\$0.60	\$145.84

## Details of the 2022 Localized Distress Maintenance Plan

BranchID	SectionID	Description	Severity	Distress Qty	Distress Unit	Percent Distress	Work Description	Surface Type	Section Length (Ft)	Section Width (Ft)	Work Qty	Work Unit	Unit Cost	Work Cost
SUNNYSIDEA	0395	POTHOLE	Low	3	Count	0.0	Patching - AC Deep	AC	1027	22	8	SqFt	\$5.56	\$43.61
SUNNYSIDEA	0395	L & T CR	High	1	Ft	0.0	Patching - AC Shallow	AC	1027	22	3	SqFt	\$2.78	\$9.78
SUNNYSIDEA	0395	ALLIGATOR CR	Medium	110	SqFt	0.5	Patching - AC Deep	AC	1027	22	156	SqFt	\$5.56	\$866.64
SURREYLN	0236	L & T CR	High	4	Ft	0.0	Patching - AC Shallow	AC	2040	26	12	SqFt	\$2.78	\$32.25
SURREYLN	0236	POTHOLE	Low	6	Count	0.0	Patching - AC Deep	AC	2040	26	17	SqFt	\$5.56	\$98.31
SURREYLN	0236	RUTTING	Medium	10	SqFt	0.0	Patching - AC Shallow	AC	2040	26	10	SqFt	\$2.78	\$27.28
SURREYLN	0236	L & T CR	Medium	41	Ft	0.1	Crack Sealing - AC	AC	2040	26	41	Ft	\$0.60	\$24.68
SUSSEXLN	0173	L & T CR	Medium	56	Ft	0.2	Crack Sealing - AC	AC	1075	26	56	Ft	\$0.60	\$33.68
SUSSEXLN	0173	RUTTING	Medium	10	SqFt	0.0	Patching - AC Shallow	AC	1075	26	10	SqFt	\$2.78	\$27.65
SUSSEXLN	0617	RUTTING	High	8	SqFt	0.0	Patching - AC Shallow	AC	1405	22	9	SqFt	\$2.78	\$23.03
SUTHERLAND	0100	L & T CR	Medium	44	Ft	0.1	Crack Sealing - AC	AC	1259	26	44	Ft	\$0.60	\$26.38
SUTHERLAND	0100	RUTTING	Medium	10	SqFt	0.0	Patching - AC Shallow	AC	1259	26	10	SqFt	\$2.78	\$27.60
SUTTONDR	0497	L & T CR	Medium	3	Ft	0.1	Crack Sealing - AC	AC	288	26	3	Ft	\$0.60	\$2.05
SWALKUPAVE	0160	RUTTING	Medium	13	SqFt	0.0	Patching - AC Shallow	AC	1201	34	13	SqFt	\$2.78	\$35.60
SWALKUPAVE	0160	L & T CR	High	11	Ft	0.0	Patching - AC Shallow	AC	1201	34	38	SqFt	\$2.78	\$104.51
SWALKUPAVE	0160	ALLIGATOR CR	Medium	2	SqFt	0.0	Patching - AC Deep	AC	1201	34	12	SqFt	\$5.56	\$65.52
SWALKUPAVE	0160	L & T CR	Medium	549	Ft	1.3	Crack Sealing - AC	AC	1201	34	549	Ft	\$0.60	\$329.51
SWALKUPAVE	0307	L & T CR	Medium	2	Ft	0.0	Crack Sealing - AC	AC	1109	22	2	Ft	\$0.60	\$1.48
SWALKUPAVE	0307	L & T CR	High	4	Ft	0.0	Patching - AC Shallow	AC	1109	22	14	SqFt	\$2.78	\$38.00
SWANSONRD	0106	RUTTING	Medium	854	SqFt	0.5	Patching - AC Shallow	AC	5220	36	854	SqFt	\$2.78	\$2,373.54
SWANSONRD	0106	RUTTING	High	40	SqFt	0.0	Patching - AC Deep	AC	5220	36	40	SqFt	\$5.56	\$223.91
SWANSONRD	0106	POTHOLE	Low	16	Count	0.0	Patching - AC Deep	AC	5220	36	48	SqFt	\$5.56	\$268.96
SWILLIAMSS	0473	L & T CR	Medium	369	Ft	0.8	Crack Sealing - AC	AC	1597	30	369	Ft	\$0.60	\$221.69
SWILLIAMSS	0473	ALLIGATOR CR	Medium	35	SqFt	0.1	Patching - AC Deep	AC	1597	30	62	SqFt	\$5.56	\$348.56
SWILLIAMSS	0473	L & T CR	High	6	Ft	0.0	Patching - AC Shallow	AC	1597	30	18	SqFt	\$2.78	\$51.07
SYCAMORELN	0234	POTHOLE	Low	4	Count	0.0	Patching - AC Deep	AC	346	26	11	SqFt	\$5.56	\$59.58
SYCAMORELN	0234	L & T CR	Medium	215	Ft	2.4	Crack Sealing - AC	AC	346	26	216	Ft	\$0.60	\$129.28
TALCOTTAVE	0154	POTHOLE	Low	3	Count	0.0	Patching - AC Deep	AC	2058	26	9	SqFt	\$5.56	\$49.59
TALCOTTAVE	0154	L & T CR	High	4	Ft	0.0	Patching - AC Shallow	AC	2058	26	12	SqFt	\$2.78	\$32.00
TALCOTTAVE	0154	RUTTING	Medium	30	SqFt	0.1	Patching - AC Shallow	AC	2058	26	30	SqFt	\$2.78	\$82.57
TALCOTTAVE	0154	L & T CR	Medium	198	Ft	0.4	Crack Sealing - AC	AC	2058	26	198	Ft	\$0.60	\$119.06
TALCOTTCT	0252	L & T CR	Medium	11	Ft	0.1	Crack Sealing - AC	AC	333	26	11	Ft	\$0.60	\$6.57
TALISMONDR	0017	L & T CR	Medium	3	Ft	0.0	Crack Sealing - AC	AC	4163	24	3	Ft	\$0.60	\$2.05
TAMARISKLN	0356	L & T CR	Medium	36	Ft	0.1	Crack Sealing - AC	AC	1062	26	36	Ft	\$0.60	\$21.51
TAMARISKTE	0541	L & T CR	Medium	3	Ft	0.0	Crack Sealing - AC	AC	689	26	3	Ft	\$0.60	\$1.61
TAMARISKTE	0541	L & T CR	High	0	Ft	0.0	Patching - AC Shallow	AC	689	26	1	SqFt	\$2.78	\$3.93

## Details of the 2022 Localized Distress Maintenance Plan

BranchID	SectionID	Description	Severity	Distress Qty	Distress Unit	Percent Distress	Work Description	Surface Type	Section Length (Ft)	Section Width (Ft)	Work Qty	Work Unit	Unit Cost	Work Cost
TAMARISKTE	0541	ALLIGATOR CR	Medium	9	SqFt	0.1	Patching - AC Deep	AC	689	26	26	SqFt	\$5.56	\$143.04
TANGLEWOOD	0043	RUTTING	High	9	SqFt	0.0	Patching - AC Shallow	AC	1073	24	10	SqFt	\$2.78	\$25.47
TANGLEWOOD	0086	L & T CR	High	1	Ft	0.0	Patching - AC Shallow	AC	798	26	2	SqFt	\$2.78	\$5.53
TANGLEWOOD	0086	L & T CR	Medium	362	Ft	1.8	Crack Sealing - AC	AC	798	26	363	Ft	\$0.60	\$217.45
TANGLEWOOD	0086	ALLIGATOR CR	Medium	0	SqFt	0.0	Patching - AC Deep	AC	798	26	5	SqFt	\$5.56	\$29.49
TANGLEWOOD	0730	RUTTING	High	25	SqFt	0.5	Patching - AC Shallow	AC	222	24	25	SqFt	\$2.78	\$68.55
TEAKWOODLN	0537	POTHOLE	Low	10	Count	0.1	Patching - AC Deep	AC	984	22	31	SqFt	\$5.56	\$170.75
TEAKWOODLN	0537	ALLIGATOR CR	Medium	8	SqFt	0.0	Patching - AC Deep	AC	984	22	24	SqFt	\$5.56	\$132.06
TEAKWOODLN	0537	RUTTING	High	7	SqFt	0.0	Patching - AC Deep	AC	984	22	8	SqFt	\$5.56	\$40.69
TEAKWOODLN	0537	RUTTING	Medium	43	SqFt	0.2	Patching - AC Shallow	AC	984	22	43	SqFt	\$2.78	\$118.46
TEAKWOODLN	0537	L & T CR	High	31	Ft	0.1	Patching - AC Shallow	AC	984	22	102	SqFt	\$2.78	\$283.13
TEAKWOODLN	0537	L & T CR	Medium	196	Ft	0.9	Crack Sealing - AC	AC	984	22	196	Ft	\$0.60	\$117.51
TECKLERBLV	0262	RUTTING	High	14	SqFt	0.0	Patching - AC Shallow	AC	1882	38	14	SqFt	\$2.78	\$39.54
TECKLERBLV	0324	RUTTING	High	14	SqFt	0.0	Patching - AC Shallow	AC	1140	36	14	SqFt	\$2.78	\$37.70
TECKLERBLV	0422	ALLIGATOR CR	Medium	5	SqFt	0.0	Patching - AC Deep	AC	1304	36	17	SqFt	\$5.56	\$95.08
TECKLERBLV	0422	L & T CR	Medium	972	Ft	2.1	Crack Sealing - AC	AC	1304	36	972	Ft	\$0.60	\$583.01
TECKLERBLV	0422	L & T CR	High	453	Ft	1.0	Patching - AC Shallow	AC	1304	36	1488	SqFt	\$2.78	\$4,135.25
TECKLERBLV	0422	RUTTING	Medium	29	SqFt	0.1	Patching - AC Shallow	AC	1304	36	28	SqFt	\$2.78	\$79.16
TEKDR	0405	L & T CR	High	8	Ft	0.0	Patching - AC Shallow	AC	2630	36	25	SqFt	\$2.78	\$69.56
TEKDR	0405	L & T CR	Medium	175	Ft	0.2	Crack Sealing - AC	AC	2630	36	175	Ft	\$0.60	\$104.73
TEKDR	0405	RUTTING	Medium	14	SqFt	0.0	Patching - AC Shallow	AC	2630	36	14	SqFt	\$2.78	\$37.75
TERRACOTTA	0145	L & T CR	High	3	Ft	0.0	Patching - AC Shallow	AC	2876	24	10	SqFt	\$2.78	\$27.88
TERRACOTTA	0145	ALLIGATOR CR	Medium	0	SqFt	0.0	Patching - AC Deep	AC	2876	24	6	SqFt	\$5.56	\$34.57
TERRACOTTA	0145	L & T CR	Medium	119	Ft	0.2	Crack Sealing - AC	AC	2876	24	119	Ft	\$0.60	\$71.51
TERRACOTTA	0145	RUTTING	High	9	SqFt	0.0	Patching - AC Deep	AC	2876	24	9	SqFt	\$5.56	\$49.65
TERRACOTTA	0247	RUTTING	High	18	SqFt	0.0	Patching - AC Shallow	AC	2581	24	18	SqFt	\$2.78	\$49.77
TERRACOTTA	0631	L & T CR	Medium	189	Ft	0.8	Crack Sealing - AC	AC	982	24	189	Ft	\$0.60	\$113.36
THIRDST	0598	L & T CR	Medium	222	Ft	2.1	Crack Sealing - AC	AC	446	24	222	Ft	\$0.60	\$133.24
THOMASVILLE	0316	ALLIGATOR CR	Medium	199	SqFt	0.8	Patching - AC Deep	AC	1027	24	259	SqFt	\$5.56	\$1,444.74
THOMASVILLE	0316	L & T CR	High	4	Ft	0.0	Patching - AC Shallow	AC	1027	24	13	SqFt	\$2.78	\$36.73
THOMASVILLE	0316	RUTTING	Medium	27	SqFt	0.1	Patching - AC Shallow	AC	1027	24	27	SqFt	\$2.78	\$76.07
THOMASVILLE	0316	L & T CR	Medium	106	Ft	0.4	Crack Sealing - AC	AC	1027	24	106	Ft	\$0.60	\$63.77
THORNWOODL	0350	L & T CR	High	0	Ft	0.0	Patching - AC Shallow	AC	2211	22	0	SqFt	\$2.78	\$0.45
THORNWOODL	0350	L & T CR	Medium	75	Ft	0.2	Crack Sealing - AC	AC	2211	22	75	Ft	\$0.60	\$45.04
THORNWOODL	0350	ALLIGATOR CR	Medium	0	SqFt	0.0	Patching - AC Deep	AC	2211	22	6	SqFt	\$5.56	\$34.76
THREEOAKSR	0090	RUTTING	High	33	SqFt	0.0	Patching - AC Deep	AC	5675	30	33	SqFt	\$5.56	\$185.65

## Details of the 2022 Localized Distress Maintenance Plan

BranchID	SectionID	Description	Severity	Distress Qty	Distress Unit	Percent Distress	Work Description	Surface Type	Section Length (Ft)	Section Width (Ft)	Work Qty	Work Unit	Unit Cost	Work Cost
THREEOAKSR	0090	ALLIGATOR CR	Medium	1001	SqFt	0.6	Patching - AC Deep	AC	5675	30	1132	SqFt	\$5.56	\$6,295.98
THREEOAKSR	0090	L & T CR	High	990	Ft	0.6	Patching - AC Shallow	AC	5675	30	3250	SqFt	\$2.78	\$9,032.56
THREEOAKSR	0090	L & T CR	Medium	4990	Ft	2.9	Crack Sealing - AC	AC	5675	30	4990	Ft	\$0.60	\$2,994.23
THREEOAKSR	0090	POTHOLE	Low	3	Count	0.0	Patching - AC Deep	AC	5675	30	10	SqFt	\$5.56	\$55.75
THREEOAKSR	0090	RUTTING	Medium	121	SqFt	0.1	Patching - AC Shallow	AC	5675	30	121	SqFt	\$2.78	\$335.99
TIMBERHILL	0457	L & T CR	High	138	Ft	0.7	Patching - AC Shallow	AC	843	22	452	SqFt	\$2.78	\$1,255.54
TIMBERHILL	0457	L & T CR	Medium	56	Ft	0.3	Crack Sealing - AC	AC	843	22	56	Ft	\$0.60	\$33.88
TIMBERHILL	0457	RUTTING	High	107	SqFt	0.6	Patching - AC Deep	AC	843	22	107	SqFt	\$5.56	\$592.86
TIMBERHILL	0457	POTHOLE	Low	3	Count	0.0	Patching - AC Deep	AC	843	22	8	SqFt	\$5.56	\$42.95
TOMAHAWKLN	0491	L & T CR	High	3	Ft	0.0	Patching - AC Shallow	AC	507	24	9	SqFt	\$2.78	\$23.39
TRACYTRL	0586	L & T CR	High	2	Ft	0.0	Patching - AC Shallow	AC	656	36	6	SqFt	\$2.78	\$18.36
TRACYTRL	0586	L & T CR	Medium	311	Ft	1.3	Crack Sealing - AC	AC	656	36	311	Ft	\$0.60	\$186.73
TRACYTRL	0586	RUTTING	Medium	15	SqFt	0.1	Patching - AC Shallow	AC	656	36	15	SqFt	\$2.78	\$40.51
TRACYTRL	0586	ALLIGATOR CR	Medium	43	SqFt	0.2	Patching - AC Deep	AC	656	36	74	SqFt	\$5.56	\$411.00
TRAILWOODC	0239	L & T CR	Medium	55	Ft	0.6	Crack Sealing - AC	AC	361	26	55	Ft	\$0.60	\$32.83
TRAILWOODD	0454	L & T CR	Medium	755	Ft	3.4	Crack Sealing - AC	AC	854	26	755	Ft	\$0.60	\$452.96
TRAILWOODD	0454	RUTTING	Medium	50	SqFt	0.2	Patching - AC Shallow	AC	854	26	51	SqFt	\$2.78	\$139.40
TRAILWOODD	0454	L & T CR	High	3	Ft	0.0	Patching - AC Shallow	AC	854	26	11	SqFt	\$2.78	\$30.47
UNIONST	0275	RUTTING	High	68	SqFt	0.1	Patching - AC Shallow	AC	2952	30	68	SqFt	\$2.78	\$188.65
UNIVERSITY	0265	L & T CR	High	0	Ft	0.0	Patching - AC Shallow	AC	949	22	1	SqFt	\$2.78	\$4.23
UNIVERSITY	0265	POTHOLE	Low	3	Count	0.0	Patching - AC Deep	AC	949	22	8	SqFt	\$5.56	\$43.00
UNIVERSITY	0265	RUTTING	Medium	16	SqFt	0.1	Patching - AC Shallow	AC	949	22	16	SqFt	\$2.78	\$44.36
UNIVERSITY	0265	L & T CR	Medium	168	Ft	0.8	Crack Sealing - AC	AC	949	22	168	Ft	\$0.60	\$100.85
UNIVERSITY	0265	ALLIGATOR CR	Medium	88	SqFt	0.4	Patching - AC Deep	AC	949	22	129	SqFt	\$5.56	\$720.84
UTEGST	0315	L & T CR	Medium	63	Ft	0.3	Crack Sealing - AC	AC	959	22	63	Ft	\$0.60	\$38.05
UTEGST	0315	RUTTING	Medium	8	SqFt	0.0	Patching - AC Shallow	AC	959	22	9	SqFt	\$2.78	\$23.08
UTEGST	0315	L & T CR	High	4	Ft	0.0	Patching - AC Shallow	AC	959	22	15	SqFt	\$2.78	\$40.70
VANBURENST	0428	RUTTING	Medium	22	SqFt	0.1	Patching - AC Shallow	AC	946	30	23	SqFt	\$2.78	\$61.67
VANBURENST	0428	L & T CR	Medium	44	Ft	0.2	Crack Sealing - AC	AC	946	30	44	Ft	\$0.60	\$26.19
VANBURENST	0428	POTHOLE	Low	14	Count	0.1	Patching - AC Deep	AC	946	30	43	SqFt	\$5.56	\$239.11
VICTORPKWY	0485	POTHOLE	Low	3	Count	0.0	Patching - AC Deep	AC	916	26	10	SqFt	\$5.56	\$55.18
VICTORPKWY	0485	L & T CR	Medium	309	Ft	1.3	Crack Sealing - AC	AC	916	26	309	Ft	\$0.60	\$185.64
VICTORPKWY	0485	L & T CR	High	11	Ft	0.1	Patching - AC Shallow	AC	916	26	36	SqFt	\$2.78	\$100.18
VIEWST	0024	L & T CR	High	2	Ft	0.0	Patching - AC Shallow	AC	971	24	5	SqFt	\$2.78	\$14.17
VIEWST	0024	POTHOLE	Low	3	Count	0.0	Patching - AC Deep	AC	971	24	9	SqFt	\$5.56	\$48.00
VIEWST	0024	L & T CR	Medium	9	Ft	0.0	Crack Sealing - AC	AC	971	24	9	Ft	\$0.60	\$5.37

## Details of the 2022 Localized Distress Maintenance Plan

BranchID	SectionID	Description	Severity	Distress Qty	Distress Unit	Percent Distress	Work Description	Surface Type	Section Length (Ft)	Section Width (Ft)	Work Qty	Work Unit	Unit Cost	Work Cost
VIEWST	0024	RUTTING	Medium	8	SqFt	0.0	Patching - AC Shallow	AC	971	24	9	SqFt	\$2.78	\$22.88
VILLAGECT	0125	L & T CR	Medium	57	Ft	0.4	Crack Sealing - AC	AC	541	26	57	Ft	\$0.60	\$34.34
VILLAGERD	0061	RUTTING	Medium	25	SqFt	0.0	Patching - AC Shallow	AC	3961	34	25	SqFt	\$2.78	\$70.32
VILLAGERD	0061	L & T CR	Medium	333	Ft	0.3	Crack Sealing - AC	AC	3961	34	333	Ft	\$0.60	\$199.94
VILLAGERD	0061	L & T CR	High	19	Ft	0.0	Patching - AC Shallow	AC	3961	34	64	SqFt	\$2.78	\$175.97
VILLAGERD	0061	POTHOLE	Low	4	Count	0.0	Patching - AC Deep	AC	3961	34	12	SqFt	\$5.56	\$63.35
VILLAGERD	0061	ALLIGATOR CR	High	7	SqFt	0.0	Patching - AC Deep	AC	3961	34	23	SqFt	\$5.56	\$123.95
VILLAGERD	0091	L & T CR	Medium	604	Ft	1.9	Crack Sealing - AC	AC	958	34	604	Ft	\$0.60	\$362.33
VILLAGERD	0195	L & T CR	Medium	81	Ft	0.2	Crack Sealing - AC	AC	1533	34	81	Ft	\$0.60	\$48.56
VILLAGERD	0195	RUTTING	Medium	26	SqFt	0.1	Patching - AC Shallow	AC	1533	34	26	SqFt	\$2.78	\$71.49
VILLAGERD	0195	ALLIGATOR CR	Medium	2	SqFt	0.0	Patching - AC Deep	AC	1533	34	12	SqFt	\$5.56	\$65.63
VILLAGERD	0224	L & T CR	Medium	54	Ft	0.3	Crack Sealing - AC	AC	673	26	54	Ft	\$0.60	\$32.63
VILLAGERD	0224	L & T CR	High	1	Ft	0.0	Patching - AC Shallow	AC	673	26	2	SqFt	\$2.78	\$6.57
WALLACEAVE	0278	RUTTING	Medium	11	SqFt	0.0	Patching - AC Shallow	AC	2504	30	11	SqFt	\$2.78	\$31.40
WALLACEAVE	0278	L & T CR	High	1	Ft	0.0	Patching - AC Shallow	AC	2504	30	4	SqFt	\$2.78	\$10.52
WALLACEAVE	0278	L & T CR	Medium	12	Ft	0.0	Crack Sealing - AC	AC	2504	30	12	Ft	\$0.60	\$7.12
WALLACEAVE	0456	RUTTING	Medium	17	SqFt	0.2	Patching - AC Shallow	AC	384	22	17	SqFt	\$2.78	\$48.32
WALLACEAVE	0456	L & T CR	Medium	14	Ft	0.2	Crack Sealing - AC	AC	384	22	14	Ft	\$0.60	\$8.39
WARRINGTON	0232	L & T CR	Medium	225	Ft	0.7	Crack Sealing - AC	AC	1223	26	225	Ft	\$0.60	\$134.78
WATERFORDC	0254	L & T CR	High	9	Ft	0.0	Patching - AC Shallow	AC	4075	32	29	SqFt	\$2.78	\$79.88
WATERFORDC	0254	POTHOLE	Low	7	Count	0.0	Patching - AC Deep	AC	4075	32	22	SqFt	\$5.56	\$120.23
WATERFORDC	0254	RUTTING	Medium	72	SqFt	0.1	Patching - AC Shallow	AC	4075	32	72	SqFt	\$2.78	\$200.18
WATERFORDC	0254	L & T CR	Medium	2329	Ft	1.8	Crack Sealing - AC	AC	4075	32	2329	Ft	\$0.60	\$1,397.23
WATERFORDC	0254	ALLIGATOR CR	Medium	75	SqFt	0.1	Patching - AC Deep	AC	4075	32	114	SqFt	\$5.56	\$632.29
WCRYSTALLA	0039	L & T CR	Medium	1362	Ft	2.7	Crack Sealing - AC	AC	1596	32	1362	Ft	\$0.60	\$817.00
WCRYSTALLA	0039	L & T CR	High	23	Ft	0.1	Patching - AC Shallow	AC	1596	32	76	SqFt	\$2.78	\$213.57
WCRYSTALLA	0206	RUTTING	Medium	24	SqFt	0.1	Patching - AC Shallow	AC	1388	34	24	SqFt	\$2.78	\$65.40
WCRYSTALLA	0206	POTHOLE	Low	4	Count	0.0	Patching - AC Deep	AC	1388	34	12	SqFt	\$5.56	\$63.39
WCRYSTALLA	0206	L & T CR	Medium	49	Ft	0.1	Crack Sealing - AC	AC	1388	34	49	Ft	\$0.60	\$29.23
WCRYSTALLA	0206	L & T CR	High	2	Ft	0.0	Patching - AC Shallow	AC	1388	34	6	SqFt	\$2.78	\$18.72
WCRYSTALLA	0655	ALLIGATOR CR	Medium	6	SqFt	0.0	Patching - AC Deep	AC	2414	30	19	SqFt	\$5.56	\$109.92
WCRYSTALLA	0655	L & T CR	Medium	219	Ft	0.3	Crack Sealing - AC	AC	2414	30	219	Ft	\$0.60	\$131.11
WCRYSTALLA	0655	POTHOLE	Low	7	Count	0.0	Patching - AC Deep	AC	2414	30	20	SqFt	\$5.56	\$112.81
WCRYSTALLA	0655	L & T CR	High	20	Ft	0.0	Patching - AC Shallow	AC	2414	30	66	SqFt	\$2.78	\$181.35
WCRYSTALLA	0655	RUTTING	Medium	56	SqFt	0.1	Patching - AC Shallow	AC	2414	30	56	SqFt	\$2.78	\$156.52
WEDGEWOODD	0008	RUTTING	Medium	19	SqFt	0.0	Patching - AC Shallow	AC	4802	26	19	SqFt	\$2.78	\$53.51

## Details of the 2022 Localized Distress Maintenance Plan

BranchID	SectionID	Description	Severity	Distress Qty	Distress Unit	Percent Distress	Work Description	Surface Type	Section Length (Ft)	Section Width (Ft)	Work Qty	Work Unit	Unit Cost	Work Cost
WEDGEWOODD	0008	L & T CR	Medium	6	Ft	0.0	Crack Sealing - AC	AC	4802	26	6	Ft	\$0.60	\$3.80
WEDGEWOODD	0008	RUTTING	High	48	SqFt	0.0	Patching - AC Deep	AC	4802	26	48	SqFt	\$5.56	\$267.71
WEDGEWOODD	0317	L & T CR	High	16	Ft	0.0	Patching - AC Shallow	AC	2699	26	52	SqFt	\$2.78	\$144.11
WEDGEWOODD	0317	L & T CR	Medium	67	Ft	0.1	Crack Sealing - AC	AC	2699	26	67	Ft	\$0.60	\$39.98
WEDGEWOODD	0726	L & T CR	High	2	Ft	0.0	Patching - AC Shallow	AC	336	26	5	SqFt	\$2.78	\$15.69
WEDGEWOODD	0726	L & T CR	Medium	2	Ft	0.0	Crack Sealing - AC	AC	336	26	2	Ft	\$0.60	\$1.39
WELLINGTON	0065	RUTTING	High	20	SqFt	0.0	Patching - AC Shallow	AC	2023	26	19	SqFt	\$2.78	\$55.21
WESLEYDR	0667	L & T CR	Medium	96	Ft	0.8	Crack Sealing - AC	AC	509	24	96	Ft	\$0.60	\$57.68
WESTONDR	0396	L & T CR	Medium	1	Ft	0.0	Crack Sealing - AC	AC	848	26	1	Ft	\$0.60	\$0.62
WESTPORTCT	0441	L & T CR	Medium	92	Ft	2.4	Crack Sealing - AC	AC	151	26	93	Ft	\$0.60	\$55.44
WESTPORTRD	0037	L & T CR	Medium	281	Ft	0.7	Crack Sealing - AC	AC	1657	24	281	Ft	\$0.60	\$168.58
WESTPORTRD	0037	ALLIGATOR CR	Medium	56	SqFt	0.1	Patching - AC Deep	AC	1657	24	90	SqFt	\$5.56	\$502.34
WESTPORTRD	0037	L & T CR	High	2	Ft	0.0	Patching - AC Shallow	AC	1657	24	8	SqFt	\$2.78	\$22.12
WESTPORTRD	0328	RUTTING	High	19	SqFt	0.0	Patching - AC Shallow	AC	2671	26	19	SqFt	\$2.78	\$54.11
WESTPORTRD	0649	L & T CR	Medium	132	Ft	0.4	Crack Sealing - AC	AC	1393	26	132	Ft	\$0.60	\$79.32
WESTPORTRD	0649	RUTTING	Medium	148	SqFt	0.4	Patching - AC Shallow	AC	1393	26	147	SqFt	\$2.78	\$410.76
WESTPORTRD	0773	L & T CR	High	2	Ft	0.0	Patching - AC Shallow	AC	190	26	5	SqFt	\$2.78	\$14.68
WESTPORTRD	0773	L & T CR	Medium	64	Ft	1.3	Crack Sealing - AC	AC	190	26	64	Ft	\$0.60	\$38.66
WFANKLINA	0513	L & T CR	Medium	225	Ft	1.2	Crack Sealing - AC	AC	555	34	224	Ft	\$0.60	\$134.70
WFANKLINA	0513	L & T CR	High	46	Ft	0.2	Patching - AC Shallow	AC	555	34	150	SqFt	\$2.78	\$416.72
WFANKLINA	0513	ALLIGATOR CR	Medium	223	SqFt	1.2	Patching - AC Deep	AC	555	34	287	SqFt	\$5.56	\$1,597.32
WFANKLINA	0513	RUTTING	Medium	27	SqFt	0.1	Patching - AC Shallow	AC	555	34	27	SqFt	\$2.78	\$74.66
WHEATLANDD	0319	RUTTING	High	10	SqFt	0.0	Patching - AC Shallow	AC	1962	26	11	SqFt	\$2.78	\$28.52
WIGGINTOND	0390	L & T CR	Medium	36	Ft	0.1	Crack Sealing - AC	AC	1059	26	36	Ft	\$0.60	\$21.60
WILLIAMSBU	0549	L & T CR	Medium	1	Ft	0.0	Crack Sealing - AC	AC	1477	24	1	Ft	\$0.60	\$0.36
WILLIAMSBU	0549	RUTTING	Medium	9	SqFt	0.0	Patching - AC Shallow	AC	1477	24	9	SqFt	\$2.78	\$25.31
WILLOWTREE	0078	L & T CR	High	59	Ft	0.1	Patching - AC Shallow	AC	1669	26	195	SqFt	\$2.78	\$540.24
WILLOWTREE	0078	RUTTING	High	50	SqFt	0.1	Patching - AC Deep	AC	1669	26	50	SqFt	\$5.56	\$275.71
WILLOWTREE	0078	L & T CR	Medium	178	Ft	0.4	Crack Sealing - AC	AC	1669	26	177	Ft	\$0.60	\$106.51
WINDHAMCOV	0343	L & T CR	High	27	Ft	0.1	Patching - AC Shallow	AC	1553	26	89	SqFt	\$2.78	\$248.90
WINDHAMCOV	0343	RUTTING	Medium	141	SqFt	0.4	Patching - AC Shallow	AC	1553	26	141	SqFt	\$2.78	\$393.15
WINDHAMCOV	0343	POTHOLE	Low	6	Count	0.0	Patching - AC Deep	AC	1553	26	18	SqFt	\$5.56	\$101.15
WINDHAMCOV	0343	L & T CR	Medium	684	Ft	1.7	Crack Sealing - AC	AC	1553	26	684	Ft	\$0.60	\$410.18
WINDHAMCOV	0343	ALLIGATOR CR	Medium	17	SqFt	0.0	Patching - AC Deep	AC	1553	26	39	SqFt	\$5.56	\$212.62
WINDHAMCOV	0579	L & T CR	Medium	132	Ft	1.0	Crack Sealing - AC	AC	533	26	132	Ft	\$0.60	\$79.42
WINDHAMCOV	0579	L & T CR	High	3	Ft	0.0	Patching - AC Shallow	AC	533	26	10	SqFt	\$2.78	\$27.51

## Details of the 2022 Localized Distress Maintenance Plan

BranchID	SectionID	Description	Severity	Distress Qty	Distress Unit	Percent Distress	Work Description	Surface Type	Section Length (Ft)	Section Width (Ft)	Work Qty	Work Unit	Unit Cost	Work Cost
WINDSORDR	0240	L & T CR	Medium	125	Ft	0.3	Crack Sealing - AC	AC	1659	26	125	Ft	\$0.60	\$75.02
WINDSORDR	0240	RUTTING	Medium	10	SqFt	0.0	Patching - AC Shallow	AC	1659	26	10	SqFt	\$2.78	\$27.73
WOODBINEDR	0608	L & T CR	Medium	18	Ft	0.1	Crack Sealing - AC	AC	699	22	18	Ft	\$0.60	\$10.98
WOODHAVEND	0409	POTHOLE	Low	3	Count	0.0	Patching - AC Deep	AC	1554	24	9	SqFt	\$5.56	\$45.49
WOODHAVEND	0409	L & T CR	Medium	154	Ft	0.4	Crack Sealing - AC	AC	1554	24	154	Ft	\$0.60	\$92.16
WOODLANDDR	0611	L & T CR	High	57	Ft	0.1	Patching - AC Shallow	AC	2914	24	188	SqFt	\$2.78	\$523.18
WOODLANDDR	0611	L & T CR	Medium	67	Ft	0.1	Crack Sealing - AC	AC	2914	24	67	Ft	\$0.60	\$40.03
WOODLANDDR	0611	ALLIGATOR CR	Medium	12	SqFt	0.0	Patching - AC Deep	AC	2914	24	29	SqFt	\$5.56	\$163.22
WOODLANDDR	0611	RUTTING	Medium	53	SqFt	0.1	Patching - AC Shallow	AC	2914	24	53	SqFt	\$2.78	\$147.38
WOODSCREEK	0381	POTHOLE	Low	3	Count	0.0	Patching - AC Deep	AC	2626	26	9	SqFt	\$5.56	\$49.43
WOODSCREEK	0381	RUTTING	Medium	10	SqFt	0.0	Patching - AC Shallow	AC	2626	26	10	SqFt	\$2.78	\$27.44
WPADDOCKST	0472	L & T CR	Medium	881	Ft	2.6	Crack Sealing - AC	AC	1419	24	881	Ft	\$0.60	\$528.70
WPADDOCKST	0472	ALLIGATOR CR	Medium	2	SqFt	0.0	Patching - AC Deep	AC	1419	24	12	SqFt	\$5.56	\$67.63
WPADDOCKST	0472	L & T CR	High	2	Ft	0.0	Patching - AC Shallow	AC	1419	24	6	SqFt	\$2.78	\$18.77
WTERRACOTT	0653	RUTTING	High	67	SqFt	0.3	Patching - AC Shallow	AC	879	24	67	SqFt	\$2.78	\$185.22
WUPLANDDR	0069	L & T CR	High	21	Ft	0.1	Patching - AC Shallow	AC	708	26	69	SqFt	\$2.78	\$190.50
WUPLANDDR	0069	POTHOLE	Low	3	Count	0.0	Patching - AC Deep	AC	708	26	10	SqFt	\$5.56	\$51.69
WUPLANDDR	0069	L & T CR	Medium	393	Ft	2.1	Crack Sealing - AC	AC	708	26	393	Ft	\$0.60	\$236.01
WUPLANDDR	0069	ALLIGATOR CR	Medium	528	SqFt	2.9	Patching - AC Deep	AC	708	26	624	SqFt	\$5.56	\$3,471.15
WUPLANDDR	0069	RUTTING	Medium	50	SqFt	0.3	Patching - AC Shallow	AC	708	26	51	SqFt	\$2.78	\$139.39
WWOODSTOCK	0104	L & T CR	High	23	Ft	0.0	Patching - AC Shallow	AC	5808	30	76	SqFt	\$2.78	\$212.39
WWOODSTOCK	0104	ALLIGATOR CR	Medium	364	SqFt	0.2	Patching - AC Deep	AC	5808	30	446	SqFt	\$5.56	\$2,476.12
WWOODSTOCK	0104	L & T CR	Medium	1216	Ft	0.7	Crack Sealing - AC	AC	5808	30	1216	Ft	\$0.60	\$729.35
WWOODSTOCK	0104	RUTTING	Medium	44	SqFt	0.0	Patching - AC Shallow	AC	5808	30	44	SqFt	\$2.78	\$123.18
WWOODSTOCK	0104	POTHOLE	Low	10	Count	0.0	Patching - AC Deep	AC	5808	30	30	SqFt	\$5.56	\$166.47
WYNDMUIRDR	0273	RUTTING	Medium	9	SqFt	0.0	Patching - AC Shallow	AC	1455	28	9	SqFt	\$2.78	\$25.34
WYNDMUIRDR	0273	RUTTING	High	11	SqFt	0.0	Patching - AC Deep	AC	1455	28	11	SqFt	\$5.56	\$59.01
WYNDMUIRDR	0661	L & T CR	High	1	Ft	0.0	Patching - AC Shallow	AC	342	24	4	SqFt	\$2.78	\$11.53
YORKSHIREL	0492	RUTTING	Medium	10	SqFt	0.0	Patching - AC Shallow	AC	1522	26	10	SqFt	\$2.78	\$27.88
YORKSHIREL	0492	L & T CR	High	1	Ft	0.0	Patching - AC Shallow	AC	1522	26	3	SqFt	\$2.78	\$8.51
YORKSHIREL	0492	L & T CR	Medium	36	Ft	0.1	Crack Sealing - AC	AC	1522	26	36	Ft	\$0.60	\$21.52